

Attachment J-14

Government-Furnished Container Inventory

**Table J-9 –Container Inventory and Most Recent Maintenance Performed
 Last Maintenance PMs, Panel Repair, Misc Repairs & Measurements
 (as of 10/13/20)**

Container No.	Date	Notes
1	1/30/20	PM
2	10/12/20	Replaced endgate gasket, adjust j-hook and checked cam locks.
3	1/30/20	PM
4	2/12/20	PM; replaced 2 bolts and 2 zerks
5	10/21/19	PM
6	10/8/19	PM, repaired tailgate rib hole
7	1/7/20	PM
8	12/16/19	PM
9	4/14/20	PM; Replaced 1 Rad7
10	3/3/20	PM; Replaced 3 Rad7; 3 Caution; 2 lid
11	12/20/18	PM; Panels #5,6,7,8,9,10,11 welded cracks on bottom; lubed linkage
12	2/24/20	pm; Replaced 2 bolts; OOS replaced right bulkhead lid lock
13	10/6/20	PM; 1 bolt; 3 Rad 7; 2 zerks
14	4/8/20	PM; replaced lid lock
15	2/20/20	PM; replaced stencils 1 lid and 3 caution
16	9/5/19	PM
17	1/15/20	PM; Welded cracks; repaired 2 holes in bulkhead patch welded holes.
18	3/11/19	Panels 1, 4, 6, 11 replaced
19	3/31/20	PM; replaced 2 Rad7
20	5/13/19	Replace bottom end gate gasket
21	9/16/20	Replaced end gate gasket. Checked cam locks and J-Hooks
22	9/25/19	Welded cracks on welds on bottom, straightened tailgate hinge, lid lock
23	12/12/19	PM-Replaced tailgate end lid lock. Rebuilt other side lid lock. Replaced lid lock on bulkhead end.
24	12/3/19	PM - Stencils replaced as needed 2 Rad 7; 3 Caution; 2 Lid
25	2/11/20	PM; replaced 2 bolts, 1 zerk; replaced stencils 1 lid, 1 caution
26	5/27/20	PM; Ground off sharp piece off of J-Hook
27	8/12/20	PM; replaced 3 Rad7
28	1/30/20	PM; Welded cracked welds.
29	6/11/20	PM
30	4/14/20	PM; repaired panels 1,2,3,8,9,10,11; welded cracked welds on bottom; replaced right tailgate end lid lock
31	6/29/20	PM; replace 2 Rad7; 1 zerk
32	3/7/18	Container spray coating completed - Corner casting damage
33	2/12/20	PM: replaced 1 bolt; replaced stencils 1 lid, 2 cautions
34	1/11/19	6 cracks on bottom repaired
35	7/1/20	PM; replaced 2 Rad7; 2 zerks
36	3/11/19	Repaired panels 7, 11, 12, 13, 14
37	10/4/17	PM
38	7/7/20	J-Hooks needed to be adjusted to spec.
39	7/1/20	PM; Replaced 2 bolts; 1 Rad7; 1 zerk
40	4/8/20	PM; replaced 2 bolts
41	1/6/20	PM
42	7/13/20	PM; replace 1 Rad7; 1 zerk

43	5/5/20	PM; Replaced panel @2,4,5,6,9,11,12,13,14; repaired 13 cracks, replaced 4 Rad7; 2 zerks
44	9/28/20	PM; Replaced 2 fingers that were bent; adjusted all fingers to spec.
45	5/27/20	PM: Repaired 6 cracks on floor plate; repaired panels #1,8,13,14.
46	6/29/20	PM; replaced 1 rad 7
47	1/10/18	PM
48	7/2/20	PM; replaced 2 Rad7; 2 zerks
49	2/27/19	Repaired cracked welds on bottom and repaired 4 holes on lid
50	4/6/20	PM; repaired panels 12,13; welded cracked welds on bottom, lubed linkage
51	2/18/20	PM; Welded cracked welds on bottom; repaired hole in lid; repaired panels #1,2,6; replaced lid lock; tightened jam nuts and lubed linkage.
52	3/31/20	PM; replaced 1 Rad7; 3 zerks
53	5/5/20	PM; Replace 2 lid locks; straighten 2 floor beams; repair 10 cracks in floors; replace 4 Rad7; 3 zerks; tighten and lube jam nuts on camlocks.
54	9/25/19	Weld (10) cracks, (2) floor beams, repaired 12 panels.
55	5/31/18	Center J Hook wled cracked, grind out crack, reweld and adjust
56	12/10/19	PM - Repaired thin panel #1; welded cracked welds on bottom lubed linkage with graphite
57	4/8/20	PM; replaced 2 bolts; 2 zerks
58	4/20/02	PM; welded cracked welds on bottom; tightened jam nuts and repaired panel #6.
59	3/14/19	Repaired panel #9
60	6/10/20	PM; Painted a zero
61	12/16/19	PM - Tailgate Gasket
62	12/20/18	PM-Repaired panels #2,3,4,9,10,11; Welded cracked welds on bottom; lubed linkage with dry graphhite. Replaced stencils 2 Rad7, 2 lid, 4 cautions and paint
63	2/12/20	PM; replaced 1 zerk; replaced stencils 2 caution, 1 lid
64	7/14/20	PM; replace 2 bolts; 1 Rad7; 1 zerk
65	12/16/19	PM
66	6/4/20	PM; Repaired panels 1,2,3,5,6,7,8,9,10,11,12,13,14; Repaired 17 cracks in floor plate
67	2/27/18	PM
68	4/29/20	Reglued bottom endgate gasket.
69	5/16/19	Repair holes in floor. Repaired cracked welds.
70	10/29/19	PM Replaced 2 lid lock bolts and 3 placards
71	4/8/20	PM; replaced 2 bolts; 1 Rad7
72	7/2/20	PM; replace lid lock; 2 Rad7
73	1/9/20	Gasket Repair
74	9/28/20	PM; replaced 1 Rad7; 1 zerk
75	2/6/20	PM; replaced 1 bolt; replaced stencils 2 Rad7, and 2 lids; Replaced passenger side J Hook foot, lock nuts.
76	7/2/20	PM; Replaced 2 bolts; 3 Rad7; 2 Zerks
77	8/12/20	PM; replaced 2 Rad7; 1 zerk
78	7/6/20	PM; Replace 1 lid lock
79	6/29/20	PM; Replace 1 Rad7; 1 zerk
80	3/9/20	Reweld endgate protection plate.
81	6/3/20	Removed and cleaned gasket and container surface; glued new gasket back in place. Measured j-hooks and checked cam locks.
82	9/4/19	PM
83	7/7/20	End gasket needed to be taken out , cleaned and re-attached

84	4/20/20	PM; Repaired panels 6,8,10; Welded cracked welds on bottom. Lubed linkage with dry graphite and tightened jam nuts.
85	4/8/20	PM; replaced 1 zerk
86	1/30/20	PM
87	6/29/20	PM; replace 1 zerk
88	1/15/20	PM; OOS - welded cracked welds on bottom; Lubed etc
89	7/9/19	PM and welded floor beams full length
90	6/23/20	Replaced end gasket; removed broken Z-rail on channel
91	12/3/19	PM; Stencils replaced as needed 1 rad 7; 2 caution; 1 lid
92	4/9/20	PM; replaced 2 Rad 7
93	3/30/20	PM
94	9/4/19	PM
95	2/24/20	PM; Replaced 1 zerk
96	12/16/19	PM
97	7/1/20	PM; replaced 1 bolt; 2 Rad7 ; 1 zerk
98	4/9/20	PM; replaced 1 bolt; replaced 2 Rad7
99	8/12/20	PM; replaced 2 rad7; 2 zerks
100	9/28/20	PM; reokaced 1 Rad7; 1 zerk; cracks with liner.
101	6/3/20	PM
102	1/7/20	PM
103	6/22/20	PM; replaced 4 Rad7; 1 zerk
104	10/6/20	PM; 1 Rad7; 3 zerks
105	9/13/17	PM
106	1/28/20	PM
107	9/4/19	PM and replaced right tail gate end led latch
108	12/17/19	PM-Welded cracked welds on bottom. Lubed linkage with dry graphite.
109	8/12/20	PM; replaced 1 Rad7
110	3/3/20	PM; replaced 2 bolts; replaced 1 lid sticker, 1 zerk
111	3/4/20	PM; OOS - welded cracked welds on bottom; replaced missing retainer
112	9/28/20	PM; replace 3 Rad7
113	1/23/20	PM; Replaced 2 lid stencils
114	7/11/19	Repaired hole in lid, welded beams on bottom, replaced right rear lid lock
115	12/6/17	PM
116	5/14/20	Replaced end gate gasket
117	1/13/20	PM; Replaced 2 lid, 2 Rad7, 2 caution
118	10/1/19	Replaced lid lock PM
119	4/16/20	PM; Replaced 1,2,3,6,9,10,13; Welded cracked welds on bottom; tightened jam nuts
120	7/15/20	PM
121	3/3/20	PM; replaced 2 Rad7; 2 lid; 4 caution; 1 zerk
122	12/20/18	PM and 14 panels Repairs Welded crack welds
123	12/12/19	PM - Replaced 1 lid lock on tailgate end and rebuilt other side; Replaced 1 lid and 2 caution stencils.
124	4/14/20	PM; Replaced 2 bolts; replaced 2 Rad7
125	6/10/19	Weld corner post cracks, repair all cracks on bottom, repair left latch finger
126	9/9/19	PM
127	1/9/20	Gasket Repair
128	10/7/20	Replaced endgate gasket; checked cam lock function and j-hooks are adjusted within spcifications.
129	9/24/19	PM and welded cracks on bottom and floor plate

130	6/9/20	PM; replaced 1 bolt; 2 Rad7; 2 zerks
131	8/28/19	PM
132	10/6/20	PM; replaced 3 Rad7; 1 zerk
133	1/23/20	PM; Replaced 4 bolts; replaced 2 lid and 2 caution stencils
134	12/19/19	PM-Welded cracked welds on bottom. Lubed linkage with dry graphite.
135	4/21/20	PM; replaced 2 bolts; 3 Rad7; 2 zerks
136	10/6/20	PM; 1 bolt; 1 zerk
137	3/2/20	PM; replaced 2 bolts; replaced stencils 4 caution, 2 lids, 2 Rad7; replaced 1 zerk
138	3/5/18	PM
139	8/20/20	PM; welded nut on tailgate flap.
140	12/3/19	PM replaced 1 Rad 7
141	1/6/20	PM
142	6/17/20	PM; replaced detent ball and spring; 2 bolts; 1 Rad7; 1 zerk
143	7/29/20	PM
144	10/16/13	Permanently Out of Service
145	4/27/20	PM; Replaced left bulkhead end lid lock
146	12/20/18	Repaired panels 3, 11
147	10/22/19	PM 3 bolts replaced and 2 placards.
148	12/29/19	PM; Replaced 1 lid stencil
149	1/8/20	PM
150	11/4/19	PM Replaced 5 placards
151	1/13/20	Replaced bottom endgate gasket and adj. L & R J-Hooks
152	1/29/20	PM; Replaced 5 bolts and replaced 2 zerks
153	1/13/20	PM-repaired dent end post on bulkhead end, Replaced 2 Rad 7, 4 caution, and 2 lid.
154	10/28/19	PM Welded broken weld on left gusset
155	4/14/20	PM; repaired panels 2,3,4,8,11; replaced left bulkhead lid lock; welded cracked welds on bottom.
156	1/8/20	PM
157	3/9/20	Rewelded endgate protection plate (debris can)
158	12/9/19	PM Replaced 1 bolt; stencils 2 lid and 1 caution; Replaced 2 zerks
159	12/20/19	Repaired 1,4,7,8 panels
160	9/5/19	PM
161	5/13/20	PM; replaced 1 Rad7, 2 caution, and 1 lid stencil
162	2/12/20	PM
163	12/2/19	PM; stencils replaced 1 Rad 7; 2 caution; 1 lid
164	6/29/18	PM
165	1/7/20	PM
166	5/18/20	PM; replaced j-hook; welded piece of strap below gasket.
167	12/20/18	PM; replaced 2 Rad 7; replaced 1 zerk; repaired all 14 panels 1-14; welded cracked welds on bottom; lubed linkage with dry graphite.
168	7/29/20	PM; replaced 2 bolts; 2 zerks
169	12/3/19	PM; Stencils replaced 2 caution; 2 lid
170	12/4/19	PM; stencils replaced 1 Rad 7; 2 caution; 1 lid
171		PM. Performed spring of 2020.
172	7/9/20	Repair 1" angle behind center latch finger. Remove and repaired by welding new 1' cold roll.
173		PM. Performed spring of 2020.
174		PM. Performed spring of 2020.
175	6/5/18	PM
176	9/18/17	PM

177	1/23/20	PM; replaced 1 Rad7, 2 caution, and 1 lid stencil
178	2/11/20	PM; replaced 2 bolts; replaced stencils 2 lid, 1 Rad7, 1 caution
179	10/1/19	PM
180	4/11/19	Repair panels #5,11,14
181	3/11/20	PM; Repaired panels #1,2,3,4,8,9,10,11,13; welded cracked welds on bottom; replaced 2 lid locks on tailgate end; replaced 4 Rad7
182	10/8/19	PM
183	6/23/20	PM; Replaced 1 Rad7
800001	5/13/20	PM; replaced 1 Rad7; 1 zerk
800002	3/30/20	PM; Replaced 1 Rad 7
800003	2/24/20	PM; replaced 2 bolts; replaced stencil 1 lid
800004	5/14/20	PM
800005		OOS for corner casting damage - no repairs made
800006	1/28/20	PM; replaced stencils 1 Rad7 and 1 lid
800007	3/18/20	PM; replaced 2 bolts; replaced 2 Rad7, 2 caution, 1 lid
800008	8/31/20	PM
800009	12/12/19	PM Stencils replced 2 lid; replaced 1 zerk
800010	11/6/19	PM - Replaced 2 RAD; 1 lid; 4 cautions
800011	3/16/20	PM; replaced 2 Rad7, 2 lid, 1 caution
800012	12/17/18	PM completed at 11 trips
800013	9/1/17	PM
800014	7/14/20	PM; replaced 2 lid locks; 3 rad7; 2 zerks; 2 nuts
800015	11/29/17	OOS for low bottom measurement - measured below 0.060 in multiple areas
800016	11/26/18	Gaskets checked
800017	3/9/20	PM; Replaced 2 Rad7; 2 cation
800018	6/7/18	Container spray coating completed
800019	4/27/20	PM; replaced right tailgate end lid lock
800020	7/7/20	PM; Replace 1 lid lock; 2 Rad7; 2 zerks
800021	10/16/17	PM
800022	3/27/18	PM
800023	7/31/17	PM
800024	7/27/20	Install new endgate gasket; check camlock and j-hook
800025	11/9/17	Replace right twist lock on bulk head
800026	1/29/20	PM; replaced 6 bolts, replaced 2 lid stencils; Replaced 1 zerk and 1 washer and cotter pin
800027	8/23/17	PM
800028	11/6/19	PM - replaced 1 lid stencil Replaced 1 zerks
800029	1/24/18	PM
800030	8/16/17	PM
800031	3/2/20	PM; replaced stencils 2 lid, 3 caution, 1 Rad7
800032	1/28/20	PM; Replaced stencil 1 lid and 2 caution
800033	5/16/19	PM; welded crack welds on bottom; replaced 1 Rad7; removed safety stickers.
800034	4/21/20	PM; replaced 1 bolt; 2 Rad7; 2 zerks
800035	12/11/19	Replaced bottom end gate gasket
800036	8/21/17	PM
800037	3/18/20	PM; replaced 2 bolts; replaced 12 lid, 3 caution, and 1 Rad7; replaced 1 zerk
800038	6/19/12	Pemenantly Out of Service
800039	12/18/18	PM completed at 6 trips
800040	5/23/18	Container spray coating completed

800041	5/19/19	PM; welded cracked welds on bottom; removed safety stickers; replaced 4 Rad7; lubed and tightened linkage and jam nuts.
800042	11/7/18	Weld cracks on bottom of container
800043	9/18/17	PM
800044	4/2/19	Replaced bottom endgate gasket
800045	4/16/20	PM; replaced 3 Rad7; repainted numbers; 2 zerks
800046	1/13/20	PM; replaced stencils 2 rad7 2 caution and 1 lid
800047	12/16/19	PM; Replaced 4 bolts; replaced stencils 2 caution, 1 lid; Replaced left bulkhead end lid lock.
800048	8/9/17	PM
800049	12/16/19	PM
800050	4/6/20	PM; replaced 1 Rad 7; 2 zerks
800051	7/11/19	PM; Welded cracked welds on bottom.
800052	6/30/20	PM; Replaced 1 bolt; 2 Rad7
800053	1/28/20	PM; replaced 1 lid and 2 caution stencils
800054	7/2/20	PM; replaced 1 Rad7
800055	5/23/18	Container spray coating completed
800056	3/24/20	PM; replaced 5 bolts; repalced 1 Rad7; replaced 2 zerks
800057	7/31/17	PM
800058	12/11/17	PM
800059	10/22/19	PM Replaced 1 bolt
800060	5/14/20	Replaced endgate gasket and adjusted all 3 J-Hooks
800061	1/30/20	Tighten loos lid lock bolts. Replace broken grease fitting
800062	11/19/18	Repaired left and right dents with 1/4"x4"x4" angle
800063	12/17/19	PM; welded cracks on bottom: lubed and tightened jam nuts and linkage.
800064	9/20/17	Repaired panels 1, 2, 3, 4, 6
800065	1/30/20	Replace missing bolt; tightened lock bolts; replaced placard; adjust detent
800066	2/11/20	PM; replaced stencils 2 rad7 2 caution and 1 lid
800067	4/15/20	PM; Replaced 1 bolt; replaced 2 Rad7; 1 zerk
800068	3/9/20	PM; replaced 4 bolts; replaced 2 lid, 1 Rad7; Replaced 2 zerks
800069	6/24/20	PM; replaced lid lock; 1 Rad7
800070	4/30/20	Reuglued bottom endgate gaskets
800071	3/30/20	PM; replaced 2 Rad7; replaced 1 zerk
800072	4/6/20	PM; 2 Rad7; 1 zerk
800073	3/16/20	PM; replaced 4 caution, 1 Rad7, 2 lid; replaced 2 zerks
800074	12/16/19	PM
800075	2/11/20	PM; replaced 1 zerk; replaced stencils 2 lid, 3 caution
800076	5/6/20	PM; replaced 1 bolt; 2 Rad7 and #'s; 1 zerk
800077	3/24/20	PM; repalced 2 Rad7; replaced 1 zerk
800078	12/21/15	Measurements Taken
800079	3/18/20	PM; replace 1 lid and 1 Rad7
800080	2/20/20	PM; Replaced stencils 2 lid and 1 caution
800081	1/29/20	PM; replaced 5 bolts, painted 2 gouges, replaced 2 lid and 2 caution stencils, replaced 1 zerk
800082	3/24/20	PM; replace 1 bolt, replace 1 Rad7; repalced 1 zerk
800083	2/11/20	PM; Replaced 1 bolt; replaced stencil 1 lid
800084	4/6/20	PM; Replaced 3 Rad7; 2 zerks/2 washers
800085	3/2/16	Permanently Out of Service
800086	12/4/19	PM; replaced 2 bolts; stencils replaced 4 caution; 1 rad7; 1 lid
800087	4/6/20	PM; replaced 2 Rad 7
800088	11/6/19	PM - Replaced 1 rad, 2 cautions, 1 lid; replaced bolt and 2 zerks

800089	2/11/20	PM; replaced stencils 2 rad7
800090	11/11/19	PM - Replaced 1 zerk
800091	1/30/20	Replace missing bolt; tighten other bolts; replace placard.
800092	1/6/20	PM - Replaced stencils 3 rad7, 2 caution, 1 lid
800093	7/9/20	PM; Replaced 1 Rad7; 2 zerks
800094	4/17/17	Taken OOS for corner casting damage - no repairs
800095	4/29/20	PM; replaced 4 bolts and 1 zerk
800096	7/7/20	End gate gasket needed to be replaced.
800097	2/19/20	PM; Replaced 2 bolts; replaced 1 zerk; replaced stencils 2 Rad7, and 2 lid
800098	4/22/20	PM; replaced 2 bolts, 2 Rad7; 2 zerks
800099	4/15/20	PM; replaced 3 Rad7; 2 zerks
800100	3/16/20	PM; replaced 2 bolts; 2 caution, 1 lid; repalced 1 zerk
800101	2/24/20	PM
800102	1/14/20	PM
800103	6/7/17	PM
800104	4/27/20	PM; replaced 2 bolts; 1 Rad7; and 2 zerks
800105	2/19/20	PM; Replaced 4 bolts; replaced 2 zerks
800106	12/2/19	PM; stencil replaced 1 rad 7
800107	4/21/20	PM; replaced 1 Rad7; 3 zerks
800108	5/16/19	PM; Welded cracks on bottom; removed afety stickers; replaced 3 Rad7; lubed and tightened linkage and jam nuts.
800109	11/4/19	PM Replaced 8 Placards
800110	2/12/18	Permanent Liner Damage
800111	7/31/17	PM
800112	3/30/20	PM; Replaced 2 zerks
800113	12/16/19	PM
800114	4/29/20	PM; replaced 1 bolt, 2 Rad7; 2 zerks
800115	11/7/16	Permanent Liner Damage
800116	8/29/16	Permanently Out of Service
800117	6/24/20	PM; replace 2 Rad7; 2 zerks
800118	9/9/20	Installed new end gate gasket - Checked camlock and J-Hook
800119	3/4/20	PM
800120	5/13/20	PM; replaced 2 Rad7; 2 bolts
800121	1/13/20	PM; Replaced bottom end gate gasket and adjusted middle J Hook
800122	4/15/20	PM; replaced 1 bolt; replaced 1 Rad7; 2 zerks
800123	10/6/20	PM; replaced 1 zerk
800124	2/12/20	PM; Replaced serk; Replaced stencils 3 caution, 3 Rad 7
800125	6/22/20	PM; replaced 2 Rad7; 1 zerk
800126	2/12/20	PM; Replaced zerk; replaced stencils 2 caution, 1 lid, 2 Rad7
800127	2/26/20	PM; replaced 2 bolts; replaced stencils 3 Rad7, 2 lid, 4 caution
800128	4/27/20	PM; replaced 2 Rad7, 2 zerks
800129	10/24/19	PM Replaced 8 bolts and 1 rad placard
800130	3/12/20	PM
800131	1/14/20	PM-replaced 2 lid
800132	8/2/17	PM
800133	3/30/20	PM; replaced 1 Rad7; replaced 1 zerk
800134	1/7/20	PM
800135	10/11/17	PM
800136	1/30/20	PM
800137	4/6/20	PM; replaced 3 Rad7; 2 serks

800138	4/27/20	PM; bolt, 1 Rad7; 2 zerks
800139	12/19/17	Left rear bottom casting pocket cover cracked and pushed up. Fork access rib weld crack. Wled in plate and grind and reweld as needed.
800140	12/16/19	PM
800141	6/22/20	PM; replaced 2 bolts; 1 Rad7; 2 zerks; repaired hole in side sill.
800142	6/23/20	Replaced end gate gasket and j-hooks needed to be adjusted to spec.
800143	11/5/19	PM Replaced 4 placards
800144	6/30/20	Replaced end gasket and adjusted j-hooks to 2 3/4 in within Spec
800145	12/11/17	PM
800146	12/4/19	PM replaced stencils 3 caution and 1 lid
800147	7/10/19	PM
800148	1/7/20	PM
800149	3/8/18	PM
800150	3/12/20	PM; replaced 4 Rad7, 2 lid, 2 caution; replaced 2 zerks
800151	3/12/20	PM
800152	1/17/18	Permanent Liner Damage
800153	5/16/19	PM; welded cracked welds on bottom; removed safety stickers and replaced 2 Rad7.
800154	2/11/20	PM; Replaced stencils 2 lids, 2 Rad7; Tightened right and left J Hook
800155	4/15/20	PM; replaced 1 Rad7; replaced 1 zerk
800156	4/6/16	Permanent Liner Damage
800157	8/31/20	PM
800158	2/11/20	PM; Replaced 2 bolts; replaced stencils 2 lids, 1 caution
800159	9/20/17	PM
800160	10/23/17	PM
800401	4/30/20	PM
800402	10/31/17	New Container- PM
800403	2/19/20	PM; Replaced stencils 1 lid, 3 caution, 3 Rad 7; replaced zerk; Siliconed corner of tailgate seal
800404	4/13/20	PM; replaced 1 Rad7; 2 zerks
800405	6/18/20	PM; 2 zerks
800406	4/9/20	PM; Replaced 2 Rad 7
800407	4/13/20	PM; replaced 1 zerk
800408	5/14/20	PM
800409	1/30/20	PM ; replaced 1 lid, 2 caution, and 1 Rad7 stencil
800410	10/31/17	New Container- PM
800411	6/24/20	PM; replace 1 Rad7; 2 zerks
800412	6/18/20	PM; replaced 2 zerks
800413	2/26/20	PM; replaced 2 zerks
800414	4/13/20	PM; replaced 1 zerk
800415	11/5/19	PM Replaced 4 placards.
800416	4/30/20	PM; replaced 2 zerks
800417	6/24/20	PM; replace 1 Rad7; 2 zerks
800418	4/30/20	PM
800419	4/9/20	PM; replaced 3 Rad7; 2 zerks
800420	2/12/20	PM
800421	5/6/20	PM; replaced 2 Rad7; 3 zerks
800422	12/16/19	PM
800423	6/23/20	PM; replaced 3 Rad7; 1 zerk
800024	6/2/20	PM; 2 bolts, 3 zerks
800425	7/6/20	PM; 2 bolts; 2 Rad7; 4 zerks
800426	6/15/20	PM; replaced 2 Rad7

800427	12/19/19	PM; replaced missing bolts.
800428	5/13/20	PM; replaced 2 bolts; 2 Rad7; 1 zerk
800429	7/15/20	PM; Replaced 1 Rad7
800430	6/23/20	PM; replaced 2 zerks
800431		Acquired 12/2018
800432	7/6/20	PM; replace 1 bolt; 3 Rad7; 2 zerks
800433	12/16/19	PM
800434		Acquired 12/2018
800435	8/12/20	PM; replace 1 Rad7
800436	6/17/20	PM; replaced 2 Rad7
800437		Acquired 12/2018
800438	5/27/20	PM; replaced 2 bolts; 1 Rad7; 2 zerks
800439	4/21/20	PM; replaced 2 zerks
800440	6/22/20	PM; replaced 1 Rad7; 3 zerks
800441	7/29/20	PM; replaced 1 bolt; 1 Rad7; 1 zerk
800442	4/15/19	Weld washer retrofit complete - washer added 9
800443	7/1/20	PM
800444	5/14/20	PM
800445	6/3/20	PM; replaced 2 bolts; 3 zerks
800446	7/7/20	PM; Replace 1 zerk
800447	5/6/20	PM; replaced 1 bolt; 2 Rad 7; 2 zerks
800448	4/29/20	PM; replaced 2 bolts; 1 Rad7; 1 zerk
800449	6/22/20	PM; replaced 3 zerks
800450	6/25/20	PM; replace 1 bolt; 2 Rad7; 1 Zerk
800451	8/3/20	PM; replaced 1 bolt, replaced 2 zerks
800452	4/21/20	PM; Replaced 2 Rad7; 1 zerk
800453		Acquired 12/2018
800454	6/25/20	PM; replace 1 bolt; 1 Rad7
800455	6/11/20	PM; replaced 2 zerks
800456	6/17/20	PM; replaced 1 bolt; 1 Rad7; 1 zerk
800457	11/5/19	PM - Replaced J-Hook;replaced broken tailgate hinge
800458	7/1/20	PM; Replaced 2 bolts; 2 Rad7; 2 zerks
800459		Acquired 12/2018
800460	/29/20	PM; replace 1 botl; 3 Rad7; 2 zerks
800461	6/23/20	PM; replaced 1 bolt; 4 Rad7; 2 zerks
800462	5/12/20	PM; 2 bolts, 2 Rad7; 2 zerks
800463	7/14/20	PM; replaced 1 bolt; 2 Rad7; 2 zerks; and repaired dent on lid
800464	7/14/20	PM; replace 1 bolt; 3 Rad7; 2 zerks
800465	6/3/20	PM; replaced 1 bolt; 1 Rad7; 2 zerks
800466		Acquired 12/2018
800467	7/10/19	PM
800468	7/2/20	PM; replace 1 zerk
800469	6/24/20	PM; replace 1 zerk
800470	6/23/20	PM; replaced 1 bolt; 3 Rad7; 2 zerks
800471	5/14/20	PM
800472	7/15/20	PM; replaced 2 bolts; 2 Rad7
800473	6/30/20	PM; replaced 2 Rad7; 2 zerks
800474		Acquired 07/2020
800475		Acquired 07/2020
800476		Acquired 07/2020
800477		Acquired 07/2020

800478		Acquired 07/2020
800479		Acquired 07/2020
800480		Acquired 07/2020
800481		Acquired 07/2020
800482		Acquired 07/2020
800483		Acquired 07/2020
800484		Acquired 07/2020
800485		Acquired 07/2020
800486		Acquired 07/2020
800487		Acquired 07/2020
800488		Acquired 07/2020
800489		Acquired 07/2020
800490		Acquired 07/2020
800491		Acquired 07/2020
800492		Acquired 07/2020
800493		Acquired 07/2020
800494		Acquired 07/2020
800495		Acquired 07/2020
800496		Acquired 07/2020
800497		Acquired 07/2020
800498		Acquired 07/2020
800499		Acquired 07/2020
800500		Acquired 07/2020
800501		Acquired 07/2020
800502		Acquired 07/2020
800503		Acquired 07/2020
800504		Acquired 07/2020
800505		Acquired 07/2020
800506		Acquired 07/2020
800507		Acquired 07/2020
800508		Acquired 07/2020
800509		Acquired 07/2020
800510		Acquired 07/2020
800511		Acquired 07/2020
800512		Acquired 07/2020
800513		Acquired 07/2020
800514		Acquired 07/2020
800515		Acquired 07/2020
800516		Acquired 07/2020
800517		Acquired 07/2020
800518		Acquired 07/2020
800519		Acquired 07/2020
800520		Acquired 07/2020
800521		Acquired 07/2020
800522		Acquired 07/2020
800523		Acquired 07/2020
800524		Acquired 07/2020