VERIFY ALL DOCUMENTS FOR CURRENT REVISION AND PENDING CHANGES PRIOR TO EACH USE.
INIT_____ DATE_____



NOTES:

1. RECOMMENDED OPERATING PRESSURE OF 3 PSI REQUIRES 250 CFM
2. MAX. RECOMMENDED OPERATING PRESSURE OF 5 PSI REQUIRES 300 CFM
3. 50 PSI INSTRUMENT QUALITY PLANT AIR SUPPLY BY CUSTOMER.
4. 1-60-115V CONTROL WIRING TO SMOOT CO. CONTROL PANEL REQUIRED

WVNS APPROVAL
COG. MGR. [signature] 5/16/86
COG. ENGR. J.L. Nacol 5/19/86
DRFT. SUPR. [signature] 5/16/86
Q.A. [signature] 5/20/86

DETAIL NO.	NO. REQ'D.	PART NO.	STOCK	SIZE	MATERIAL	SOURCE
	9					

REVISIONS

REMARKS	DATE	CHG. NO.
AIR SUPPLY REVISED	1-2-85	A
ECO-734	5/16/86	0

TOLERANCES UNLESS OTHERWISE STATED
FRACT. ± 1/64
DECIMALS ± .015
ANGLES ± 1/2°

SMOOT COMPANY
KANSAS CITY, KANSAS

SILO HOPPER AIR PAD DISCHARGE ASSEMBLY
WVNS P.O.# 19-FWV-06167

DATE 10-31-84
DWN. BY KFH
SCALE 1/4
DWG. NO. 7046-5
APPROVED KH