

WP 04-ED4542

Revision 0

Central Uninterruptible Power Supply Unit 2, 45P-UPS03/2 Alarm Response

Technical Procedure

EFFECTIVE DATE: 8/30/96

Signature on file J. Uptergrove 8/21/96
SIGNATURE PRINTED NAME DATE

APPROVED FOR USE

REVIEW ORGANIZATIONS

Facility Operations	Engineering	
N/A	N/A	N/A

SUMMARY

ALARM SUMMARY	SET POINT NONE
-------------------------	--------------------------

AUTOMATIC ACTIONS

- Battery charger/rectifier may have shut down.
- Inverter may have shutdown.
- UPS may have shifted to Internal Bypass Mode.

IMMEDIATE ACTIONS

- 1.0 Determine which alarm has occurred by observing LED indicators (red) on UPS display panel.
- 2.0 Scroll down UPS display panel to determine cause of alarm.
- 3.0 Report cause of alarm to CMRO.
- 4.0 Determine current operating mode by observing LED indicators (green) on UPS display panel and report to CMRO.
- 5.0 Notify FSM of condition.

POSSIBLE CAUSES

- Battery charger/rectifier has shutdown.
- Inverter has shut down.

END