

PLATE 6

STRUCTURE : TOP OF TILL SAND

CONTOUR INTERVAL : 5 FEET

EXPLANATION

- CONTROL POINT
- 1370 STRUCTURE CONTOUR LINE
- LOW CLOSURE
- TILL SAND SUBCROP : LAVERY TILL NOT PRESENT ABOVE UNIT ; TILL SAND DIRECTLY OVERLAIN BY EITHER ALLUVIUM OR FILL MATERIAL
- LIMIT OF ALLUVIAL COVER ON THE LAVERY TILL
- SEEP (U.S.G.S. WATER RESOURCES INVES. REPORT 85-4145)

NOTES:

THE BASE MAP SHOWN HERE HAS BEEN IMPORTED FROM DWG 900D-5000 SH 3 FOR USE IN RCRA FACILITY INVESTIGATION REPORTS. THIS DATA BASE IS REPRESENTATIVE OF CONDITIONS AS OF JUNE, 1992. FUTURE USERS ARE REQUIRED TO OBTAIN UPDATES MADE TO DWG 900D-5000 SH 3.

TOPOGRAPHIC MAPPING COMPILED BY TALLAMY, VAN KUREN, GERTIS & ASSOCIATES USING STEREOPHOTOGRAMMETRIC METHODS FROM 1:6000 SCALE AERIAL PHOTOGRAPHY FLOWN ON 5/17/89

HORIZONTAL DATUM: NYS PLANE COORDINATE SYSTEM, WEST ZONE

VERTICAL DATUM: NGVD , 1929

SCALE

100 0 100 200 300 400

CONTOUR INTERVAL: 10 FEET

REVISIONS		
REV.	DESCRIPTION	APVD

UNLESS OTHERWISE SPECIFIED

2 PL DEC ± | 3 PL DEC ± | ANGLES ± | AA

FRACTIONS ±

D.SPEC.NO.

NEXT ASSEMBLY

DRAFTER		DATE
CHECKER		DATE
ENGR.		DATE
COG.MGR.APPVL		DATE
E&OS APPVL		DATE
Q.A.APPVL		DATE
DFTG.SUPR.		DATE

A/E CONTRACT NO. | CODE IDENT. NO.

FOR

West Valley Nuclear Services Co.,Inc.
West Valley, New York

DWG SIZE D | SCALE | WEIGHT | DWG NO. | REV | A/E DWG NO. | SHEET OF

CAD DRAWING-DO NOT REVISE THIS ORIGINAL

PLATE 6

WVDP-RFI-014, REV. 0