

PART III – LIST OF DOCUMENTS, EXHIBITS, AND OTHER ATTACHMENTS
SECTION J – LIST OF ATTACHMENTS
ATTACHMENT J-12 – GOVERNMENT FURNISHED SERVICES AND ITEMS (GFS&I)

Description	GFS&I
1. Government Controlled Data Systems/Infrastructure	DOE will ensure the following systems are available to the Contractor throughout the period of performance of this Contract: <ol style="list-style-type: none"> 1. Computerized Accident/Incident Reporting System (CAIRS) 2. Integrated Planning Accountability and Budget System (IPABS) 3. Project Assessment and Reporting System (PARSII) 4. Facility Information Management System (FIMS) 5. Non-Compliance Tracking System (NTS) database 6. Occurrence Reporting and Processing System (ORPS) 7. Foreign Access Central Tracking System (FACTS) database 8. Federal Telephone System Access 9. Condition Assessment Information System (CAIS) 10. iBenefits
2. SRS Computing	DOE shall provide use of and support for government-owned SRS computing infrastructure and all related software applications, including but not limited to: PrimaVera, Site Tracking, Analysis, & Reporting System (STARS), Lotus Notes, InSite, PeopleSoft, Procurement Cycle System (PCS), Field Material Tracking system (FMTS), Asset Management Information System (AMIS), and Passport.
3. Liquid Waste System Facilities	DOE shall provide use of DOE-owned SRS Liquid Waste facilities and infrastructure necessary for the Contractor to perform the Liquid Waste scope of work. See attached FIMS listing. Section J, Attachment 12, Appendix A.
4. Liquid Waste System Property	DOE shall provide use of DOE-owned SRS Liquid Waste property necessary for the Contractor to perform the Liquid Waste scope of work.

Description	GFS&I
5. Liquid Waste Functional Service Agreements	DOE shall provide the Contractor the current established Functional Service Agreements for the LW contractor provided by the M&O contractor. These SRS Liquid Waste FSAs are necessary for the Contractor to perform the Liquid Waste scope of work. The agreement that authorizes exchange of specific, direct-funded services between the M&O contractor and an SRS Tenant per the provisions of the MOA previously established between the two Parties. These services are DOE direct funded and are not part of the LW contract. Section J, Attachment 12, Appendix B.
6. Liquid Waste GSA Leased Vehicles	DOE shall provide the Contractor with the opportunity to utilize General Services Administration (GSA) vehicles to support mission needs. GSA vehicles are provided at a better than commercial rate. GSA approves the number of vehicles for use on each particular contract/project. Section J, Attachment 12, Appendix C.

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes	
1	Liquid Waste Contractor	Operating	Trailer	B	707009	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
2	Liquid Waste Contractor	Operating	Trailer	B	707010	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
3	Liquid Waste Contractor	Operating	Trailer	B	707019	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
4	Liquid Waste Contractor	Operating	Trailer	B	707020	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
5	Liquid Waste Contractor	Operating	Trailer	B	707021	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
6	Liquid Waste Contractor	Operating	Trailer	B	707061	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
7	Liquid Waste Contractor	Operating	Trailer	B	707062	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
8	Liquid Waste Contractor	Operating	Trailer	B	707063	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
9	Liquid Waste Contractor	Operating	Building	E	641000	HIGH POINT DRAIN	N	MB16 Other-Desc brief in Notes field/supp doc	720	1968	1	694 Other Service Buildings		Fair			
10	Liquid Waste Contractor	Operating	Trailer	E	707001	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
11	Liquid Waste Contractor	Operating	Trailer	E	707002	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
12	Liquid Waste Contractor	Operating	Trailer	E	707003	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
13	Liquid Waste Contractor	Operating	Trailer	E	707004	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
14	Liquid Waste Contractor	Operating	Trailer	E	707005	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	2,043	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
15	Liquid Waste Contractor	Operating	Trailer	E	707006	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
16	Liquid Waste Contractor	Operating	Trailer	E	707007	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
17	Liquid Waste Contractor	Operating	Trailer	E	707008	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
18	Liquid Waste Contractor	Operating	Trailer	E	707009	CONFERENCE ROOM TRAILER	N	MB05 Steel Light Frame	1,726	2009		233 Tech Transfer/Conference Buildings		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
19	Liquid Waste Contractor	Operating	Trailer	E	707010	CONFERENCE ROOM TRAILER	N	MB05 Steel Light Frame	1,728	2009		233 Tech Transfer/Conference Buildings		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
20	Liquid Waste Contractor	Operating	Trailer	E	707011	RESTROOM TRAILER	N	MB05 Steel Light Frame	743	2009		298 Comfort Station/Restrooms		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
21	Liquid Waste Contractor	Operating	Trailer	E	707012	RESTROOM TRAILER	N	MB05 Steel Light Frame	653	2009		298 Comfort Station/Restrooms		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
22	Liquid Waste Contractor	Operating	Trailer	E	707013	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
23	Liquid Waste Contractor	Operating	Trailer	E	707014	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
24	Liquid Waste Contractor	Operating	Trailer	E	707015	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
25	Liquid Waste Contractor	Operating	Trailer	E	707016	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
26	Liquid Waste Contractor	Operating	Trailer	E	707017	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
27	Liquid Waste Contractor	Operating	Trailer	E	707018	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,728	2009		101 Office		Excellent		Supports the Radioactive Liquid Waste Disposition mission.	
28	Liquid Waste Contractor	Operating	OSF	F	241000	SYSTEMS SUPPLY WASTE STORAGE TANKS 1-8	N			1954		6009 Other, Other,Service Structures	N				
29	Liquid Waste Contractor	Operating	OSF	F	241002	FDB-1											
30	Liquid Waste Contractor	Unknown	OSF	F	241006	Waste Storage Tanks 17 thru 20											
31	Liquid Waste Contractor	Unknown	OSF	F	241008	C2 Riser Hut											
32	Liquid Waste Contractor	Reserved	OSF	F	241009	C2 Riser Hut											
33	Liquid Waste Contractor	Unknown	OSF	F	241010	Tanks 33 and 34 Vamp Towers											
34	Liquid Waste Contractor	Operating	OSF	F	241011	GANG VALVE HOUSE	N			1989		2009 Catchall	N				
35	Liquid Waste Contractor	Operating	Building	F	241013	WEST PUMPHOUSE	N	MB03 Steel Moment Frame	847	1976	1	694 Other Service Buildings		Poor			
36	Liquid Waste Contractor	Operating	OSF	F	241014	Waste Storage Tanks 26 thru 28											
37	Liquid Waste Contractor	Operating	OSF	F	241015	Effluent Pump Station											
38	Liquid Waste Contractor	Operating	Building	F	241017	EAST PUMPHOUSE	N	MB05 Steel Light Frame	1,139	1980	1	694 Other Service Buildings		Fail			
39	Liquid Waste Contractor	Operating	Building	F	241018	CONTROL ROOM/MCC	N	MB03 Steel Moment Frame	7,564	1980	2	642 Communications/Control Centers		Fail			
40	Liquid Waste Contractor	Shutdown P	OSF	F	241019	EMER DIES GENER TANKS/25-28, 44-47, EVAP	N			1980		5906 Electric Generators	N				
41	Liquid Waste Contractor	Operating	OSF	F	241020	COOLING TOWERS/PUMPHOUSE SER 25-28,44-47	N			1980		5769 Towers (Chill Water)	N				
42	Liquid Waste Contractor	Operating	OSF	F	241021	FDB-4 AND FPPs 2 AND 3	N			1980		6009 Other, Other,Service Structures	Y				
43	Liquid Waste Contractor	Operating	OSF	F	241022	LIFT STATION SOUTH OF TANK 8											
44	Liquid Waste Contractor	Operating	OSF	F	241023	STORM H2O DIV BOX TKS 25-28,44-47,MON 4F	N			1980		2009 Catchall	N				
45	Liquid Waste Contractor	Operating	Trailer	F	241024	RCO TRAILER	N	MB05 Steel Light Frame	1,493	1983		791 Laboratories, General (Non-Nuclear)		Poor			
46	Liquid Waste Contractor	Operating	OSF	F	241025	CHEMICAL STORAGE TANK											
47	Liquid Waste Contractor	Operating	Building	F	241028	OFFICE/CHANGE ROOMS	N	MB05 Steel Light Frame	2,602	1982	1	101 Office		Poor			
48	Liquid Waste Contractor	Operating	OSF	F	241029	COOLING TOWER FOR EVAP #2				1982		5769 Towers (Chill Water)	N				
49	Liquid Waste Contractor	Unknown	Building	F	241031	DIVERSION BOX & PUMP PIT CONTAINMENT BLDG											
50	Liquid Waste Contractor	Operating	OSF	F	241032	FDB-6 DIVERSION BOX	N			1982		6009 Other, Other,Service Structures	Y				
51	Liquid Waste Contractor	Operating	OSF	F	241033	FDB-5 DIVERSION BOX	N			1982		2009 Catchall	Y				
52	Liquid Waste Contractor	Unknown	OSF	F	241048	LAW DISPOSAL VAULT											
53	Liquid Waste Contractor	Unknown	Building	F	241052	10 X 16 HP EQUIPMENT HANDI-HOUSE											
54	Liquid Waste Contractor	Operating	Building	F	241053	AIR COMPRESSOR BUILDING	N	MB05 Steel Light Frame	600	1980	1	694 Other Service Buildings		Fail			
55	Liquid Waste Contractor	Operating	OSF	F	241054	WASTE STORAGE TANKS 44 THRU 47											
56	Liquid Waste Contractor	Reserved	Building	F	241055	PROCESS AIR COMPRESSOR FACILITY											
57	Liquid Waste Contractor	Operating	Building	F	241058	MAINTENANCE SHOP BUILDING	N	MB04 Steel Braced Frame	2,507	1983	1	601 Maintenance Shops, General		Fair			
58	Liquid Waste Contractor	Operating	Trailer	F	241059	E&I (SHIFT) FACILITY	N	MB05 Steel Light Frame	765	1992		400 General Storage		Poor			
59	Liquid Waste Contractor	Operating	Trailer	F	241060	E&I EQUIPMENT STORAGE	N	MB05 Steel Light Frame	571	1989		400 General Storage		Poor			
60	Liquid Waste Contractor	Operating	Building	F	241062	MCC BUILDING	N	MB05 Steel Light Frame	400	1984	1	599 Other Industrial Facilities		Fail			
61	Liquid Waste Contractor	Shutdown P	Building	F	241064	AIR COMPRESSOR BUILDING	N	MB05 Steel Light Frame	492	1983	1	694 Other Service Buildings		Not Applicable			
62	Liquid Waste Contractor	Operating	Building	F	241065	BREATHING AIR COMPRESSOR BUILDING	N	MB04 Steel Braced Frame	440	1983	1	694 Other Service Buildings		Fail			
63	Liquid Waste Contractor	Unknown	Building	F	241067	SWP CLOTHING CHANGE STATION											
64	Liquid Waste Contractor	Unknown	OSF	F	241073	BEARING & INHIBITED WATER											
65	Liquid Waste Contractor	Operating	Building	F	241074	CONTROL ROOM/MCC	N	MB05 Steel Light Frame	1,800	1980	1	694 Other Service Buildings		Fail			
66	Liquid Waste Contractor	Operating	Building	F	241075	CESIUM REMOVAL CONTROL PUMP HOUSE	N	MB04 Steel Braced Frame	141	2000	1	694 Other Service Buildings		Poor			
67	Liquid Waste Contractor	Operating	OSF	F	241076	DIVERSION BOX	N			1990		2009 Catchall	Y				

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (BPPI)	Summary Condition	Excess Date	Condition Notes
68	Liquid Waste Contractor	Operating	OSF	F	241077	FDB-3 DIVERSION BOX										
69	Liquid Waste Contractor	Unknown	OSF	F	241080	MAINTENANCE & E&I STORAGE FACILITY										
70	Liquid Waste Contractor	Unknown	OSF	F	241081	STORAGE HUSE, T&T MATERIAL										
71	Liquid Waste Contractor	Operating	Building	F	241084	INTERIM RECORD STORAGE	N	MB15 Unreinforced Masonry Bearing Walls	680	1986	1	694 Other Service Buildings		Fail		
72	Liquid Waste Contractor	Operating	Building	F	241091	WASTE CERTIFICATION BUILDING	N	MB03 Steel Moment Frame	2,413	1986	1	571 Manufacturing Inspection Building		Adequate		
73	Liquid Waste Contractor	Operating	OSF	F	241092	STORAGE PAD										
74	Liquid Waste Contractor	Operating	Building	F	241093	ALARA STORAGE BUILDING	N	MB03 Steel Moment Frame	618	1986	1	400 General Storage		Poor		
75	Liquid Waste Contractor	Operating	Trailer	F	241096	CHEMICAL ADDITION BUILDING	N	MB05 Steel Light Frame	182	1987		801 Other		Poor		
76	Liquid Waste Contractor	Operating	OSF	F	241097	COOLING WATER BASIN	N			1990		5789 Cooling Ponds Or Reservoirs	N			
77	Liquid Waste Contractor	Operating	Trailer	F	241098	CHANGE HOUSE	N	MB05 Steel Light Frame	48	1990		631 Change Houses		Fail		
78	Liquid Waste Contractor	Operating	Building	F	241099	MCC BUILDING	N	MB05 Steel Light Frame	750	1990	1	694 Other Service Buildings		Fail		
79	Liquid Waste Contractor	Operating	Trailer	F	241100	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,760	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the interior and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
80	Liquid Waste Contractor	Operating	Trailer	F	241102	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,760	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the interior and the electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
81	Liquid Waste Contractor	Operating	Trailer	F	241103	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,760	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the interior and the electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
82	Liquid Waste Contractor	Operating	Building	F	241104	STORAGE/SUPPLY BUILDING	N	MB05 Steel Light Frame	2,400	1995	1	400 General Storage		Fair		
83	Liquid Waste Contractor	Unknown	Building	F	241105	CHANGE FACILITY										
84	Liquid Waste Contractor	Unknown	Building	F	241106	CHANGE FACILITY										
85	Liquid Waste Contractor	Operating	OSF	F	241107	DILUTION FACILITY FOR F-AREA TANK FARM	N			2000		6009 Other, Other Service Structures	N			
86	Liquid Waste Contractor	Operating	Trailer	F	241108	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,749	1991		101 Office		Poor		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, interior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
87	Liquid Waste Contractor	Operating	Trailer	F	241109	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,773	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, interior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
88	Liquid Waste Contractor	Operating	Trailer	F	241110	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,770	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
89	Liquid Waste Contractor	Operating	OSF	F	241116	PORTABLE HEATING AND VENTILATION SKID										
90	Liquid Waste Contractor	Unknown	Building	F	241118	RAD COM MONITOR BUILDING										
91	Liquid Waste Contractor	Unknown	OSF	F	241119	SKID MOUNTED BOOSTER ASSEMBLY										
92	Liquid Waste Contractor	Operating	OSF	F	241120	GANG VALVE HOUSE										
93	Liquid Waste Contractor	Operating	Building	F	241121	STORAGE SHACK										
94	Liquid Waste Contractor	Operating	OSF	F	241123	AIR PURGE FILTER										
95	Liquid Waste Contractor	Operating	Building	F	241124	SAMPLE STORAGE BUILDING	N	MB05 Steel Light Frame	180	1989	1	400 General Storage		Fair		
96	Liquid Waste Contractor	Operating	OSF	F	241125	PUMP TRANSFER SWITCH PAD										
97	Liquid Waste Contractor	Operating	Building	F	241126	PERSONNEL MONITORING BUILDING										
98	Liquid Waste Contractor	Operating	Trailer	F	241127	FTF OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	1988		101 Office		Poor		This Modular Office is 27 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
99	Liquid Waste Contractor	Reserved	OSF	F	241128	FTF ENHANCED CHEMICAL CLEANING PROCESS FACILITY										
100	Liquid Waste Contractor	Operating	OSF	F	241901	WASTE STORAGE TANK 01	N			1980		4441 Tanks (Hazardous Contaminated)	Y			
101	Liquid Waste Contractor	Operating	OSF	F	241902	WASTE STORAGE TANK 02	N			1954		4441 Tanks (Hazardous Contaminated)	Y			
102	Liquid Waste Contractor	Operating	OSF	F	241903	WASTE STORAGE TANK 03	N			1954		4441 Tanks (Hazardous Contaminated)	Y			
103	Liquid Waste Contractor	Operating	OSF	F	241904	WASTE STORAGE TANK 04	N			1954		4441 Tanks (Hazardous Contaminated)	Y			
104	Liquid Waste Contractor	D&D in Prog	OSF	F	241905	WASTE STORAGE TANK 05	Y			1954		4441 Tanks (Hazardous Contaminated)	Y		07/07/2014	
105	Liquid Waste Contractor	D&D in Prog	OSF	F	241906	WASTE STORAGE TANK 06	Y			1954		4441 Tanks (Hazardous Contaminated)	Y		07/07/2014	
106	Liquid Waste Contractor	Operating	OSF	F	241907	WASTE STORAGE TANK 07	N			1954		4441 Tanks (Hazardous Contaminated)	Y			
107	Liquid Waste Contractor	Operating	OSF	F	241908	WASTE STORAGE TANK 08	N			1954		4441 Tanks (Hazardous Contaminated)	Y			
108	Liquid Waste Contractor	Shutdown P	OSF	F	241917	WASTE STORAGE TANK 17	Y			1959		4441 Tanks (Hazardous Contaminated)	Y		08/13/2014	
109	Liquid Waste Contractor	D&D in Prog	OSF	F	241918	WASTE STORAGE TANK 18	Y			1959		4441 Tanks (Hazardous Contaminated)	Y			
110	Liquid Waste Contractor	D&D in Prog	OSF	F	241919	WASTE STORAGE TANK 19	Y			1959		4441 Tanks (Hazardous Contaminated)	Y		07/07/2014	
111	Liquid Waste Contractor	Shutdown P	OSF	F	241920	WASTE STORAGE TANK 20	Y			1959		4441 Tanks (Hazardous Contaminated)	Y			
112	Liquid Waste Contractor	Operating	OSF	F	241925	WASTE STORAGE TANK 25	N			1980		4441 Tanks (Hazardous Contaminated)	Y		08/13/2014	
113	Liquid Waste Contractor	Operating	OSF	F	241926	WASTE STORAGE TANK 26	N			1980		4441 Tanks (Hazardous Contaminated)	Y			
114	Liquid Waste Contractor	Operating	OSF	F	241927	WASTE STORAGE TANK 27	N			1980		4441 Tanks (Hazardous Contaminated)	Y			
115	Liquid Waste Contractor	Operating	OSF	F	241928	WASTE STORAGE TANK 28	N			1980		4441 Tanks (Hazardous Contaminated)	Y			
116	Liquid Waste Contractor	Operating	OSF	F	241933	WASTE STORAGE TANK 33	N			1972		4441 Tanks (Hazardous Contaminated)	Y			
117	Liquid Waste Contractor	Operating	OSF	F	241934	WASTE STORAGE TANK 34	N			1972		4441 Tanks (Hazardous Contaminated)	Y			
118	Liquid Waste Contractor	Operating	OSF	F	241944	WASTE STORAGE TANK 44	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
119	Liquid Waste Contractor	Operating	OSF	F	241945	WASTE STORAGE TANK 45	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
120	Liquid Waste Contractor	Operating	OSF	F	241946	WASTE STORAGE TANK 46	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
121	Liquid Waste Contractor	Operating	OSF	F	241947	WASTE STORAGE TANK 47	N			1983		4441 Tanks (Hazardous Contaminated)	Y			

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
122	Liquid Waste Contractor	Operational	OSF	F	242000	1F EVAPORATOR	N			1960		6009 Other, Other,Service Structures	N			
123	Liquid Waste Contractor	Operating	Building	F	242001	WASTE EVAPORATOR #1 CONTROL HOUSE	N	MB05 Steel Light Frame	1,072	1974	1	599 Other Industrial Facilities		Poor		
124	Liquid Waste Contractor	Operational	OSF	F	242003	WASTE CONCENTRATE Xfer SYS(CTS) PUMP PIT	N			1967		6009 Other, Other,Service Structures	N			
125	Liquid Waste Contractor	Operating	Trailer	F	242008	RADCON TRAILER NEAR FDB-2	N	MB06 Steel Frame with Concrete Shear Walls	224	1994		401 Programmatic General Storage		Fail		
126	Liquid Waste Contractor	Operating	Trailer	F	242009	RADCON TRAILER NEAR TANKS 33/34	N	MB05 Steel Light Frame	224	1994		401 Programmatic General Storage		Fail		
127	Liquid Waste Contractor	Operating	Trailer	F	242010	RADCON TRAILER NEAR TANK 4	N	MB05 Steel Light Frame	220	1990		401 Programmatic General Storage		Fail		
128	Liquid Waste Contractor	Operating	Trailer	F	242011	RADCON TRAILER NEAR 1F EVAPORATOR	N	MB05 Steel Light Frame	160	1990		401 Programmatic General Storage		Fail		
129	Liquid Waste Contractor	Operating	Trailer	F	242012	RADCON TRAILER AND 2 F EVAPORATOR	N									
130	Liquid Waste Contractor	Operating	Trailer	F	242013	MODULAR TRAILER	N	MB05 Steel Light Frame	655	1994		401 Programmatic General Storage		Excellent		Supports the Radioactive Liquid Waste Disposition mission.
131	Liquid Waste Contractor	Operating	Building	F	242016	2F EVAPORATOR	N	MB09 Concrete Shear Walls	2,364	1982	1	694 Other Service Buildings		Poor		
132	Liquid Waste Contractor	Operating	Trailer	F	242021	FTF RCO COUNTING ROOM TRAILER	N	MB05 Steel Light Frame	163	2001		792 Laboratories, General (Nuclear)		Fail		
133	Liquid Waste Contractor	Operating	OSF	F	252102	TRANSFORMER FOR 717_30F	N			2008		8988 Power Transformers	N			
134	Liquid Waste Contractor	Operating	OSF	F	254001	1F EMERGENCY DIESEL GENERATOR	N									
135	Liquid Waste Contractor	Operational	OSF	F	254004	DIESEL SER PUMPSHOUSE/TANKS 25-28, 44-47	N			1980		5008 Pumping Stations	N			
136	Liquid Waste Contractor	Operating	OSF	F	254008	DIESEL GENERATOR	N			1990		5906 Electric Generators	N			
137	Liquid Waste Contractor	Operating	Trailer	F	263239	HEAT OASIS/CHANGE HOUSE	N	MB05 Steel Light Frame	237	1989		631 Change Houses		Poor		
138	Liquid Waste Contractor	Operating	OSF	F	281007	WEIR BOX #2	N									
139	Liquid Waste Contractor	Operating	OSF	F	281008	STORAGE BASIN, 4 MILLION GALLON, LINED	N			1974		4109 Other, Water Storage	N			
140	Liquid Waste Contractor	Operating	OSF	F	281009	PUMP PIT FOR STORAGE BASIN	N			1974		1309 Other,Water Transportation System	N			
141	Liquid Waste Contractor	Operating	OSF	F	281010	FILTER AND DEIONIZER FACILITY	N			1983		2009 Catchall	N			
142	Liquid Waste Contractor	Operating	OSF	F	607020	LIFT STATION	N			1990		5009 Structures, Industrial, Other	N			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ESKH and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operation budgets.
143	Liquid Waste Contractor	Operating	OSF	F	619002	DIESEL FUEL TANK										
144	Liquid Waste Contractor	Operating	OSF	F	641000	INTER TRANSFER LINES DIVER BOX/PUMP PIT	N			1970		6009 Other, Other,Service Structures	Y			
145	Liquid Waste Contractor	Operating	Building	F	704026	ADMINISTRATION BUILDING	N	MB03 Steel Moment Frame	5,099	1983	1	101 Office		Poor		Asset has deficiencies that limit performance of the Radioactive liquid wastes disposition mission including attracting and maintaining key staff, poses added ESKH and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
146	Liquid Waste Contractor	Operating	Trailer	F	704070	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	1991		101 Office		Poor		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
147	Liquid Waste Contractor	Operating	Trailer	F	704071	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	1991		101 Office		Poor		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
148	Liquid Waste Contractor	Operating	Trailer	F	704075	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	840	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
149	Liquid Waste Contractor	Operating	Building	F	717011	ADMINISTRATION BUILDING	N	MB04 Steel Braced Frame	4,867	1983	2	101 Office		Fair		Asset has deficiencies that limit performance of the Radioactive liquid wastes disposition mission including attracting and maintaining key staff, poses added ESKH and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
150	Liquid Waste Contractor	Operating	OSF	F	717015	HAZARDOUS WASTE STAGING AREA										
151	Liquid Waste Contractor	Operating	Trailer	F	717020	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	880	1987		101 Office		Fail		This Modular Office is 27 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
152	Liquid Waste Contractor	Operating	Trailer	F	717021	RESTROOM TRAILER	N	MB05 Steel Light Frame	526	1995		298 Comfort Station/Restrooms		Fail		This Modular Office is 19 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
153	Liquid Waste Contractor	Operating	Trailer	F	717022	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	1991		101 Office		Fail		This Modular Office is 22 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
154	Liquid Waste Contractor	Operating	Trailer	F	717023	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	551	2001		101 Office		Fail		This Modular Office is greater than 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
155	Liquid Waste Contractor	Operating	Building	F	717030	F-AREA TANK FARM CONSTRUCTION FABRICATION FACILITY										
156	Liquid Waste Contractor	Operating	Trailer	F	725000	TOOL STORAGE HOUSE										
157	Liquid Waste Contractor	Operating	OSF	F	907000	STORM SEWERS	N			1972		2009 Catchall	Y			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ESKH and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operation budgets.
158	Liquid Waste Contractor	Operating	OSF	F	907001	DIVERSION BOX	N			1974		2009 Catchall	Y			
159	Liquid Waste Contractor	Operating	OSF	F	907002	STORM WATER MONITORING STATION	N			1988		2009 Catchall	N			
160	Liquid Waste Contractor	Operating	OSF	F	907003	STORM WATER MONITORING STATION	N			1988		2009 Catchall	N			
161	Liquid Waste Contractor	Operating	OSF	F	907004	STORM WATER MONITORING STATION	N			1980		2009 Catchall	N			

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes	
162	Liquid Waste Contractor	Operating	Trailer	G	241001	MOBILE WASTE REMOVAL CTRL CTR (TRL)	N	MB05 Steel Light Frame	320	2004		694 Other Service Buildings		Poor			
163	Liquid Waste Contractor	Reserved	Trailer	G	241002	MOBILE WASTE REMOVAL CTRL CTR (H-AREA TRL)											
164	Liquid Waste Contractor	Reserved	OSF	G	241003	SALT DISSOLUTION WATER ADDITION/INHIBIT WATER SKIK											
165	Liquid Waste Contractor	Reserved	OSF	G	241005	ELECTRICAL EQUIPMENT SKID #2											
166	Liquid Waste Contractor	Reserved	OSF	G	241006	WATER EVAPORATION SKID											
167	Liquid Waste Contractor	Operating	OSF	G	241007	PNEUMATIC PUMP REGULATOR STATION											
168	Liquid Waste Contractor	Operating	OSF	G	251001	MOBILE WASTE REMOVAL SUBSTATION (SKID)											
169	Liquid Waste Contractor	Reserved	OSF	G	251002	MOBILE WASTE REMOVAL SUBSTATION (H-AREA SKID)											
170	Liquid Waste Contractor	Operating	Building	G	606024	ETF EFFLUENT MONITOR HOUSE											
171	Liquid Waste Contractor	Operating	LAND	G	678006	WASTE TANK MOCK-UP RETENTION BASIN											
172	Liquid Waste Contractor	Operating	Trailer	G	704005	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	2,106	1991		101 Office		Poor		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC Systems, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
173	Liquid Waste Contractor	Operating	Trailer	G	704035	MOBILE RESTROOM TRAILER (FOR WR & TC IN T-AREA)											
174	Liquid Waste Contractor	Operating	Building	G	705002	MODULAR STORAGE BUILDING											
175	Liquid Waste Contractor	Operating	Trailer	G	742000	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1990		101 Office		Poor		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, roof, HVAC, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
176	Liquid Waste Contractor	Operating	Trailer	G	742001	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1990		101 Office		Fail		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, roof, HVAC, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
177	Liquid Waste Contractor	Operating	Trailer	G	742002	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1990		101 Office		Fail		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, roof, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
178	Liquid Waste Contractor	Operating	Trailer	G	742003	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1990		101 Office		Poor		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
179	Liquid Waste Contractor	Operating	Trailer	G	742004	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1990		101 Office		Poor		This Modular Office is 25 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, roof, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
180	Liquid Waste Contractor	Operating	Trailer	G	742005	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1990		101 Office		Fail		This Modular Office is 25 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, roof, HVAC, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
181	Liquid Waste Contractor	Operating	Trailer	G	742006	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1994		101 Office		Fail		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, roof, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
182	Liquid Waste Contractor	Operating	Trailer	G	742007	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1994		101 Office		Fail		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, roof, HVAC, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
183	Liquid Waste Contractor	Operating	Trailer	G	742009	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1993		101 Office		Fail		This Modular Office is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
184	Liquid Waste Contractor	Operating	Trailer	G	742010	RESTROOM TRAILER	N	MB05 Steel Light Frame	519	1993		298 Comfort Station/Restrooms		Fail		This Rest Room Trailer is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC, plumbing, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
185	Liquid Waste Contractor	Operating	Trailer	G	742011	RESTROOM TRAILER	N	MB05 Steel Light Frame	501	1993		298 Comfort Station/Restrooms		Fail		This Rest Room Trailer is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, roof, HVAC, plumbing, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
186	Liquid Waste Contractor	Operating	Trailer	G	742012	LUNCHROOM TRAILER	N	MB05 Steel Light Frame	939	1993		291 Cafeteria		Fail		This Lunchroom Trailer is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	
187	Liquid Waste Contractor	Operating	Trailer	G	742013	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1993		101 Office		Poor		This Modular Office is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC, roof, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.	

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
188	Liquid Waste Contractor	Operating	Trailer	G	742014	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,706	1990		101 Office		Fail		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC, roof, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
189	Liquid Waste Contractor	Operating	OSF	H	80010	FAR EAST LAYDOWN PAD										
190	Liquid Waste Contractor	Ops Standby	OSF	H	81001	TANK 37 CTS LINE LEAK										
191	Liquid Waste Contractor	Reserved	OSF	H	211011	PERSONNEL SHELTER										
192	Liquid Waste Contractor	Operating	Building	H	217002	CRAFT FABRICATION FACILITY										
193	Liquid Waste Contractor	Operating	Building	H	217005	CRAFT FABRICATION FACILITY										
194	Liquid Waste Contractor	Reserved	Building	H	217006	H-AREA TANK FARM CONSTRUCTION TOOL ROOM										
195	Liquid Waste Contractor	Operating	Building	H	225023	HANDI-HOUSE										
196	Liquid Waste Contractor	Operating	Trailer	H	225025	STORAGE BUILDING										
197	Liquid Waste Contractor	Operating	OSF	H	241000	DIVERSION BOX #1	N			1955		6009 Other, Other, Service Structures	Y			
198	Liquid Waste Contractor	Operating	Building	H	241002	3H CONTROL ROOM & OFFICE BUILDING	N	MB06 Steel Frame with Concrete Shear Walls	14,992	1990	2	501 Production/Manufacturing Buildings		Fair		
199	Liquid Waste Contractor	Operating	OSF	H	241003	H-AREA DIVERSION BOX NO. 3 (HDB3)	N			1955		6009 Other, Other, Service Structures	Y			
200	Liquid Waste Contractor	Operating	OSF	H	241006	LOW LEVEL WASTE STORAGE TANKS 21-24										
201	Liquid Waste Contractor	Operating	Building	H	241008	DIVISION BOX 4 AND GANG VALVE HOUSE	N	MB05 Steel Light Frame	158	1955	1	694 Other Service Buildings		Fair		
202	Liquid Waste Contractor	Operating	OSF	H	241009	EFFLUENT PUMP STATION										
203	Liquid Waste Contractor	Unknown	OSF	H	241012	HIGH LEVEL WASTE STORAGE TANKS 35-37										
204	Liquid Waste Contractor	Operating	Building	H	241013	WEST PUMP HOUSE	N	MB04 Steel Braced Frame	642	1979	1	694 Other Service Buildings		Fail		
205	Liquid Waste Contractor	Operating	Building	H	241014	EAST PUMP HOUSE	N	MB06 Steel Frame with Concrete Shear Walls	847	1955	1	694 Other Service Buildings		Fair		
206	Liquid Waste Contractor	Operating	OSF	H	241015	WASTE STORAGE TANKS 38 THRU 43	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
207	Liquid Waste Contractor	Unknown	Trailer	H	241016	TEMPORARY CHANGE TRAILER										
208	Liquid Waste Contractor	Operating	Building	H	241017	BREATHING AIR COMPRESSOR BLDG.	N	MB05 Steel Light Frame	373	1976	1	599 Other Industrial Facilities		Fail		
209	Liquid Waste Contractor	Operating	OSF	H	241018	TREATED WATER STORAGE TANK	N			1990		4109 Other, Water Storage	N			
210	Liquid Waste Contractor	Operating	OSF	H	241019	TREATED WATER STORAGE TANK	N			1990		4109 Other, Water Storage	N			
211	Liquid Waste Contractor	Operating	OSF	H	241020	TREATED WATER STORAGE TANK	N			1990		4109 Other, Water Storage	N			
212	Liquid Waste Contractor	Operating	OSF	H	241021	CHEMICAL STORAGE TANK SHED										
213	Liquid Waste Contractor	Operating	Building	H	241022	STORAGE SHACK (HANDI-HOUSE)										
214	Liquid Waste Contractor	Operating	Trailer	H	241023	MODULAR TRAILER										
215	Liquid Waste Contractor	Operating	Trailer	H	241024	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	2,252	1977		101 Office		Fail		This Modular Office is 37 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system, and the HVAC systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
216	Liquid Waste Contractor	Operating	Building	H	241025	GANG VALVE HOUSE	N	MB05 Steel Light Frame	150	1979	1	694 Other Service Buildings		Fair		
217	Liquid Waste Contractor	Unknown	Building	H	241026	CHLORINATOR HOUSE										
218	Liquid Waste Contractor	Operating	OSF	H	241027	DIVERSION BOX	N			1970		2009 Catchall	N			
219	Liquid Waste Contractor	Operating	Building	H	241028	2H CONTROL ROOM & OFFICE BUILDING	N	MB05 Steel Light Frame	3,866	1982	1	101 Office		Fail		
220	Liquid Waste Contractor	Operating	OSF	H	241029	COOLING TOWER FOR EVAP #2	N			1995		5769 Towers (Chill Water)	N			
221	Liquid Waste Contractor	Reserved	OSF	H	241030	JUMPER STORAGE PAD										
222	Liquid Waste Contractor	Operating	OSF	H	241031	DB#7 AND GANG VALVE HOUSE	N			1999		6009 Other, Other, Service Structures	Y			
223	Liquid Waste Contractor	Operating	OSF	H	241032	COLD FEEDS AREA	N			1998		6009 Other, Other, Service Structures	N			
224	Liquid Waste Contractor	Operating	Building	H	241033	COLD FEED MCC BUILDING	N	MB08 Concrete Moment Frame	240	1985	1	599 Other Industrial Facilities		Fail		
225	Liquid Waste Contractor	Operating	OSF	H	241034	IX/RO/EVAPORATOR OH TANK CONTAINMENT										
226	Liquid Waste Contractor	Operating	OSF	H	241035	HDB-2 AND PUMP PITS 1-4	N			1955		6009 Other, Other, Service Structures	Y			
227	Liquid Waste Contractor	Operating	OSF	H	241036	EVAPORATOR CONDENSER TANK CONTAINMENT	N			1990		6009 Other, Other, Service Structures	N			
228	Liquid Waste Contractor	Operating	OSF	H	241037	EVAPORATOR FEED TANK	N			1990		4521 Tanks (Sewage)	N			
229	Liquid Waste Contractor	Operating	OSF	H	241038	WASTE TANK VALVE HOUSE TANK 38										
230	Liquid Waste Contractor	Operating	Building	H	241039	WASTE TANK VALVE HOUSE TANK 39										
231	Liquid Waste Contractor	Operating	Building	H	241040	WASTE TANK VALVE HOUSE TANK 40										
232	Liquid Waste Contractor	Operating	Building	H	241041	WASTE TANK VALVE HOUSE TANK 41										
233	Liquid Waste Contractor	Operating	Building	H	241042	WASTE TANK VALVE HOUSE TANK 42										
234	Liquid Waste Contractor	Operating	Building	H	241043	WASTE TANK VALVE HOUSE TANK 43										
235	Liquid Waste Contractor	Unknown	OSF	H	241045	CARPON OVER PNEUMATIC CONVEYER										
236	Liquid Waste Contractor	Operating	Building	H	241049	FAR EAST PUMP HOUSE	N	MB04 Steel Braced Frame	1,897	1982	1	599 Other Industrial Facilities		Fail		
237	Liquid Waste Contractor	Unknown	OSF	H	241050	COOLING TOWER SERVICING 241-49H										
238	Liquid Waste Contractor	Operating	OSF	H	241051	STORM DIVERSION BOX	N			1983		2009 Catchall	N			
239	Liquid Waste Contractor	Operating	OSF	H	241052	DIVERSION BOX DB#5	N			1968		2009 Catchall	Y			
240	Liquid Waste Contractor	Operating	OSF	H	241053	HVAC HEPA CONTAINMENT	N			1990		2009 Catchall	N			
241	Liquid Waste Contractor	Operating	OSF	H	241054	CHEMICAL MAKEUP TANK CONTAINMENT	N			1990		4009 Other, Storage	N			
242	Liquid Waste Contractor	Operating	Trailer	H	241055	MODULAR TRAILER	N	MB05 Steel Light Frame	670	1985		694 Other Service Buildings		Poor		This Modular Office is 29 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, interior, and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
243	Liquid Waste Contractor	Operating	OSF	H	241056	H-Area Diversion Box No. 6 (HDB6)	N			1979		5009 Structures, Industrial, Other	Y			
244	Liquid Waste Contractor	Operating	Building	H	241057	LAUNDRY BUILDING	N	MB05 Steel Light Frame	835	1979	1	692 Laundry (Contaminated)		Fair		
245	Liquid Waste Contractor	Operating	Building	H	241058	MAINTENANCE AND E & I SHOP	N	MB04 Steel Braced Frame	4,439	1982	1	601 Maintenance Shops, General		Fair		
246	Liquid Waste Contractor	Unknown	Building	H	241059	WASTE TANK INSPECTION EQUIP HANDI-HOUSE										
247	Liquid Waste Contractor	Operating	OSF	H	241060	TANK TRUCK UNLOADING STATION										
248	Liquid Waste Contractor	Operating	OSF	H	241061	ACID/CAUSTIC STORAGE TANK CONTAINMENT	N			1990		4009 Other, Storage	N			
249	Liquid Waste Contractor	Operating	Building	H	241062	MOTOR CONTROL CENTER	N	MB05 Steel Light Frame	356	1984	1	694 Other Service Buildings		Fail		
250	Liquid Waste Contractor	Unknown	OSF	H	241063	WASTE TANK INSPECTION EQUIP STORAGE #2										
251	Liquid Waste Contractor	Operating	Building	H	241064	PROCESS AIR COMPRESSOR BUILDING	N	MB04 Steel Braced Frame	621	1983	1	599 Other Industrial Facilities		Fair		
252	Liquid Waste Contractor	Operating	Building	H	241065	MAINTENANCE OFFICE BUILDING	N	MB05 Steel Light Frame	329	1989	1	101 Office		Poor		Asset has deficiencies that limit performance of the Radioactive liquid wastes disposition mission including attracting and maintaining key staff, poses added ESH and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
253	Liquid Waste Contractor	Unknown	Building	H	241066	WASTE MGMT EQUIPMENT HANDI-HOUSE										
254	Liquid Waste Contractor	Unknown	Building	H	241067	SWP CLOTHING CHANGE STATION										
255	Liquid Waste Contractor	Operating	OSF	H	241068	GANG VALVE HOUSE FOR PUMP PIT 5-6(241-70)	N			1982		5009 Structures, Industrial, Other	N			

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross SqFt	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
256	Liquid Waste Contractor	Operating	OSF	H	241069	VALVE HOUSE FOR PUMP PIT 5-6(241-70H)										
257	Liquid Waste Contractor	Operating	OSF	H	241070	PROCESS PUMP PIT FOR NEW WASTE HEADER	N			1982		5441 Plants (Hazardous,Contaminated)	N			
258	Liquid Waste Contractor	Operating	OSF	H	241071	PROCESS WATER TANK	N			1990		4171 Tanks, Pressure (Non-Potable)	N			
259	Liquid Waste Contractor	Operating	Trailer	H	241072	CHANGE HOUSE	N	MB05 Steel Light Frame	95	1990		631 Change Houses		Fail		
260	Liquid Waste Contractor	Operating	OSF	H	241073	ACID STORAGE TANKS										
261	Liquid Waste Contractor	Operating	Building	H	241074	CONTROL ROOM & MCC BUILDING	N	MB07 Steel Frame with Infill Shear Walls	1,800	1996	1	599 Other Industrial Facilities		Adequate		
262	Liquid Waste Contractor	Operating	OSF	H	241075	WASTEWATER COLLECTION TANK CONTAINMENT	N			1990		4009 Other, Storage	N			
263	Liquid Waste Contractor	Operating	OSF	H	241076	MERCURY REMOVAL AND CARBON TANK AREA	N			1994		6009 Other, Other,Service Structures	N			
264	Liquid Waste Contractor	Operating	Building	H	241077	COLD FEED NITROGEN STORAGE BUILDING	N	MB05 Steel Light Frame	249	1989	1	501 Production/Manufacturing Buildings		Fail		
265	Liquid Waste Contractor	Operating	Building	H	241078	STORAGE FACILITY	N	MB05 Steel Light Frame	513	1988	1	400 General Storage		Poor		
266	Liquid Waste Contractor	Unknown	Building	H	241079	CAUSTIC UNLOADING FACILITY										
267	Liquid Waste Contractor	Operating	Building	H	241080	STORAGE HANDI-HOUSE										
268	Liquid Waste Contractor	Operating	Building	H	241081	TREATMENT BUILDING	N	MB03 Steel Moment Frame	20,970	1990	1	591 Materials Handling Or Processing Fa		Adequate		
269	Liquid Waste Contractor	Operating	Building	H	241082	ITP CONTROL BUILDING	N	MB05 Steel Light Frame	4,461	1997	2	501 Production/Manufacturing Buildings		Fail		
270	Liquid Waste Contractor	Unknown	OSF	H	241083	WASTE STORAGE TANKS 48-51										
271	Liquid Waste Contractor	Operating	Building	H	241084	CONTROL BUILDING	N	MB03 Steel Moment Frame	8,646	1990	1	591 Materials Handling Or Processing Fa		Fail		
272	Liquid Waste Contractor	Operating	Building	H	241085	PERSONNEL MONITOR BUILDING NORTH GATE	N	MB05 Steel Light Frame	680	1986	1	694 Other Service Buildings		Fair		
273	Liquid Waste Contractor	Operating	Building	H	241086	PERSONNEL MONITOR BUILDING A	N	MB05 Steel Light Frame	117	1986	1	694 Other Service Buildings		Poor		
274	Liquid Waste Contractor	Operating	Building	H	241087	ICE HOUSE	N	MB05 Steel Light Frame	100	1986	1	694 Other Service Buildings		Poor		
275	Liquid Waste Contractor	Operating	Building	H	241088	EQUIPMENT STORAGE	N	MB05 Steel Light Frame	105	1986	1	694 Other Service Buildings		Fail		
276	Liquid Waste Contractor	Operating	Building	H	241089	STORAGE & SUPPLY BUILDING	N	MB04 Steel Braced Frame	1,833	1986	1	400 General Storage		Poor		
277	Liquid Waste Contractor	Operating	Building	H	241090	STORAGE & SUPPLY BUILDING	N	MB05 Steel Light Frame	967	1986	1	400 General Storage		Poor		
278	Liquid Waste Contractor	Operating	OSF	H	241091	CONTROL BUILDING EXHAUST FAN										
279	Liquid Waste Contractor	Operating	Building	H	241092	STORAGE & SUPPLY BUILDING	N	MB03 Steel Moment Frame	1,224	1986	1	400 General Storage		Fail		
280	Liquid Waste Contractor	Operating	Trailer	H	241093	ICE HOUSE	N	MB05 Steel Light Frame	363	2001		694 Other Service Buildings		Fail		
281	Liquid Waste Contractor	Operating	Building	H	241096	FILTER/STRIPPER BUILDING	N	MB03 Steel Moment Frame	4,194	1997	1	501 Production/Manufacturing Buildings		Poor		
282	Liquid Waste Contractor	Operating	Building	H	241098	CHEMICAL ADDITION PORTABLE BUILDING	N	MB05 Steel Light Frame	192	1987	1	400 General Storage		Poor		
283	Liquid Waste Contractor	Operating	Building	H	241099	CHEMICAL ADDITION PORTABLE BUILDING	N	MB05 Steel Light Frame	192	1987	1	501 Production/Manufacturing Buildings		Fair		
284	Liquid Waste Contractor	Operating	Building	H	241100	HDBB FACILITY	N	MB04 Steel Braced Frame	10,470	1996	1	501 Production/Manufacturing Buildings		Poor		
285	Liquid Waste Contractor	Operating	Building	H	241101	HDBB HVAC / FILTER BUILDING	N	MB10 Concrete Frame with Infill Shear Walls	1,580	1997	1	501 Production/Manufacturing Buildings		Good		
286	Liquid Waste Contractor	Operating	Building	H	241102	WAREHOUSE BUILDING	N	MB03 Steel Moment Frame	9,936	1996	1	400 General Storage		Fair		
287	Liquid Waste Contractor	Operating	OSF	H	241103	COOLING WATER BASIN				1990		5789 Cooling Ponds Or Reservoirs	N			
288	Liquid Waste Contractor	Operating	OSF	H	241104	INFLUENT PUMP STATION				1990		2009 catchall	N			
289	Liquid Waste Contractor	Operating	Building	H	241105	MCC BUILDING	N	MB05 Steel Light Frame	806	1990	1	694 Other Service Buildings		Fail		
290	Liquid Waste Contractor	Operating	OSF	H	241106	HVAC FA CONTAINMENT										
291	Liquid Waste Contractor	Operating	OSF	H	241107	STACK MONITOR FOUNDATION	N			1990		6009 Other, Other,Service Structures	N			
292	Liquid Waste Contractor	Operating	OSF	H	241108	AIR COMPRESSOR-CLOSED LOOP WATERCOOLERS										
293	Liquid Waste Contractor	Unknown	Building	H	241109	STORAGE BUILDING										
294	Liquid Waste Contractor	Unknown	Building	H	241110	STORAGE BUILDING										
295	Liquid Waste Contractor	Unknown	Building	H	241111	STORAGE BUILDING										
296	Liquid Waste Contractor	Unknown	Building	H	241112	STORAGE BUILDING										
297	Liquid Waste Contractor	Unknown	Building	H	241113	STORAGE BUILDING										
298	Liquid Waste Contractor	Unknown	Building	H	241114	STORAGE BUILDING										
299	Liquid Waste Contractor	Unknown	Building	H	241115	STORAGE BUILDING										
300	Liquid Waste Contractor	Unknown	Building	H	241116	STORAGE BUILDING										
301	Liquid Waste Contractor	Unknown	Building	H	241117	STORAGE BUILDING										
302	Liquid Waste Contractor	Operating	Building	H	241118	STORAGE HANDI-HOUSE										
303	Liquid Waste Contractor	Operating	Trailer	H	241119	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	1988		101 Office		Fail		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
304	Liquid Waste Contractor	Operating	Trailer	H	241120	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,733	1988		101 Office		Fail		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
305	Liquid Waste Contractor	Operating	Trailer	H	241121	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,733	1988		101 Office		Fail		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, interior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
306	Liquid Waste Contractor	Operating	Trailer	H	241122	RESTROOM TRAILER	N	MB05 Steel Light Frame	363	1989		298 Comfort Station/Restrooms		Fail		This Modular Office is 25 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior and the electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
307	Liquid Waste Contractor	Unknown	Building	H	241123	FLAMABLE STORAGE BUILDING										
308	Liquid Waste Contractor	Unknown	OSF	H	241124	STORAGE SHED FOR PORTABLE BREATHING AIR										
309	Liquid Waste Contractor	Operating	Building	H	241125	FIRE WATER PUMP HOUSE	N	MB13 Reinforce Masn Bear Walls/Wood,Metl De	1,710	1989	1	694 Other Service Buildings		Fail		
310	Liquid Waste Contractor	Operating	Trailer	H	241126	LEVEL B STORAGE BUILDING										
311	Liquid Waste Contractor	Operating	Trailer	H	241127	MAINTENANCE TRAILER										
312	Liquid Waste Contractor	Operating	OSF	H	241128	PROCESS AIR COMPRESSOR FACILITY										
313	Liquid Waste Contractor	Operating	OSF	H	241129	PROCESS AIR COMPRESSOR FACILITY										
314	Liquid Waste Contractor	Operating	Trailer	H	241133	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	545	1990		400 General Storage		Fail		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
315	Liquid Waste Contractor	Operating	Trailer	H	241134	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	552	1990		601 Maintenance Shops, General		Poor		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
316	Liquid Waste Contractor	Reserved	Building	H	241135	ECR/ICR BUILDING										
317	Liquid Waste Contractor	Reserved	OSF	H	241140	LEAK DETECTION VAULT										
318	Liquid Waste Contractor	Unknown	Building	H	241141	FIRE PROTECTION FOAM BUILDING										
319	Liquid Waste Contractor	Unknown	Trailer	H	241142	MODULAR OFFICE TRAILER										
320	Liquid Waste Contractor	Operating	Trailer	H	241143	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	350	2001		101 Office		Poor		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
321	Liquid Waste Contractor	Operating	Trailer	H	241144	E&I SHOP TRAILER										
322	Liquid Waste Contractor	Operating	Trailer	H	241145	E&I STORAGE BUILDING	N	MB05 Steel Light Frame	186	1990		400 General Storage		Poor		
323	Liquid Waste Contractor	Operating	Building	H	241146	MAINTENANCE SHOP	N	MB05 Steel Light Frame	623	1989	1	601 Maintenance Shops, General		Adequate		Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ESH and/or security requirements, meets stated DOE objectives or goals, and has only minor deficiencies that can be corrected with normal operating budgets.
324	Liquid Waste Contractor	Operating	Trailer	H	241147	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	711	1977		101 Office		Poor		This Modular Office is 37 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior and the electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
325	Liquid Waste Contractor	Operating	Trailer	H	241148	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	698	1977		101 Office		Poor		This Modular Office is 37 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior and the electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
326	Liquid Waste Contractor	Operating	Building	H	241149	ETF STORAGE BUILDING	N	MB05 Steel Light Frame	2,567	1992	1	450 Shed Storage		Adequate		
327	Liquid Waste Contractor	Unknown	Building	H	241151	HANDI-HOUSE										
328	Liquid Waste Contractor	Operating	Trailer	H	241152	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,744	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
329	Liquid Waste Contractor	Operating	Trailer	H	241153	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,733	1994		101 Office		Fail		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the interior, exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
330	Liquid Waste Contractor	Operating	Trailer	H	241154	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,733	1994		101 Office		Fail		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the interior, exterior, electrical system, and the HVAC Systems is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
331	Liquid Waste Contractor	Operating	Trailer	H	241155	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,749	1993		101 Office		Poor		This Modular Office is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the interior, exterior, electrical system and the HVAC Systems are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
332	Liquid Waste Contractor	Operating	Trailer	H	241156	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,919	1990		101 Office		Poor		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system and the HVAC Systems are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
333	Liquid Waste Contractor	Operating	Trailer	H	241157	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	2,678	1978		101 Office		Poor		This Modular Office is 36 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that major refurbishment of the exterior, electrical system and the HVAC Systems are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
334	Liquid Waste Contractor	Operating	Trailer	H	241161	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,733	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, electrical system and the HVAC Systems are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
335	Liquid Waste Contractor	Operating	Trailer	H	241162	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,733	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
336	Liquid Waste Contractor	Unknown	Trailer	H	241163	RESTROOM TRAILER										
337	Liquid Waste Contractor	Unknown	OSF	H	241167	HAZARDOUS LOW LEVEL WASTE TANKS										
338	Liquid Waste Contractor	Operating	Trailer	H	241168	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,746	1990		101 Office		Poor		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
339	Liquid Waste Contractor	Operating	Building	H	241169	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	537	1992	1	400 General Storage		Poor		Asset has deficiencies that limit performance of the Radioactive liquid wastes disposition mission including attracting and maintaining key staff, poses added ESH and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
340	Liquid Waste Contractor	Operating	Trailer	H	241170	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	543	2005		400 General Storage		Poor		This Modular Office is 17 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
341	Liquid Waste Contractor	Operating	Trailer	H	241173	HANDI-HOUSE										
342	Liquid Waste Contractor	Operating	Trailer	H	241174	PORTABLE GAS CHROMATOGRAPH TRAILER										
343	Liquid Waste Contractor	Operating	Trailer	H	241175	STORAGE BUILDING										
344	Liquid Waste Contractor	Unknown	Building	H	241176	CHANGE FACILITY										
345	Liquid Waste Contractor	Operating	Trailer	H	241179	E&I TRAILER										
346	Liquid Waste Contractor	Operating	Trailer	H	241180	TOOL CONTROL TRAILER										
347	Liquid Waste Contractor	Unknown	Building	H	241181	HP MONITORING BUILDING										
348	Liquid Waste Contractor	Unknown	Building	H	241182	HP MONITORING BUILDING										
349	Liquid Waste Contractor	Unknown	Building	H	241183	HP MONITORING BUILDING										
350	Liquid Waste Contractor	Unknown	Building	H	241184	HP MONITORING BUILDING										
351	Liquid Waste Contractor	Unknown	Building	H	241185	HP MONITORING BUILDING										
352	Liquid Waste Contractor	Unknown	Trailer	H	241186	STORAGE TRAILER										
353	Liquid Waste Contractor	Unknown	Trailer	H	241187	STORAGE TRAILER										
354	Liquid Waste Contractor	Unknown	Trailer	H	241189	STORAGE TRAILER										
355	Liquid Waste Contractor	Operating	OSF	H	241190	STORAGE PAD										
356	Liquid Waste Contractor	Operating	Trailer	H	241193	CONSTRUCTION SUPPLY SHACK										
357	Liquid Waste Contractor	Operating	Building	H	241194	CONSTRUCTION TOOL ROOM	N	MB04 Steel Braced Frame	314	1996	1	801 Other		Poor		
358	Liquid Waste Contractor	Operating	Trailer	H	241195	RBA ENTRANCE SHACK TO THE HDBB FACILITY										
359	Liquid Waste Contractor	Operating	Trailer	H	241197	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,713	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
360	Liquid Waste Contractor	Operating	Building	H	241205	CHEMICAL STORAGE BUILDING										
361	Liquid Waste Contractor	Operating	Building	H	241206	HANDI-HOUSE										
362	Liquid Waste Contractor	Operating	Building	H	241207	HANDI-HOUSE										
363	Liquid Waste Contractor	Operating	Building	H	241208	HANDI-HOUSE										
364	Liquid Waste Contractor	Operating	Building	H	241209	HANDI-HOUSE										
365	Liquid Waste Contractor	Operating	Building	H	241210	SEA TRAIN STORAGE BUILDING										
366	Liquid Waste Contractor	Operating	Building	H	241211	MAINTENANCE STORAGE SEA BOX										
367	Liquid Waste Contractor	Unknown	Building	H	241212	STORAGE BUILDING										
368	Liquid Waste Contractor	Unknown	Building	H	241213	STORAGE BUILDING										
369	Liquid Waste Contractor	Operating	Building	H	241214	DCS I/O STATION	N	MB05 Steel Light Frame	221	1995	1	400 General Storage		Fail		
370	Liquid Waste Contractor	Unknown	Building	H	241215	STORAGE BUILDING										
371	Liquid Waste Contractor	Unknown	Building	H	241217	CLASS B STORAGE										
372	Liquid Waste Contractor	Unknown	Building	H	241221	CLASS C STORAGE										
373	Liquid Waste Contractor	Unknown	OSF	H	241222	MAINTENANCE CLASS C STORAGE										
374	Liquid Waste Contractor	Unknown	OSF	H	241223	SPRINKLER VALVE HOUSE										
375	Liquid Waste Contractor	Operating	Building	H	241224	RBA ENTRANCE SHACK TO TKS 9-12	N	MB05 Steel Light Frame	234	1995	1	801 Other		Fair		
376	Liquid Waste Contractor	Operating	Trailer	H	241225	MONITORING TRAILER	N	MB05 Steel Light Frame	150	1995		801 Other		Fail		
377	Liquid Waste Contractor	Operating	Trailer	H	241226	PCM-18 MONITOR BUILDING SITE NO. 3	N	MB05 Steel Light Frame	150	1995		642 Communications/Control Centers		Fail		
378	Liquid Waste Contractor	Operating	Building	H	241227	RBA ENTR SHACK TO TANKS 29-32 AND 35-37	N	MB05 Steel Light Frame	156	1990	1	694 Other Service Buildings		Poor		
379	Liquid Waste Contractor	Operating	Building	H	241228	RBA ENTRANCE SHACK TO TANKS 13-16	N	MB05 Steel Light Frame	150	1995	1	694 Other Service Buildings		Fair		
380	Liquid Waste Contractor	Operating	Building	H	241229	RBA ENTRANCE SHACK TO PUMP PIT 5 & 6	N	MB05 Steel Light Frame	150	1995	1	694 Other Service Buildings		Poor		
381	Liquid Waste Contractor	Operating	Trailer	H	241230	RBA ENTRANCE SHACK TO TANKS 38 & 43	N	MB05 Steel Light Frame	165	1995		801 Other		Fail		
382	Liquid Waste Contractor	Operating	Trailer	H	241231	ITP RMA BUILDING	N	MB05 Steel Light Frame	157	1995		801 Other		Poor		
383	Liquid Waste Contractor	Unknown	OSF	H	241232	BREATHING AIR COMPRESSOR										
384	Liquid Waste Contractor	Operating	Trailer	H	241233	MODULAR TRAILER										
385	Liquid Waste Contractor	Unknown	Building	H	241235	STORAGE BUILDING										
386	Liquid Waste Contractor	Operating	OSF	H	241236	ITP LEAK DETECTION BOX										
387	Liquid Waste Contractor	Operating	OSF	H	241237	COLD CHEMICAL AREA										
388	Liquid Waste Contractor	Operating	OSF	H	241238	CARGO SEATRIN										
389	Liquid Waste Contractor	Unknown	OSF	H	241239	ACID STORAGE TANKS										
390	Liquid Waste Contractor	Operating	Trailer	H	241241	EAST HILL RCO OFFICE TRAILER	N	MB05 Steel Light Frame	703	1989		101 Office		Poor		This Modular Office is 25 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC Systems, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
391	Liquid Waste Contractor	Operating	Building	H	241242	EMERG. PURGE VENTILATION EQUIP STRG BLDG	N	MB04 Steel Braced Frame	751	1998	1	400 General Storage		Adequate		
392	Liquid Waste Contractor	Operating	OSF	H	241243	NITROGEN STORAGE FACILITY	N					6008 Other, Service Structures	N			
393	Liquid Waste Contractor	Operating	OSF	H	241245	SHROUDED PROBE CONSTANT AIR MONITOR										
394	Liquid Waste Contractor	Operating	Trailer	H	241246	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,269	1991		101 Office		Fail		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC Systems, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
395	Liquid Waste Contractor	Operating	OSF	H	241247	NITROGEN FACILITY										
396	Liquid Waste Contractor	Operating	Trailer	H	241251	MONITORING TRAILER	N	MB05 Steel Light Frame	394	1993		642 Communications/Control Centers		Fail		
397	Liquid Waste Contractor	Operating	Trailer	H	241252	CF RCO MONITORING SHACK	N	MB05 Steel Light Frame	377	1993		642 Communications/Control Centers		Fail		

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
398	Liquid Waste Contractor	Operating	Trailer	H	241253	MODULAR TRAILER	N	MB05 Steel Light Frame	1,758	1991		601 Maintenance Shops, General		Fail		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC Systems, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
399	Liquid Waste Contractor	Operating	Trailer	H	241254	MAINTENANCE OFFICE	N	MB05 Steel Light Frame	1,329	1992		101 Office		Poor		This Modular Office is 22 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
400	Liquid Waste Contractor	Operating	Trailer	H	241255	MAINTENANCE CHANGE HOUSE										
401	Liquid Waste Contractor	Operating	Trailer	H	241257	PORTABLE CONSTRUCTION LAYOUT OFFICE										
402	Liquid Waste Contractor	Operating	Trailer	H	241258	PERSONNEL MONITOR BUILDING WEST OF 241-100H										
403	Liquid Waste Contractor	Unknown	OSF	H	241263	TK49 HEATED VALVE PANEL ENCLOSURE										
404	Liquid Waste Contractor	Unknown	OSF	H	241268	PORTABLE H&V SKID										
405	Liquid Waste Contractor	Operating	Building	H	241269	GANG VALVE HOUSE										
406	Liquid Waste Contractor	Operating	OSF	H	241270	STORM WATER DIVERSION BOX	N			2000		2009 Catchall	N			
407	Liquid Waste Contractor	Operating	OSF	H	241271	STORM WATER DIVERSION BOX	N			2000		2009 Catchall	N			
408	Liquid Waste Contractor	Operating	Trailer	H	241272	STORAGE BUILDING										
409	Liquid Waste Contractor	Operating	OSF	H	241273	STORAGE SHED FOR PORTABLE BREATHING AIR										
410	Liquid Waste Contractor	Operating	Trailer	H	241275	TANK 43 GAS CHROMOGRAPH TRAILER										
411	Liquid Waste Contractor	Operating	Building	H	241277	RADIOLOGICAL CONTROL STORAGE FACILITY										
412	Liquid Waste Contractor	Operating	OSF	H	241278	MODULAR CAUSTIC SIDE SOLVENT EXTRACTION (CSSX)										
413	Liquid Waste Contractor	Operating	Trailer	H	241279	PORTABLE RESTROOM TRAILER	N	MB05 Steel Light Frame	168	2008		298 Comfort Station/Restrooms		Excellent		Supports the Radioactive Liquid Waste Disposition mission.
414	Liquid Waste Contractor	Reserved	OSF	H	241280	HUMIC ACID STORAGE TANKS AND PUMPS (SKID)										
415	Liquid Waste Contractor	Operating	Building	H	241281	STORAGE FACILITY (QUONSET HUT)										
416	Liquid Waste Contractor	Operating	OSF	H	241282	WASTE CONCENTRATE HOLDING TANK (40,000 GALLON)										
417	Liquid Waste Contractor	Operating	Trailer	H	241283	ETF OFFICE TRAILER	N	MB05 Steel Light Frame	1,751	1989		101 Office		Poor		This Modular Office is 25 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
418	Liquid Waste Contractor	Operating	Trailer	H	241284	HTF OFFICE TRAILER	N	MB05 Steel Light Frame	1,760	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
419	Liquid Waste Contractor	Operating	Trailer	H	241285	HTF OFFICE TRAILER	N	MB05 Steel Light Frame	917	1989		101 Office		Fair		This Modular Office is 25 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
420	Liquid Waste Contractor	Reserved	Building	H	241286	SCIX CHEMICAL STORAGE/RAIN SHELTER (HTF)										
421	Liquid Waste Contractor	Reserved	Building	H	241287	SCIX CHILLER FACILITY										
422	Liquid Waste Contractor	Reserved	Building	H	241288	SCIX ELECTRICAL EQUIPMENT FACILITY										
423	Liquid Waste Contractor	Reserved	Building	H	241289	SCIX DISTRIBUTED CONTROL SYSTEM BUILDING										
424	Liquid Waste Contractor	Operating	Building	H	241290	RADIOLOGICAL CONTROL STORAGE FACILITY										
425	Liquid Waste Contractor	Operating	OSF	H	241909	WASTE STORAGE TANK 09	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
426	Liquid Waste Contractor	Operating	OSF	H	241910	WASTE STORAGE TANK 10	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
427	Liquid Waste Contractor	Operating	OSF	H	241911	WASTE STORAGE TANK 11	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
428	Liquid Waste Contractor	Operating	OSF	H	241912	WASTE STORAGE TANK 12	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
429	Liquid Waste Contractor	Operating	OSF	H	241913	WASTE STORAGE TANK 13	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
430	Liquid Waste Contractor	Operating	OSF	H	241914	WASTE STORAGE TANK 14	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
431	Liquid Waste Contractor	Operating	OSF	H	241915	WASTE STORAGE TANK 15	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
432	Liquid Waste Contractor	Operating	OSF	H	241916	WASTE STORAGE TANK 16	N			1955		4441 Tanks (Hazardous Contaminated)	Y			
433	Liquid Waste Contractor	Operating	OSF	H	241921	WASTE STORAGE TANK 21	N			1963		4441 Tanks (Hazardous Contaminated)	Y			
434	Liquid Waste Contractor	Operating	OSF	H	241922	WASTE STORAGE TANK 22	N			1963		4441 Tanks (Hazardous Contaminated)	Y			
435	Liquid Waste Contractor	Operating	OSF	H	241923	WASTE STORAGE TANK 23	N			1963		4441 Tanks (Hazardous Contaminated)	Y			
436	Liquid Waste Contractor	Operating	OSF	H	241924	WASTE STORAGE TANK 24	N			1963		4441 Tanks (Hazardous Contaminated)	Y			
437	Liquid Waste Contractor	Operating	OSF	H	241929	WASTE STORAGE TANK 29	N			1970		4441 Tanks (Hazardous Contaminated)	Y			
438	Liquid Waste Contractor	Operating	OSF	H	241930	WASTE STORAGE TANK 30	N			1970		4441 Tanks (Hazardous Contaminated)	Y			
439	Liquid Waste Contractor	Operating	OSF	H	241931	WASTE STORAGE TANK 31	N			1970		4441 Tanks (Hazardous Contaminated)	Y			
440	Liquid Waste Contractor	Operating	OSF	H	241932	WASTE STORAGE TANK 32	N			1970		4441 Tanks (Hazardous Contaminated)	Y			
441	Liquid Waste Contractor	Operating	OSF	H	241935	WASTE STORAGE TANK 35	N			1979		4441 Tanks (Hazardous Contaminated)	Y			
442	Liquid Waste Contractor	Operating	OSF	H	241936	WASTE STORAGE TANK 36	N			1979		4441 Tanks (Hazardous Contaminated)	Y			
443	Liquid Waste Contractor	Operating	OSF	H	241937	WASTE STORAGE TANK 37	N			1979		4441 Tanks (Hazardous Contaminated)	Y			
444	Liquid Waste Contractor	Operating	OSF	H	241938	WASTE STORAGE TANK 38	N			1982		4441 Tanks (Hazardous Contaminated)	Y			
445	Liquid Waste Contractor	Operating	OSF	H	241939	WASTE STORAGE TANK 39	N			1982		4441 Tanks (Hazardous Contaminated)	Y			
446	Liquid Waste Contractor	Operating	OSF	H	241940	WASTE STORAGE TANK 40	N			1982		4441 Tanks (Hazardous Contaminated)	Y			
447	Liquid Waste Contractor	Operating	OSF	H	241941	WASTE STORAGE TANK 41	N			1982		4441 Tanks (Hazardous Contaminated)	Y			
448	Liquid Waste Contractor	Operating	OSF	H	241942	WASTE STORAGE TANK 42	N			1982		4441 Tanks (Hazardous Contaminated)	Y			
449	Liquid Waste Contractor	Operating	OSF	H	241943	WASTE STORAGE TANK 43	N			1982		4441 Tanks (Hazardous Contaminated)	Y			
450	Liquid Waste Contractor	Operating	OSF	H	241948	WASTE STORAGE TANK 48	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
451	Liquid Waste Contractor	Operating	OSF	H	241949	WASTE STORAGE TANK 49	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
452	Liquid Waste Contractor	Operating	OSF	H	241950	WASTE STORAGE TANK 50	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
453	Liquid Waste Contractor	Operating	OSF	H	241951	WASTE STORAGE TANK 51	N			1983		4441 Tanks (Hazardous Contaminated)	Y			
454	Liquid Waste Contractor	Operational	OSF	H	242000	TH EVAPORATOR	N			1969		6009 Other, Other Service Structures	N			
455	Liquid Waste Contractor	Operating	Building	H	242001	TH EVAPORATOR CONTROL BUILDING	N	MB05 Steel Light Frame	725	1968	1	599 Other Industrial Facilities		Fair		
456	Liquid Waste Contractor	Operating	OSF	H	242003	CONCENTRATE PUMP TANK PIT										
457	Liquid Waste Contractor	Unknown	Building	H	242007	STORAGE HANDI-HOUSE										
458	Liquid Waste Contractor	Unknown	Building	H	242008	TOOL AND STORAGE HANDI-HOUSE										
459	Liquid Waste Contractor	Operating	Building	H	242009	HEPA FILTER BUILDING FOR 3H EVAPORATOR	N	MB10 Concrete Frame with Infill Shear Walls	1,953	1999	1	599 Other Industrial Facilities		Fail		

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
460	Liquid Waste Contractor	Operating	Building	H	242011	SERVICE BUILDING FOR 3H EVAPORATOR	N	MB04 Steel Braced Frame	3,737	1999	1	599 Other Industrial Facilities		Excellent		
461	Liquid Waste Contractor	Unknown	Building	H	241214	HANDI-HOUSE										
462	Liquid Waste Contractor	Operating	Building	H	242016	2H EVAPORATOR	N	MB09 Concrete Shear Walls	317	1982	1	501 Production/Manufacturing Buildings		Fail		
463	Liquid Waste Contractor	Operational	OSF	H	242018	WASTE CONCENTRATE XFER SYS(CTS) : H-Area	N			1981		6009 Other, Other, Service Structures	Y			
464	Liquid Waste Contractor	Operating	OSF	H	242021	CONCENTRATE TRANSFER SYSTEM (CTS):h&v FOR 242-28H										
465	Liquid Waste Contractor	Unknown	OSF	H	242022	EVAPORATOR #3										
466	Liquid Waste Contractor	Unknown	Building	H	242023	WASTE MGMT BUILDING										
467	Liquid Waste Contractor	Operating	Building	H	242024	CHANGE ROOM AND OFFICE BUILDING	N	MB03 Steel Moment Frame	3,054	1986	1	631 Change Houses		Poor		
468	Liquid Waste Contractor	Operating	Building	H	242025	3H EVAPORATOR CONNECT W/242-11H SERV BLD	N	MB04 Steel Braced Frame	2,226	1996	1	599 Other Industrial Facilities		Poor		
469	Liquid Waste Contractor	Operating	Trailer	H	242026	PHA EQUIPMENT ROOM										
470	Liquid Waste Contractor	Operating	Trailer	H	242029	RBA ENTRANCE BUILDING TO RHLWE										
471	Liquid Waste Contractor	Unknown	OSF	H	243000	PH CONTROL FACILITIES										
472	Liquid Waste Contractor	Operating	Trailer	H	249007	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	2000		101 Office		Fail		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC Systems, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
473	Liquid Waste Contractor	Operating	Trailer	H	249008	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,727	2000		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
474	Liquid Waste Contractor	Operating	Trailer	H	249009	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,726	1991		101 Office		Poor		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
475	Liquid Waste Contractor	Shutdown P	Trailer	H	249010	RESTROOM TRAILER	Y	MB05 Steel Light Frame	105	2001		298 Comfort Station/Restrooms		Not Applicable	02/04/2013	
476	Liquid Waste Contractor	Reserved	OSF	H	252083	SCIX SUBSTATION										
477	Liquid Waste Contractor	Operating	OSF	H	254000	DIESEL GENERATOR AND TANK (FOR 241-49H)										
478	Liquid Waste Contractor	Operating	OSF	H	254001	DIESEL GENERATOR AND TANK	N			1975		5009 Structures, Industrial, Other	N			
479	Liquid Waste Contractor	Operating	OSF	H	254003	DIESEL GENERATOR AND TANK	N			1982		5906 Electric Generators	N			
480	Liquid Waste Contractor	Operating	OSF	H	254004	ITP EMERGENCY DIESEL GENERATOR										
481	Liquid Waste Contractor	Operating	OSF	H	254008	DIESEL GENERATOR (H-AREA RETENTION BASIN	N			1990		5906 Electric Generators	N			
482	Liquid Waste Contractor	Operating	OSF	H	254009	DIESEL GENERATOR	N			1990		5906 Electric Generators	N			
483	Liquid Waste Contractor	Operating	OSF	H	254013	DIESEL GENERATOR AND TANK										
484	Liquid Waste Contractor	Operating	OSF	H	254015	DIESEL GENERATOR AND TANK	N			1993		5906 Electric Generators	N			
485	Liquid Waste Contractor	Operating	OSF	H	254016	DIESEL GENERATOR FOR 241-2H	N			1995		5906 Electric Generators	N			
486	Liquid Waste Contractor	Operating	OSF	H	254074	DIESEL GENERATOR FOR 241074H										
487	Liquid Waste Contractor	Operating	Building	H	260004	MONITORING CHANGE BUILDING	N	MB05 Steel Light Frame	240	1952	1	694 Other Service Buildings		Poor		
488	Liquid Waste Contractor	Operating	OSF	H	263169	HTF CONSOLIDATION YARD										
489	Liquid Waste Contractor	Operating	OSF	H	263171	SPENT CARBON/RESIN STORAGE PAD										
490	Liquid Waste Contractor	Operating	OSF	H	281007	WEIR BOX #3										
491	Liquid Waste Contractor	Operating	OSF	H	281008	STORAGE BASIN, 4 MILLION GALLON, LINED	N			1974		4109 Other, Water Storage	N			
492	Liquid Waste Contractor	Operating	OSF	H	281009	PUMP PIT FOR STORAGE BASIN	N			1990		5008 Pumping Stations	N			
493	Liquid Waste Contractor	Operating	OSF	H	281010	FILTER AND DEIONIZER FACILITY	N			1983		2009 Catchall	N			
494	Liquid Waste Contractor	Operational Standby	OSF	H	284011	COAL STORAGE AREA										
495	Liquid Waste Contractor	Operating	OSF	H	285006	EVAPORATIVE COOLING UNITS	N			1990		2009 Catchall	N			
496	Liquid Waste Contractor	Operating	OSF	H	285007	EVAPORATIVE COOLING UNITS	N			1990		2009 Catchall	N			
497	Liquid Waste Contractor	Operating	OSF	H	285008	EVAPORATIVE COOLING UNITS	N			1990		2009 Catchall	N			
498	Liquid Waste Contractor	Operating	Building	H	299000	MAINTENANCE FACILITY	N	MB04 Steel Braced Frame	8,637	1982	1	601 Maintenance Shops, General		Poor		
499	Liquid Waste Contractor	Operating	OSF	H	299001	DIESEL GENERATOR	N			1982		5906 Electric Generators	N			
500	Liquid Waste Contractor	Operating	Building	H	299002	AIR COMPRESSOR BUILDING	N	MB04 Steel Braced Frame	2,080	1982	1	599 Other Industrial Facilities		Fail		
501	Liquid Waste Contractor	Operating	Building	H	299004	STORAGE/SUPPLY BUILDING	N	MB05 Steel Light Frame	1,431	1986	1	400 General Storage		Poor		
502	Liquid Waste Contractor	Operating	Building	H	299005	CRANE SHELTER	N	MB03 Steel Moment Frame	608	1986	1	400 General Storage		Poor		
503	Liquid Waste Contractor	Operating	OSF	H	299006	TREATMENT BUILDING STACK FOR 241-81H	N			1990		5461 Struc.Industrial,Stack(Gaseous W	N			
504	Liquid Waste Contractor	Operating	OSF	H	299007	CONTROL BUILDING STACK FOR 241-84H	N			1990		5461 Struc.Industrial,Stack(Gaseous W	N			
505	Liquid Waste Contractor	Operating	OSF	H	603000	ROADS (INC. BRIDGES & CULVERTS)	N			1955		1749 Tertiary Roads	N			Asset has deficiencies including reliability issues or capacity that limits performance or capacity of the Radioactive liquid wastes disposition mission, poses added ES&H and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
506	Liquid Waste Contractor	Operating	OSF	H	604000	WALKS	N			1982		1129 Sidewalks	N			Asset has deficiencies including reliability issues or capacity that limits performance or capacity of the Radioactive liquid wastes disposition mission, poses added ES&H and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
507	Liquid Waste Contractor	Operating	OSF	H	605000	FENCES	N			1990		2429 Fencing	N			Asset has deficiencies including reliability issues or capacity that limits performance or capacity of the Radioactive liquid wastes disposition mission, poses added ES&H and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
508	Liquid Waste Contractor	Operating	OSF	H	607024	LIFT STATION	N			1990		5009 Structures, Industrial, Other	N			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ES&H and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operation budgets.
509	Liquid Waste Contractor	Operating	OSF	H	607049	SEPTIC TANK ADJACENT TO 704-56H										
510	Liquid Waste Contractor	Operating	OSF	H	619003	DIESEL FUEL TANK										
511	Liquid Waste Contractor	Operating	OSF	H	619004	DIESEL FUEL TANK										
512	Liquid Waste Contractor	Operating	OSF	H	619005	DIESEL FUEL TANK FOR 254-15H										
513	Liquid Waste Contractor	Operating	OSF	H	619006	DIESEL FUEL TANK FOR 241-2H										
514	Liquid Waste Contractor	Operating	OSF	H	641000	INTERAREA TRANSFER LINE	N			1968		8441 Piping (Hazardous, Contaminated)	Y			

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
515	Liquid Waste Contractor	Operating	OSF	H	681015	LOW POINT DRAIN TANK										
516	Liquid Waste Contractor	Operating	Building	H	681016	LOW POINT DRAIN TANK SUPPORT BLDG										
517	Liquid Waste Contractor	Shutdown P	Trailer	H	704008	ADMINISTRATION TRAILER	Y	MB05 Steel Light Frame	5,040	1980		101 Office		Not Applicable	02/04/2013	
518	Liquid Waste Contractor	Operating	Trailer	H	704023	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	864	1983		101 Office		Fail		This Modular Office is 31 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC Systems, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
519	Liquid Waste Contractor	Operating	Trailer	H	704024	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	702	1983		101 Office		Fail		This Modular Office is 31 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
520	Liquid Waste Contractor	Operating	Trailer	H	704046	RESTROOM TRAILER	N	MB05 Steel Light Frame	167	1983		694 Other Service Buildings		Fail		This Modular Office is 31 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
521	Liquid Waste Contractor	Operating	Building	H	704056	ADMINISTRATION BUILDING	N	MB04 Steel Braced Frame	12,574	1993	1	101 Office		Fair		Asset has deficiencies that limit performance of the Radioactive liquid wastes disposition mission including attracting and maintaining key staff, poses added ES&H and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
522	Liquid Waste Contractor	Operating	Trailer	H	704060	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,919	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
523	Liquid Waste Contractor	Operating	Trailer	H	704061	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	2,873	1994		101 Office		Poor		This Modular Office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
524	Liquid Waste Contractor	Operating	Trailer	H	704062	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	2,837	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
525	Liquid Waste Contractor	Operating	Trailer	H	704065	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	971	1993		101 Office		Poor		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
526	Liquid Waste Contractor	Operating	Trailer	H	704066	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	908	1989		101 Office		Poor		This Modular Office is 25 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC system(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
527	Liquid Waste Contractor	Operating	Trailer	H	704067	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	894	1993		101 Office		Fair		This Modular Office is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
528	Liquid Waste Contractor	Operating	Trailer	H	704068	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	867	2001		101 Office		Poor		This Modular Office is greater than 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
529	Liquid Waste Contractor	Operating	Trailer	H	704082	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,680	2001		101 Office		Poor		This Modular Office is greater 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
530	Liquid Waste Contractor	Operating	Trailer	H	704083	MODULAR TRAILER	N	MB05 Steel Light Frame	636	2001		101 Office		Poor		This Modular Office is greater 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
531	Liquid Waste Contractor	Operating	Trailer	H	704084	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	711	2001		101 Office		Poor		This Modular Office is greater 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
532	Liquid Waste Contractor	Operating	Trailer	H	704088	STORAGE FACILITY										
533	Liquid Waste Contractor	Operating	Trailer	H	704178	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,733	1991		101 Office		Fail		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
534	Liquid Waste Contractor	Operating	Trailer	H	704183	RESTROOM TRAILER										

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross SqFt	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
535	Liquid Waste Contractor	Operating	Trailer	H	704186	RESTROOM TRAILER										
536	Liquid Waste Contractor	Shutdown P	Building	H	706000	ADMINISTRATION BUILDING	Y	MB04 Steel Braced Frame	4,000	1955	1	101 Office		Not Applicable	02/04/2013	
537	Liquid Waste Contractor	Operating	Trailer	H	706002	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,517	1980		101 Office		Poor		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
538	Liquid Waste Contractor	Operating	Building	H	706004	HANDI-HOUSE										
539	Liquid Waste Contractor	Operating	Trailer	H	706006	TRAINING TRAILER	N	MB05 Steel Light Frame	544	1992		400 General Storage		Poor		This Modular Office is 22 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
540	Liquid Waste Contractor	Operating	Trailer	H	706007	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,705	1993		101 Office		Fair		This Modular Office is 21 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
541	Liquid Waste Contractor	Operating	Building	H	707000	ADMINISTRATION BUILDING	N	MB04 Steel Braced Frame	16,464	1990	1	101 Office		Fair		Asset has deficiencies that limit performance of the Radioactive liquid wastes disposition mission including attracting and maintaining key staff, poses added ES&H and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
542	Liquid Waste Contractor	Shutdown P	Trailer	H	707001	MODULAR OFFICE TRAILER	Y	MB05 Steel Light Frame	1,694	1980		101 Office		Not Applicable	02/04/2013	
543	Liquid Waste Contractor	Unknown	OSF	H	707003	STORES DROP POINT										
544	Liquid Waste Contractor	Operating	Building	H	707004	HANDI-HOUSE										
545	Liquid Waste Contractor	Unknown	Building	H	707008	HANDI-HOUSE										
546	Liquid Waste Contractor	Operating	OSF	H	707010	STORES DROP POINT PAD										
547	Liquid Waste Contractor	Operating	Trailer	H	740037	MODULAR OFFICE TRAILER										
548	Liquid Waste Contractor	Operating	Trailer	H	740038	MODULAR TRAILER										
549	Liquid Waste Contractor	Operating	Trailer	H	740039	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	701	1983		101 Office		Fair		This Modular Office is greater than 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, roof, and electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
550	Liquid Waste Contractor	Operating	Building	H	772000	PRE-FABRICATED BUILDING	N	MB04 Steel Braced Frame	4,800	1997	1	400 General Storage		Excellent		
551	Liquid Waste Contractor	Operating	OSF	H	801001	DIVERSION BOX										
552	Liquid Waste Contractor	Operating	OSF	H	805001	DIVERSION BOX										
553	Liquid Waste Contractor	Operating	OSF	H	805003	JUNCTION BOX										
554	Liquid Waste Contractor	Operating	OSF	H	907000	STORM SEWERS	N			1974		2009 Catchall	Y			Asset has deficiencies including reliability issues or capacity that limits performance or capacity of the Radioactive liquid wastes disposition mission, poses added ES&H and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
555	Liquid Waste Contractor	Operating	OSF	H	907001	DIVERSION BOX	N			1974		2009 Catchall	N			
556	Liquid Waste Contractor	Shutdown P	OSF	H	907002	STORM WATER MONITORING STATION	N			1988		2009 Catchall	N			
557	Liquid Waste Contractor	Shutdown P	OSF	H	907003	STORM WATER MONITORING STATION	N			1988		2009 Catchall	N			
558	Liquid Waste Contractor	Shutdown P	OSF	H	907004	STORM WATER MONITORING STATION	N			1988		2009 Catchall	N			
559	Liquid Waste Contractor	Shutdown P	OSF	H	907005	STORM WATER MONITORING STATION	N			1988		2009 Catchall	N			
560	Liquid Waste Contractor	Operating	OSF	H	907006	STORM WATER MONITOR	N			1988		6009 Other, Other.Service Structures	N			
561	Liquid Waste Contractor	Shutdown P	OSF	H	927007	STORM WATER MONITOR	N			1988		6009 Other, Other.Service Structures	N			
562	Liquid Waste Contractor	Reserved	Building	J	221000	SWPF PROCESSING FACILITY										
563	Liquid Waste Contractor	Reserved	Building	J	221003	SWPF ALPHA FINISHING FACILITY										
564	Liquid Waste Contractor	Reserved	Building	J	221004	SWPF COMPRESSOR BUILDING										
565	Liquid Waste Contractor	Reserved	Building	J	660000	SWPF SERVICE BUILDING										
566	Liquid Waste Contractor	Reserved	Building	J	701000	SWPF CONTROL PORTAL BUILDING										
567	Liquid Waste Contractor	Reserved	Building	J	704000	SWPF ADMINISTRATION BUILDING										
568	SWPF Contractor	Operating	Trailer	J	705015	SWPF OFFICE TRAILER (CONSTRUCTION)										
569	SWPF Contractor	Operating	Trailer	J	705016	SWPF OFFICE TRAILER (CONSTRUCTION)	N	MB05 Steel Light Frame	1,744	1991		101 Office		Fair		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s) and the electrical system are required to restore this facility to adequate condition.
570	SWPF Contractor	Operating	Trailer	J	705017	SWPF OFFICE TRAILER (CONSTRUCTION)	N	MB05 Steel Light Frame	1,744	1991		101 Office		Fair		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s) and the electrical system are required to restore this facility to adequate condition.
571	SWPF Contractor	Operating	Trailer	J	705022	SWPF OFFICE TRAILER (CONSTRUCTION)	N	MB05 Steel Light Frame	1,347	1995		101 Office		Poor		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
572	SWPF Contractor	Operating	Trailer	J	705023	SWPF OFFICE TRAILER (CONSTRUCTION)	N	MB05 Steel Light Frame	1,909	1995		101 Office		Poor		This Modular Office is 17 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
573	SWPF Contractor	Operating	Trailer	J	705024	SWPF OFFICE TRAILER (CONSTRUCTION)	N	MB05 Steel Light Frame	1,909	1995		101 Office		Poor		This Modular Office is 19 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
574	SWPF Contractor	Operating	OSF	J	752002	ADMINISTRATION BUILDING TRANSFORMER	N			2008		8988 Power Transformers	N			
575	Liquid Waste Contractor	Operating	OSF	S	51000	SAFETY SIGN										
576	Liquid Waste Contractor	Operating	OSF	S	51001	SAFETY SIGN										
577	Liquid Waste Contractor	Operating	OSF	S	52000	FLAG POLE										
578	Liquid Waste Contractor	Operating	OSF	S	52001	FLAG POLE										
579	Liquid Waste Contractor	Operating	Building	S	54002	RAIN SHELTER, ENTRACE TO S-AREA										
580	Liquid Waste Contractor	Operating	Trailer	S	54003	RAIN SHELTER, SE CORNER OF 707-505										
581	Liquid Waste Contractor	Operating	Trailer	S	54004	RAIN SHELTER										
582	Liquid Waste Contractor	Operating	Trailer	S	54005	RAIN SHELTER, WEST OF 714-S										
583	Liquid Waste Contractor	Operating	Trailer	S	54006	RAIN SHELTER										
584	Liquid Waste Contractor	Operating	Building	S	210000	SERVICE BUILDING	N	MB08 Concrete Moment Frame	61,012	1983	1	501 Production/Manufacturing Buildings		Poor		
585	Liquid Waste Contractor	Operating	Building	S	221000	VITRIFICATION BUILDING	N	MB09 Concrete Shear Walls	242,467	1995	5	593 Nuclear Waste Processing And/Or H		Poor		
586	Liquid Waste Contractor	Operating	OSF	S	221001	TORNADO PROTECTION PAD										
587	Liquid Waste Contractor	Reserved	Building	S	221002	DRY FRIT CONVEYING FACILITY										
588	Liquid Waste Contractor	Unknown	OSF	S	224000	SALT CELL BENZENE ABATEMENT										
589	Liquid Waste Contractor	Reserved	Trailer	S	235000	DWPF LABORATORY FACILITY										
590	Liquid Waste Contractor	Operating	Building	S	250000	GLASS WASTE STORAGE BLDG #1 (GWSB #1)	N	MB04 Steel Braced Frame	48,197	1986	1	593 Nuclear Waste Processing And/Or H		Fair		
591	Liquid Waste Contractor	Operating	Building	S	250001	SPARE EQUIPMENT STORAGE BUILDING	N	MB04 Steel Braced Frame	3,030	1989	1	400 General Storage		Adequate		
592	Liquid Waste Contractor	Shutdown P	Building	S	250002	PORTABLE STORAGE BUILDING	Y	MB04 Steel Braced Frame	1,999	1992	1	400 General Storage		Not Applicable	11/07/2011	
593	Liquid Waste Contractor	Operating	OSF	S	250004	CONCRETE PAD										
594	Liquid Waste Contractor	Operating	OSF	S	250005	CONCRETE PAD										
595	Liquid Waste Contractor	Operating	Building	S	251000	GLASS WASTE STORAGE BUILDING #2 (GWSB #2)	N	MB07 Steel Frame with Infill Shear Walls	43,360	2005	1	593 Nuclear Waste Processing And/Or H		Excellent		
596	Liquid Waste Contractor	Reserved	Building	S	252000	GLASS WASTE STORAGE CAPABILITY (GWSB#3)		future facility						In AAIM		
597	Liquid Waste Contractor	Reserved	Building	S	253000	CANISTER SHIPPING FACILITY (CSF)		future facility						In AAIM		
598	Liquid Waste Contractor	Operating	Building	S	260000	FAILED EQUIPMT STRG VAULT/CRANE CTRL RM	N	MB09 Concrete Shear Walls	575	1986	1	694 Other Service Buildings		Fail		
599	Liquid Waste Contractor	Operating	OSF	S	260002	FAILED EQUIPMENT STORAGE VAULT #1										
600	Liquid Waste Contractor	Operating	OSF	S	260004	FAILED EQUIPMENT STORAGE VAULT #2										
601	Liquid Waste Contractor	Unknown	OSF	S	263012	CSM 12-2 LABOR STORAGE (#4548)										
602	Liquid Waste Contractor	Operating	Building	S	263096	EQUIPMENT BUILDING	N	MB05 Steel Light Frame	103	2008	1	400 General Storage		Adequate		
603	Liquid Waste Contractor	Unknown	Trailer	S	263149	STORAGE TRAILER 11										
604	Liquid Waste Contractor	Unknown	OSF	S	263152	LAUNDRY DROP POINT										
605	Liquid Waste Contractor	Unknown	Building	S	263158	STORAGE BUILDING #4032										
606	Liquid Waste Contractor	Operating	OSF	S	291000	VENT EXHAUST STACK	N			1999		2009 Catchall	N			
607	Liquid Waste Contractor	Operating	Building	S	292000	FAN HOUSE	N	MB08 Concrete Moment Frame	13,093	1995	1	801 Other		Fail		
608	Liquid Waste Contractor	Operating	OSF	S	294000	SAND FILTER	N			1995		2009 Catchall	N			
609	Liquid Waste Contractor	Operating	Building	S	422000	COLD FEED STORAGE	N	MB04 Steel Braced Frame	4,611	1995	1	400 General Storage		Good		
610	Liquid Waste Contractor	Unknown	OSF	S	442001	FORMIC/CAUSTIC ACID UNLOAD										
611	Liquid Waste Contractor	Operating	Building	S	422002	BULK FRIT FACILITY	N	MB05 Steel Light Frame	4,734	1995	1	400 General Storage		Poor		
612	Liquid Waste Contractor	Operating	OSF	S	422003	REG DRAINS COLLECT TANK										
613	Liquid Waste Contractor	Operating	OSF	S	422004	CLEAN CONDENSATE TANK										
614	Liquid Waste Contractor	Operating	OSF	S	422005	DEIONIZER STATION										
615	Liquid Waste Contractor	Operating	OSF	S	422006	SOUTHWET SI STATION										
616	Liquid Waste Contractor	Operational	OSF	S	430000	ORGANIC WASTE STORAGE FACILITY	N			1995		4009 Other, Storage	N			
617	Liquid Waste Contractor	Operational	OSF	S	430001	REF ORGANIC RECOVERY UNIT	N			1995		2009 Catchall	N			
618	Liquid Waste Contractor	Operating	OSF	S	430002	BACK UP NITROGEN SYSTEM MANIFOLD										
619	Liquid Waste Contractor	Operating	OSF	S	430003	OFF GAS & OPERATING STATION										
620	Liquid Waste Contractor	Operating	OSF	S	430004	FOAM HOUSE BUILDING										
621	Liquid Waste Contractor	Reserved	OSF	S	503000	ELECTRICAL DISTRIBUTION LINES										
622	Liquid Waste Contractor	Reserved	OSF	S	510000	INTERNAL SECURITY COMMUNICATION SYSTEM										
623	Liquid Waste Contractor	Operating	Building	S	511000	LOW POINT PUMP PIT	N	MB05 Steel Light Frame	7,220	1995	1	599 Other Industrial Facilities		Poor		
624	Liquid Waste Contractor	Operating	Building	S	511001	LOW POINT PUMP PIT HVAC	N	MB05 Steel Light Frame	2,290	1987	1	599 Other Industrial Facilities		Poor		
625	Liquid Waste Contractor	Operating	Building	S	511002	INSTRUMENT SHELTER BUILDING	N	MB05 Steel Light Frame	347	1999	1	599 Other Industrial Facilities		Adequate		
626	Liquid Waste Contractor	Operating	Building	S	511003	TANKER UNLOADING FACILITY										
627	Liquid Waste Contractor	Operating	Trailer	S	511005	PORTABLE BUILDING										
628	Liquid Waste Contractor	Operating	Building	S	512000	ACTINIDE REMOVAL PROCESS FACILITY	N	MB06 Steel Frame with Concrete Shear Walls	10,782	1997	1	501 Production/Manufacturing Buildings		Fair		
629	Liquid Waste Contractor	Operating	Building	S	512001	LATEWASH FACILITY HVAC BUILDING	N	MB06 Steel Frame with Concrete Shear Walls	2,187	1992	1	599 Other Industrial Facilities		Fair		
630	Liquid Waste Contractor	Operating	Building	S	512002	INSTRUMENT SHELTER										
631	Liquid Waste Contractor	Operating	OSF	S	512004	PRIMARY NITROGEN STORAGE										
632	Liquid Waste Contractor	Operating	OSF	S	512005	LATEWASH FACILITY (PRIMARY)	N			1997		4331 Tanks (Process Gas)	N			
633	Liquid Waste Contractor	Operating	Building	S	512006	LATEWASH FACILITY	N	MB05 Steel Light Frame	1,031	1997	1	791 Laboratories, General (Non-Nuclear)		Fair		
634	Liquid Waste Contractor	Operating	OSF	S	512007	LATEWASH COLD CHEMICAL FEED SHELTER	N			1999		4009 Other, Storage	N			
635	Liquid Waste Contractor	Operating	Trailer	S	512014	SELF CONTAINED RESTROOM TRAILER										
636	Liquid Waste Contractor	Operating	OSF	S	550000	INTER AREA TRANS LINES	N			1995		8441 Piping (Hazardous/Contaminated)	Y			
637	Liquid Waste Contractor	Operating	OSF	S	601000	STANDARD GUAGE TRACK - S AREA	N			1989		1429 Primary Tracks	N			
638	Liquid Waste Contractor	Unknown	OSF	S	603000	ROADS (INC. BRIDGES & CULVERTS)										
639	Liquid Waste Contractor	Unknown	OSF	S	604000	WALKS										
640	Liquid Waste Contractor	Unknown	OSF	S	605000	FENCES										
641	Liquid Waste Contractor	Operating	OSF	S	607000	S-AREA PUMP STATION FOR WWATER TREAT FAC	N			1995		5549 Plants (Sewer, Tertiary Treatment)	N			
642	Liquid Waste Contractor	Operating	OSF	S	607016	SEWAGE LIFT STATION	N			1994		8561 Lift Stations (Sewage)	N			Asset is fully capable of performing its current radioactive liquid wastes disposition mission, meets all ESH and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operating budgets.
643	Liquid Waste Contractor	Operating	OSF	S	613000	PARKING AREA										
644	Liquid Waste Contractor	Unknown	OSF	S	697000	SITE WORK AND GENERAL GRADING										
645	Liquid Waste Contractor	Operating	OSF	S	698000	LANDSCAPING AND EROSION CONTROL										
646	Liquid Waste Contractor	Unknown	OSF	S	699000	EX MACHINERY (ACCOUNTING PURPOSES ONLY)										
647	Liquid Waste Contractor	Unknown	Building	S	701001	STORAGE BUILDING										
648	Liquid Waste Contractor	Operating	Building	S	704000	OPERATIONS BUILDING	N	MB04 Steel Braced Frame	25,927	1983	1	101 Office		Fair		

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
649	Liquid Waste Contractor	Operating	Trailer	S	704015	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,117	2000		101 Office		Fail		This Modular Office is 17 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
650	Liquid Waste Contractor	Operating	Trailer	S	704016	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,296	1977		101 Office		Poor		This Modular Office is 37 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
651	Liquid Waste Contractor	Unknown	Trailer	S	704021	MODULAR OFFICE TRAILER										
652	Liquid Waste Contractor	Unknown	Trailer	S	704022	STORAGE BUILDING										
653	Liquid Waste Contractor	Unknown	Building	S	704023	STORAGE BUILDING										
654	Liquid Waste Contractor	Operating	Trailer	S	704024	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,736	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
655	Liquid Waste Contractor	Operating	Trailer	S	704025	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,731	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
656	Liquid Waste Contractor	Operating	Trailer	S	704026	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,731	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
657	Liquid Waste Contractor	Operating	Trailer	S	704027	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,731	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
658	Liquid Waste Contractor	Operating	Trailer	S	704028	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,731	1988		101 Office		Poor		This Modular Office is 28 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
659	Liquid Waste Contractor	Operating	Trailer	S	704029	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,731	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
660	Liquid Waste Contractor	Operating	Trailer	S	704030	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,731	1988		101 Office		Poor		This Modular Office is 26 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
661	Liquid Waste Contractor	Unknown	Trailer	S	704036	MODULAR OFFICE TRAILER										
662	Liquid Waste Contractor	Unknown	Trailer	S	704038	MODULAR OFFICE TRAILER										
663	Liquid Waste Contractor	Unknown	OSF	S	704048	STORAGE SHED										
664	Liquid Waste Contractor	Operating	Trailer	S	704049	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	5,369	1992		101 Office		Poor		This Modular Office is 20+ years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/equipment/facilities.
665	Liquid Waste Contractor	Operating	Trailer	S	704050	MODULAR TRAINING TRAILER	N	MB05 Steel Light Frame	1,120	2001		101 Office		Poor		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/equipment/facilities.
666	Liquid Waste Contractor	Operating	Trailer	S	704051	MODULAR TRAINING TRAILER	N	MB05 Steel Light Frame	1,120	2001		101 Office		Poor		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/equipment/facilities.
667	Liquid Waste Contractor	Operating	Trailer	S	704052	MODULAR TRAINING TRAILER	N	MB05 Steel Light Frame	1,120	2001		101 Office		Poor		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/equipment/facilities.
668	Liquid Waste Contractor	Unknown	Building	S	704054	STORAGE BUILDING										

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
669	Liquid Waste Contractor	Operating	Trailer	S	704060	MODULAR OFFICE TRAILER										
670	Liquid Waste Contractor	Operating	Trailer	S	704061	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,704	2000		101 Office		Fail		This Modular Office is 14 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
671	Liquid Waste Contractor	Operating	Trailer	S	704062	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,120	2000		400 General Storage		Fair		This Modular Office is 14 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
672	Liquid Waste Contractor	Operating	Trailer	S	704063	MODULAR STORAGE TRAILER	N	MB05 Steel Light Frame	1,120	2000		400 General Storage		Fair		This Modular Office is 14 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
673	Liquid Waste Contractor	Operating	Trailer	S	704064	MODULAR SHOP TRAILER	N	MB05 Steel Light Frame	917	2001		601 Maintenance Shops, General		Fail		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated.
674	Liquid Waste Contractor	Operating	Trailer	S	704065	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	965	2001		101 Office		Poor		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
675	Liquid Waste Contractor	Operating	Trailer	S	704066	MODULAR OFFICE TRAILER										
676	Liquid Waste Contractor	Operating	Trailer	S	704067	MODULAR OFFICE TRAILER										
677	Liquid Waste Contractor	Operating	Trailer	S	704067	MODULAR OFFICE TRAILER										
678	Liquid Waste Contractor	Per SSSD -	Building	S	704068	CSM14-2 OFFICE (#4798)										
679	Liquid Waste Contractor	Unknown	Building	S	704069	CSM16 OFFICE (#4790)										
680	Liquid Waste Contractor	Operating	Building	S	704071	TC-S1 ADMINISTRATION BUILDING	N	MB04 Steel Braced Frame	21,113	1983	1	101 Office		Fair		Asset has deficiencies that limit performance of the Radioactive liquid wastes disposition mission including attracting and maintaining key staff, poses added ESH and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
681	Liquid Waste Contractor	Operating	Building	S	704072	TC-S2 RECEIVING STORES	N	MB04 Steel Braced Frame	19,900	1983	1	694 Other Service Buildings		Poor		
682	Liquid Waste Contractor	Unknown	Trailer	S	704081	MODULAR OFFICE TRAILER										
683	Liquid Waste Contractor	Unknown	OSF	S	704089	MOBILE STRUCTURE										
684	Liquid Waste Contractor	Operating	Building	S	704096	HANDI-HOUSE										
685	Liquid Waste Contractor	Unknown	Trailer	S	704105	MODULAR OFFICE TRAILER										
686	Liquid Waste Contractor	Operating	Building	S	704106	MERCURY STORAGE HOUSE	N	MB05 Steel Light Frame	323	1997	1	694 Other Service Buildings		Good		
687	Liquid Waste Contractor	Unknown	Trailer	S	704107	MODULAR OFFICE TRAILER										
688	Liquid Waste Contractor	Unknown	Trailer	S	704108	MODULAR OFFICE TRAILER										
689	Liquid Waste Contractor	Unknown	Trailer	S	704109	MODULAR OFFICE TRAILER										
690	Liquid Waste Contractor	Unknown	Trailer	S	704110	MODULAR OFFICE TRAILER										
691	Liquid Waste Contractor	Unknown	Building	S	704113	RESTROOM FACILITY										
692	Liquid Waste Contractor	Unknown	Trailer	S	704114	MODULAR OFFICE TRAILER										
693	Liquid Waste Contractor	Operating	Trailer	S	704115	MODULAR LABORATORY TRAILER										
694	Liquid Waste Contractor	Operating	Trailer	S	704116	MODULAR LABORATORY TRAILER										
695	Liquid Waste Contractor	Operating	Building	S	704120	E & I SHOP	N	MB05 Steel Light Frame	804	1993	1	601 Maintenance Shops, General		Good		Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ESH and/or security requirements, meets stated DOE objectives or goals, and has only minor deficiencies that can be corrected with normal operating budgets.
696	Liquid Waste Contractor	Operating	Trailer	S	704121	RESTROOM TRAILER	N	MB05 Steel Light Frame	355	2008		298 Comfort Station/Restrooms		Fair		This Modular Office is 6 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior roof and the interior finishes are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
697	Liquid Waste Contractor	Operating	Trailer	S	704122	EXECUTIVE OFFICE TRAILER	N	MB05 Steel Light Frame	1,913	2015		101 Office		Excellent		
698	Liquid Waste Contractor	Operating	Trailer	S	704123	CONFERENCE / BREAKROOM TRAILER	N	MB05 Steel Light Frame	1,913	2015		101 Office		Excellent		
699	Liquid Waste Contractor	Operating	Trailer	S	704124	ENGINEERING OFFICE TRAILER	N	MB05 Steel Light Frame	1,913	2015		101 Office		Excellent		
700	Liquid Waste Contractor	Operating	Trailer	S	704125	ENGINEERING OFFICE TRAILER	N	MB05 Steel Light Frame	1,913	2015		101 Office		Excellent		
701	Liquid Waste Contractor	Operating	Trailer	S	704126	ENGINEERING OFFICE TRAILER	N	MB05 Steel Light Frame	1,913	2015		101 Office		Excellent		
702	Liquid Waste Contractor	Operating	Trailer	S	704127	ENGINEERING OFFICE TRAILER	N	MB05 Steel Light Frame	1,913	2015		101 Office		Excellent		
703	Liquid Waste Contractor	Unknown	Building	S	705000	ADMINISTRATION OFFICE FACILITY										
704	Liquid Waste Contractor	Operating	Building	S	706000	DISTRIBUTIVE CONTROL STAGING BUILDING	N	MB04 Steel Braced Frame	8,754	1988	1	401 Programmatic General Storage		Fair		
705	Liquid Waste Contractor	Operating	Building	S	707000	MAINTENANCE SHOP	N	MB04 Steel Braced Frame	4,400	1989	1	601 Maintenance Shops, General		Adequate		
706	Liquid Waste Contractor	Unknown	Building	S	707003	OFFICE BUILDING										
707	Liquid Waste Contractor	Unknown	Building	S	707004	OFFICE BUILDING										
708	Liquid Waste Contractor	Unknown	OSF	S	710000	PLYWOOD SHED										
709	Liquid Waste Contractor	Operating	Building	S	714000	SPARE PARTS BUILDING	N	MB05 Steel Light Frame	10,680	1990	1	401 Programmatic General Storage		Poor		
710	Liquid Waste Contractor	Operating	Trailer	S	714001	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,041	2001		101 Office		Fair		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
711	Liquid Waste Contractor	Operating	Trailer	S	714002	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	955	2001		101 Office		Fair		This Modular Office is 13 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior and the HVAC System(s) are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
712	Liquid Waste Contractor	Operating	Trailer	S	714003	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	955	1991		101 Office		Fair		This Modular Office is 24 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
713	Liquid Waste Contractor	Operating	Trailer	S	714004	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	955	1991		101 Office		Fail		This Modular Office is 23 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
714	Liquid Waste Contractor	Operating	Trailer	S	714005	MODULAR SHOP TRAILER	N	MB05 Steel Light Frame	955	2001		791 Laboratories, General (Non-Nuclear)		Fail		
715	Liquid Waste Contractor	Operating	Trailer	S	714006	MODULAR LABORATORY TRAILER	N	MB05 Steel Light Frame	955	2001		615 Electrical/Motor Repair Shops		Fail		
716	Liquid Waste Contractor	Operating	Building	S	717000	MAINTENANCE SHOP	N	MB04 Steel Braced Frame	1,839	1986	1	101 Office		Poor		
717	Liquid Waste Contractor	Unknown	Building	S	717002	STORAGE BUILDING										
718	Liquid Waste Contractor	Unknown	Building	S	717004	STORAGE BUILDING										
719	Liquid Waste Contractor	Unknown	Building	S	717005	STORAGE BUILDING										
720	Liquid Waste Contractor	Unknown	Building	S	717006	STORAGE BUILDING										
721	Liquid Waste Contractor	Unknown	Building	S	717007	LUNCHROOM FACILITY										
722	Liquid Waste Contractor	Unknown	OSF	S	717008	WASTE PAD										
723	Liquid Waste Contractor	Operating	Building	S	717011	TC-S3 PIPE SHOP	N	MB04 Steel Braced Frame	9,590	1983	1	604 Pipe Fitting And Plumbing Shop		Good		
724	Liquid Waste Contractor	Operating	Building	S	717012	TC-S5 ELECTRICAL SHOP	N	MB04 Steel Braced Frame	15,206	1983	1	615 Electrical/Motor Repair Shops		Good		
725	Liquid Waste Contractor	Operating	OSF	S	718000	DWPF JUMPER STORAGE PAD										
726	Liquid Waste Contractor	Reserved	Building	S	722000	DWPF TRAINING FACILITY										
727	SWPF Contractor	Operating	Building	S	763000	SWPF WAREHOUSE	N	MB05 Steel Light Frame	15,000	2009	1	101 Office		Excellent		
728	Liquid Waste Contractor	Operating	Building	S	763001	STORAGE FACILITY (DWPF E&I MAINTENANCE)										
729	Liquid Waste Contractor	Operating	Building	S	763002	CONSTRUCTION MATERIAL STORAGE FACILITY #1										
730	Liquid Waste Contractor	Operating	Building	S	763003	CONSTRUCTION MATERIAL STORAGE FACILITY #2										
731	Liquid Waste Contractor	Unknown	OSF	S	802000	OUTSIDE OVERHEAD PIPE - STEAM										
732	Liquid Waste Contractor	Unknown	OSF	S	803000	OUTSIDE UNDERGROUND DOMESTIC WATER PIPE										
733	Liquid Waste Contractor	Unknown	OSF	S	821000	STORM SEWERS										
734	Liquid Waste Contractor	Operating	Building	S	831000	SWIRL CELL FACILITY	N	MB05 Steel Light Frame	226	1995	1	801 Other		Poor		
735	Liquid Waste Contractor	Operating	OSF	S	831003	SWIRL CELL FACILITY RETENTION ANK										
736	Liquid Waste Contractor	Operating	OSF	S	831004	SEWAGE LIFT STATION INFLUENT										
737	Liquid Waste Contractor	Operating	OSF	S	831005	SEWAGE LIFT STATION EFFLUENT	N			1987		8561 Lift Stations (Sewage)	N			Asset has deficiencies including reliability issues or capacity that limits performance or capacity of the Radioactive liquid wastes disposition mission, poses added ES&H and/or security risk, or affects DOE requirements. Asset requires refurbishment to bring to adequate condition.
738	Liquid Waste Contractor	Operating	Building	S	831010	CHEMICAL STORAGE BUILDING	N	MB05 Steel Light Frame	460	1995	1	400 General Storage		Poor		
739	Liquid Waste Contractor	Operating	OSF	S	903000	SANITARY SEWERS	N			1990		8529 Piping, Gravity (Sewage)	Y			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ES&H and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operating budgets.
740	Liquid Waste Contractor	Operating	OSF	S	905000	DIESEL FUEL TANK AND GENERATOR										
741	Liquid Waste Contractor	Operating	OSF	S	905001	WATER WELL #1	N			1995		5159 Other Industrial, Water Wells	N			
742	Liquid Waste Contractor	Operating	OSF	S	905002	WATER WELL #2	N			1995		5159 Other Industrial, Water Wells	N			
743	Liquid Waste Contractor	Operating	OSF	S	907000	STORM SEWERS	N			1990		8629 Piping, Gravity (Stormwater)	Y			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ES&H and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operating budgets.
744	Liquid Waste Contractor	Operating	Building	S	951000	PRIMARY SUBSTATION	N	MB05 Steel Light Frame	2,123	1995	1	694 Other Service Buildings		Fail		
745	Liquid Waste Contractor	Operating	OSF	S	951001	SWITCHING CUBICAL A413 FOR Z-AREA	N			1985		8979 Substations	N			
746	Liquid Waste Contractor	Operating	OSF	S	952000	TRANSFORMER FOR 706-S & 717-S	N			1986		8988 Power Transformers	N			
747	Liquid Waste Contractor	Operating	OSF	S	952001	TRANSFORMER	N			1986		8988 Power Transformers	N			
748	Liquid Waste Contractor	Operating	OSF	S	952005	TRANSFORMER 7	N			1983		8989 Distribution Transformers	N			
749	Liquid Waste Contractor	Shutdown P	OSF	S	952006	TRANSFORMER 8	N			1992		8989 Distribution Transformers	N			
750	Liquid Waste Contractor	Operating	OSF	S	952007	TRANSFORMER 952-7S	N			2001		8989 Distribution Transformers	N			
751	Liquid Waste Contractor	Operating	OSF	S	952008	TRANSFORMER FOR 512-13S										
752	Liquid Waste Contractor	Operating	OSF	S	953000	ELECTRICAL DISTRIBUTION LINES	N			1988		8939 Electrical Cables, Secondary	Y			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ES&H and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operating budgets.
753	Liquid Waste Contractor	Operating	Building	S	956000	FUEL OIL STORAGE	N	MB16 Other-Desc: brief in Notes field/supp doc	1,055	1995	1	400 General Storage		Fail		
754	Liquid Waste Contractor	Operating	OSF	S	956001	STORAGE PAD										
755	Liquid Waste Contractor	Operating	OSF	S	956002	STORAGE PAD										
756	Liquid Waste Contractor	Operating	OSF	S	956003	STORAGE PAD										
757	Liquid Waste Contractor	Operating	OSF	S	956004	STORAGE PAD										
758	Liquid Waste Contractor	Operating	OSF	S	956005	MOCK-UP SHOP SLAB										
759	Liquid Waste Contractor	Operating	OSF	S	956006	STORAGE PAD										
760	Liquid Waste Contractor	Operating	OSF	S	956007	STORAGE PAD										
761	Liquid Waste Contractor	Operating	Building	S	956010	FRIT TOTE BIN STORAGE FACILITY	N	MB05 Steel Light Frame	1,800	2005	1	400 General Storage		Excellent		
762	Liquid Waste Contractor	Operating	Building	S	956011	LUBE OIL STORAGE FACILITY #1	N	MB04 Steel Braced Frame	276	2005	1	410 Hazardous/Flammable Storage		Poor		
763	Liquid Waste Contractor	Operating	Building	S	956012	LUBE OIL STORAGE FACILITY #2	N	MB03 Steel Moment Frame	276	2005	1	410 Hazardous/Flammable Storage		Poor		
764	Liquid Waste Contractor	Operating	Building	S	980000	WATER & CHEMICAL WASTE TREATMENT FAC	N	MB04 Steel Braced Frame	9,816	1995	1	694 Other Service Buildings		Poor		
765	Liquid Waste Contractor	Operating	OSF	S	980001	NEUTRALIZED FIRE WATER TANK	N			1996		4009 Other, Storage	N			
766	Liquid Waste Contractor	Operating	OSF	S	980002	DOMESTIC WATER TANK	N			1999		4009 Other, Storage	N			

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
767	Liquid Waste Contractor	Unknown	OSF	S	980003	DOMESTIC WATER TANK										
768	Liquid Waste Contractor	Operating	OSF	S	981000	COOLING TOWER	N			1995		5769 Towers (Chill Water)	N			
769	Liquid Waste Contractor	Operating	Building	S	981001	CHEMICAL TREATMENT FACILITY	N	MB05 Steel Light Frame	671	1995	1	801 Other		Fair		
770	Liquid Waste Contractor	Operating	OSF	T	678005	SEMIWORKS WASTE TANK MOCK-UP	N			2000		6009 Other, Other,Service Structures	N			
771	Liquid Waste Contractor	Operating	Building	T	678006	WASTE TANK MOCK-UP RETENTION BASIN	N	MB05 Steel Light Frame	134	1998	1	694 Other Service Buildings		Fair		
772	Liquid Waste Contractor	Operating	Trailer	T	678007	STORAGE BUILDING										
773	Liquid Waste Contractor	Operating	Trailer	T	678008	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	880	1987		101 Office		Fail		This Modular Office is 27 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC, and the electrical system are required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission.
774	Liquid Waste Contractor	Operating	OSF	Z	52000	FLAG POLE										
775	Liquid Waste Contractor	Operating	OSF	Z	201000	SSHT/FWRT PITS & PAD	N			1995		6009 Other, Other,Service Structures	N			
776	Liquid Waste Contractor	Reserved	OSF	Z	201001	SSRT ENCLOSURE FACILITY										
777	Liquid Waste Contractor	Operating	OSF	Z	205000	FLY ASH BASIN										
778	Liquid Waste Contractor	Operating	OSF	Z	205001	FLY ASH SILO #1	N			1992		4331 Tanks (Process Gas)	N			
779	Liquid Waste Contractor	Operating	OSF	Z	205002	FLY ASH SILO #2	N			1992		4331 Tanks (Process Gas)	N			
780	Liquid Waste Contractor	Operating	OSF	Z	205003	FLY ASH SILO #3	N			1999		4331 Tanks (Process Gas)	N			
781	Liquid Waste Contractor	Operating	OSF	Z	205004	CEMENT SILO	N			1999		4331 Tanks (Process Gas)	N			
782	Liquid Waste Contractor	Operating	OSF	Z	205006	ADMIXTURE TANK	N			1992		4009 Other, Storage	N			
783	Liquid Waste Contractor	Operating	Building	Z	205007	UNLOADING SHED	N	MB05 Steel Light Frame	1,209	1999	0	450 Shed Storage		Fair		
784	Liquid Waste Contractor	Operating	Building	Z	205008	UNLOADING OFFICE	N	MB07 Steel Frame with Infill Shear Walls	196	1995	1	694 Other Service Buildings		Fair		Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ESH and/or security requirements, meets stated DOE objectives or goals, and has only minor deficiencies that can be corrected with normal operation budgets.
785	Liquid Waste Contractor	Operating	Trailer	Z	205009	STORAGE SHED										
786	Liquid Waste Contractor	Operating	Building	Z	210000	SALTSTONE PROCESS FACILITY (#1)	N	MB04 Steel Braced Frame	9,109	1992	1	593 Nuclear Waste Processing And/Or H		Fail		
787	Liquid Waste Contractor	Operating	Building	Z	210002	HANDI-HOUSE										
788	Liquid Waste Contractor	Unknown	Building	Z	210010	STORAGE BUILDING										
789	Liquid Waste Contractor	Reserved	Building	Z	210012	SALTSTONE PROCESSING FACILITY #2										
790	Liquid Waste Contractor	Reserved	OSF	Z	253000	OUTDOOR PADMOUNT SWITCHGEER										
791	Liquid Waste Contractor	Operating	Building	Z	263000	CHEMICAL STORAGE FACILITY										
792	Liquid Waste Contractor	Reserved	Building	Z	263001	STORAGE FACILITY										
793	Liquid Waste Contractor	Reserved	Building	Z	263002	STORAGE FACILITY										
794	Liquid Waste Contractor	Reserved	Building	Z	263003	RCO EQUIPMENT STORAGE FACILITY										
795	Liquid Waste Contractor	Unknown	OSF	Z	281000	EXHAUSE STACK & PAD										
796	Liquid Waste Contractor	Operating	Building	Z	291000	EXHAUSE STACK & PAD										
797	Liquid Waste Contractor	Operating	OSF	Z	451001	VAULT NO. 1	N			1991		4009 Other, Storage	N			
798	Liquid Waste Contractor	Operating	OSF	Z	451002	VAULT NO. 2	N			2000		4497 Storage Vaults (Non-Explosives)	Y			
799	Liquid Waste Contractor	Operating	OSF	Z	451003	VAULT NO. 3										
800	Liquid Waste Contractor	Operating	OSF	Z	451004	VAULT NO. 4	N			1991		4009 Other, Storage	N			
801	Liquid Waste Contractor	Operating	OSF	Z	451005	VAULT NO. 5										
802	Liquid Waste Contractor	Reserved	OSF	Z	451006	SALTSTONE DISPOSAL UNIT 6 (SDU 6)										
803	Liquid Waste Contractor	Reserved	OSF	Z	451007	VALUT NO. 7										
804	Liquid Waste Contractor	Reserved	OSF	Z	451008	VALUT NO. 8										
805	Liquid Waste Contractor	Reserved	OSF	Z	451009	VALUT NO. 9										
806	Liquid Waste Contractor	Reserved	OSF	Z	451010	VALUT NO. 10										
807	Liquid Waste Contractor	Reserved	OSF	Z	451011	VALUT NO. 11										
808	Liquid Waste Contractor	Reserved	OSF	Z	451012	VALUT NO. 12										
809	Liquid Waste Contractor	Reserved	OSF	Z	451013	VALUT NO. 13										
810	Liquid Waste Contractor	Reserved	OSF	Z	451014	VALUT NO. 14										
811	Liquid Waste Contractor	Reserved	OSF	Z	451015	VALUT NO. 15										
812	Liquid Waste Contractor	Reserved	OSF	Z	451016	VALUT NO. 16										
813	Liquid Waste Contractor	Reserved	OSF	Z	451017	VALUT NO. 17										
814	Liquid Waste Contractor	Reserved	OSF	Z	451018	VALUT NO. 18										
815	Liquid Waste Contractor	Reserved	OSF	Z	451019	VALUT NO. 19										
816	Liquid Waste Contractor	Reserved	OSF	Z	451020	VALUT NO. 20										
817	Liquid Waste Contractor	Reserved	OSF	Z	451021	VALUT NO. 21										
818	Liquid Waste Contractor	Reserved	OSF	Z	451022	VALUT NO. 22										
819	Liquid Waste Contractor	Reserved	OSF	Z	451023	VALUT NO. 23										
820	Liquid Waste Contractor	Reserved	OSF	Z	451024	VALUT NO. 24										
821	Liquid Waste Contractor	Reserved	OSF	Z	451025	VALUT NO. 25										
822	Liquid Waste Contractor	Reserved	OSF	Z	451026	VALUT NO. 26										
823	Liquid Waste Contractor	Reserved	OSF	Z	451027	VALUT NO. 27										
824	Liquid Waste Contractor	Reserved	OSF	Z	451028	VALUT NO. 28										
825	Liquid Waste Contractor	Reserved	OSF	Z	451029	VALUT NO. 29										
826	Liquid Waste Contractor	Reserved	OSF	Z	451030	VALUT NO. 30										
827	Liquid Waste Contractor	Unknown	OSF	Z	511000	INTRUSION ALARM SYSTEM										
828	Liquid Waste Contractor	Operating	OSF	Z	551000	INTER-AREA LINE										
829	Liquid Waste Contractor	Operating	OSF	Z	603000	ROADS (INC. BRIDGES & CULVERTS)	N			1995		1749 Tertiary Roads	N			Asset is fully capable of performing its current Radioactive liquid wastes dispositionmission, meets all ES&H and/or security requirements, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operation budgets.
830	Liquid Waste Contractor	Unknown	OSF	Z	604000	walks										
831	Liquid Waste Contractor	Operating	OSF	Z	605000	FENCES	N			1992		2429 Fencing	N			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ES&H and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operation budgets.
832	Liquid Waste Contractor	Unknown	OSF	Z	613000	PARKING LOT										
833	Liquid Waste Contractor	Operating	Trailer	Z	614001	PERSONNEL CONTAMINATION MONITORING FACILITY (PCB)										
834	Liquid Waste Contractor	Operating	OSF	Z	697000	SITE WORK AND GENERAL GRADING										

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
835	Liquid Waste Contractor	Unknown	OSF	Z	699000	EX MACHINERY (FOR ACCOUNTING PURPOSES ONLY)										
836	Liquid Waste Contractor	Operating	Building	Z	704000	SALTSTONE OPERATIONS BUILDING	N	MB04 Steel Braced Frame	9,067	1992	1	101 Office		Fail		
837	Liquid Waste Contractor	Unknown	Building	Z	704001	METHANE STORAGE BUILDING										
838	Liquid Waste Contractor	Operating	Trailer	Z	704002	STORAGE FACILITY	N	MB05 Steel Light Frame	360	1996		400 General Storage		Excellent		
839	Liquid Waste Contractor	Operating	Trailer	Z	704005	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,752	1988		101 Office		Poor		This modular office is 27+ years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/structure/facilities.
840	Liquid Waste Contractor	Operating	Trailer	Z	704006	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	965	1988		101 Office		Poor		This modular office is 28+ years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/structure/facilities.
841	Liquid Waste Contractor	Unknown	OSF	Z	704009	MODULAR OFFICE (#4397)										
842	Liquid Waste Contractor	Unknown	OSF	Z	704010	MODULAR OFFICE (#4396)										
843	Liquid Waste Contractor	Unknown	Building	Z	704011	MOBILE STORAGE BUILDING										
844	Liquid Waste Contractor	Operating	Trailer	Z	704012	CONSTRUCTION PERSONNEL TRAILER	N	MB05 Steel Light Frame	827	1987		101 Office		Fail		This modular office is 25+ years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Major refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/structure/facilities.
845	Liquid Waste Contractor	Operating	Trailer	Z	704013	CONSTRUCTION TRAILER	N	MB05 Steel Light Frame	917	1988		101 Office		Fail		This modular office is 28+ years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the exterior, HVAC System(s), and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Major refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/structure/facilities.
846	Liquid Waste Contractor	Operating	Trailer	Z	704014	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,277	1994		101 Office		Poor		This modular office is 20 years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Minor refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/structure/facilities.
847	Liquid Waste Contractor	Operating	Trailer	Z	704015	MODULAR OFFICE TRAILER	N	MB05 Steel Light Frame	1,679	1981		101 Office		Poor		This modular office is 35+ years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/structure/facilities.
848	Liquid Waste Contractor	Operating	Trailer	Z	704016	SDIP CONSTRUCTION TRAILER	N	MB05 Steel Light Frame	1,760	1991		101 Office		Poor		This modular office is 24+ years old and has experienced normal wear and tear. A Condition Assessment was performed and determined that refurbishment of the interior, exterior, and electrical system is required to restore this facility to adequate condition to support the Radioactive Liquid Waste Disposition mission. Refurbishment required to effectively mitigate potential negative impacts to the Radioactive Liquid Waste Disposition missions caused by aging and debilitated equipment/structure/facilities.
849	Liquid Waste Contractor	Operating	Trailer	Z	704017	SDIP CONSTRUCTION TRAILER										
850	Liquid Waste Contractor	Operating	Trailer	Z	704018	SDIP CONSTRUCTION TRAILER										
851	Liquid Waste Contractor	Operating	Building	Z	704019	Z-AREA MODULAR CONFERENCE ROOM										
852	Liquid Waste Contractor	Reserved	Building	Z	704020	CHANGE OUT FACILITY										
853	Liquid Waste Contractor	Operational	Building	Z	704021	PORTABLE REST ROOM										
854	Liquid Waste Contractor	Operational	Trailer	Z	704022	RESTROOM TRAILER										
855	Liquid Waste Contractor	Per SSSD	Trailer	Z	704023	PORTABLE REST ROOM TRAILER										Per SSSD - structure has been moved and "assigned a new Structure Number"
856	Liquid Waste Contractor	Operating	Trailer	Z	704024	MODULAR OFFICE TRAILER										
857	Liquid Waste Contractor	Operating	Trailer	Z	704025	MODULAR OFFICE TRAILER										
858	Liquid Waste Contractor	Operating	OSF	Z	734000	COMPRESSED GAS STORAGE	N			1992		4009 Other, Storage	N			
859	Liquid Waste Contractor	Unknown	OSF	Z	801000	PIPE SUPPORTS										
860	Liquid Waste Contractor	Unknown	OSF	Z	802000	STEAM LINES										
861	Liquid Waste Contractor	Operating	OSF	Z	803000	U.G. DOMESTIC WATER PIPE	N			1992		2009 Catchall	Y			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all ESKH and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operating budgets.
862	Liquid Waste Contractor	Unknown	OSF	Z	831000	SANITARY SEWERS										

Liquid Waste Facilities as of 12-8-2015

Facility Count	Assigned Contractor	Status	Prop. Type	Area Name	Prop. ID	Property Name	Excess Ind.	Model Building Type	Gross Sqft	Year Acquired	No. Floors	Usage Code	Physical Barriers (PBPI)	Summary Condition	Excess Date	Condition Notes
863	Liquid Waste Contractor	Operating	OSF	Z	831001	SEPTIC TANK - Z AREA	N			1987		5569 Septic Tanks (Sewer)	Y			
864	Liquid Waste Contractor	Operating	OSF	Z	831002	DRAIN FIELD										
865	Liquid Waste Contractor	Operating	OSF	Z	901000	FIRE WATER PUMP HOUSE	N			1992		8181 Pumping Stations (Fire Protection)	N			
866	Liquid Waste Contractor	Operating	OSF	Z	901001	FIRE WATER STORAGE TANK	N			1999		4141 Tanks, Gravity (Fire Protection)	N			
867	Liquid Waste Contractor	Operational	OSF	Z	904000	PROCESS SEWERS	N			1992		5569 Septic Tanks (Sewer)	Y			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all E&H and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operation budgets.
868	Liquid Waste Contractor	Operating	Building	Z	951000	ELECTRICAL SUBSTATION	N	MB13 Reinforce Mason Bear Walls/Wood,Metal De	1,441	1992	1	801 Other		Fail		
869	Liquid Waste Contractor	Operating	OSF	Z	953000	POWER LINES	N			1992		8909 Other, Electrical Distribution System	N			Asset is fully capable of performing its current Radioactive liquid wastes disposition mission, meets all E&H and/or security requirements, meets reliability goals, has adequate capacity, meets stated DOE requirements, and has only minor deficiencies that can be corrected with normal operation budgets.
870	Liquid Waste Contractor	Operating	OSF	Z	956000	STANDBY DIESEL GENERATOR	N			1999		5906 Electric Generators	N			
871	Liquid Waste Contractor	Operating	OSF	Z	956001	FUEL OIL TANK										
872	Liquid Waste Contractor	Operating	OSF	Z	980000	DOMESTIC WATER TANK	N			1992		5169 Wells (Potable Water)	N			
873	Liquid Waste Contractor	Operating	OSF	Z	980001	PROC. & FIRE WATER TANK	N			1999		4009 Other, Storage	N			
874	Liquid Waste Contractor	Operating	OSF	Z	980003	PROCESS WATER PUMPS	N			1992		5008 Pumping Stations	N			

M&O SERVICES to Liquid Waste Contractor via FSA 2016

SERVICE		DESCRIPTION
1	Business Services	
1-1	Finance & Benefits Accounting (PS)	Benefits Accounting Payroll, Travel, Business Systems, Pension and Post-Retirement Benefits accounting and administration services.
1-2	Services & Infrastructure Forecasts	Annual projection of needed utilities, services, and infrastructure which includes quantities and costs for each on an annual basis. M&O Contractor will develop, maintain and update a system that annually forecasts services and infrastructure requirements with associated costs.
1-3	Long-Term Stewardship	Integrated planning of LTS for entirety of SRS and interim execution of LTS for portions of the site assigned to the Contractor; includes SRS-wide assessments of institutional controls.
1-4	Planning & Budgets	Site-level budget system development and maintenance; budget formulation and execution guidance including site-level overhead rate development, financial management of site overhead organizations, site staffing reporting, overtime reporting, financial analysis, and functional cost reporting. Also includes financial and workforce analysis, funds management, NDAA language comparisons, MOB analysis, BCP processing, performance metric reporting and EAC reviews
1-5	Estimating	Site-wide business strategies, baseline integration, performance reporting, planning integration, budgeting project controls, annual Work Authorization Planning.
1-6	Program/Project Integration & Planning	Site-level issue management including strategic direction; scope definition and budgeting; manpower development, infrastructure, and resource analysis; EM EVMS fee processing and PBIs (NNSA); Management Control System polices, procedures and process guidance; site- level integrated schedules and baselines; Change Control process; site WBS, EM IPABS, Annual Plan, Out-year Budget and Life Cycle Change Control management; contract performance agreements, metrics for Key Performance Indicators, EM performance and 6B policies and procedures.
2	ESS&H: Program Services	
2-1	Site Safety Standards & Programs	Provide management guidance to ensure that SRS is a place of employment free from recognized hazards that cause or have the potential to cause death or serious harm to workers. Programs include the Worker Safety and Health Program (WSHP), Integrated Safety Management System (ISMS), Chronic Beryllium Disease Prevention Program (CBDPP) and Injury, Illness Reporting and other site documents as listed in the S/RID. Function as the integrator for health and safety with all DOE-SR prime contractors at SRS. Note: Each contractor is responsible for implementing approved procedures internally and participating in site-wide safety activities/initiatives as required
2-2	Industrial Hygiene Programs	Provides M&O Contractor and Liquid Waste Contractor with reliable, calibrated IH instruments for field use to measure chemical exposure, air quality, noise levels, etc.
2-3	Industrial Hygiene Instruments	Maintain a pool of instruments for replacement and/or lease.
2-4	Subcontractor Safety Programs	Review and accept subcontractor Worker Protection Plans and Task Specific Plans; provide field oversight of subcontractors, review of subcontractor safety submittals, maintain WPP files, develop/ maintain OSHA Category A, B, C subcontractor program guidance, and solicit Safety Engineer and STR reviews for feedback to the procurement organization
2-5	Radiological Assistance – RAP	Management of RAP aimed at providing radiological first-responder capabilities 24/7 for SRS and Region 3 (NC, SC, FL, GA, AL) in support of the DOE Regional Response Coordinator. All SRS contractors provide qualified personnel, technical expertise, equipment and support to the DOE Region 3 RAP.
2-6	Environmental Management System	Maintain site-wide EMS and manage SRS Environmental Checklist program and database as part of the Site Use Planning process. Other SRS contractors provide appropriate environmental data to support the siting process
2-7	Environmental Monitoring Program	Includes soil, water, air environmental monitoring to measure the concentration of radio-nuclides and chemicals in environmental media and assess the integrated effects of these materials on the environment and the public. M&O Contractor prepares annual SRS Environmental Report and SRS Environmental Surveillance Master Sampling Schedule
2-8	Environmental Data Integration	Provides for maintenance, configuration control and upgrade of key SRS environmental assessment databases. M&O Contractor serves as data administrator and is responsible for site-wide reporting databases
2-9	Groundwater Monitoring	Implementation of SRS groundwater strategy via maintenance and control of site-wide data and models used for groundwater/vadose zone analysis.
2-10	Radiation Protection Program	Provide a respiratory protection program and requisite respiratory protection devices in compliance with ANSI Z88.2. Manage an ALARA program and a radiological engineering program that provides radiological design analyses both in compliance with 10 CFR 835. Serve as the SRS technical authority for all radiological design aspects for new and modified facilities

M&O SERVICES to Liquid Waste Contractor via FSA 2016

2-11	External Dosimetry Services	Provides Dosimetry services using DOE Laboratory Accreditation Program accredited external Dosimetry processing capabilities for onsite processing of routine/special dosimeters.
2-12	Internal Dosimetry/Bioassay Services	Regulatory Monitoring and Bioassay Laboratory provides Dosimetry service, including processing capabilities for personnel, environmental and nuclear accident dosimeters. Other processing includes analysis of biological samples and assessment of personnel dose in the event of a nuclear criticality.
2-13	Health Physics Technical Services	Serve as SRS technical authority for all radiological design aspects for new and modified facilities. Manage the SRS ALARA program and SRS ALARA Center. Activities include deploying dose reduction equipment to the field, arranging for new equipment to be displayed at the ALARA Center, and arranging vendor visits to demonstrate new technologies
2-14	Health Physics Instrument Calibration & Distribution	Maintain a Radiological Monitoring Equipment Program compliant with 10 CFR 835 and the National Voluntary Laboratory Accreditation Program. Includes the Health Physics Instrument Calibration Facility as well as the SRS Radioactive Source Control and Radiation Generating Device programs.
2-15	Respiratory Protection Program	Administer and oversee the SRS respiratory protection program to ensure regulations are met in a cost effective manner. Activities include providing oversight of the Respiratory Equipment Facility
2-16	Facility Airborne Radioactivity Measurement Services	Responsible for maintaining an Air Sampling and Monitoring Program compliant with 10 CFR 835.
3	ESS&H: Environmental Compliance & Area Completion	
3-1	Environmental Regulatory Compliance	Site-wide processes to manage SRS environmental activities, including a site-wide strategic approach to life-cycle environmental management; generating and maintaining site-wide permits, permit applications and reports, site-wide NEPA documents and reports; and monitoring regulatory compliance status, coordinating with DOE on all regulatory interactions
3-2	SRS Policy & Site Strategy for SCDHEC Permit & EPA Closure Actions	Responsible for activities and initiatives designed to ensure compliance with DOE directives (orders, policies, and guidelines) and other federal and state environmental regulations. Includes environmental permitting, emergency preparedness, emergency response, environmental training, environmental technical assistance and facility walk-downs
3-3	National Environmental Policy Act Analysis & Documentation	Responsible for activities and initiatives designed to ensure compliance with DOE directives (orders, policies, and guidelines) and other federal and state environmental regulations. Includes environmental permitting, emergency preparedness, emergency response, environmental training, environmental technical assistance and facility walk-downs
3-4	Environmental Data Collection & Reporting	All SRS contractors collect, compile and/or integrate air and liquid effluent monitoring data from operations and activities under their control and provide environmental data for their facilities and operable units to support M&O Contractor assessments and preparation of annual SRS Environmental Report.
3-6	FFA Regulatory Support	Provide overall management of Federal Facility Agreement (FFA) commitments. Ensure FFA annual updates and project-specific requirements are achieved on time. Includes support for project deliverables, regulatory meetings and records management.
3-7	Environmental Bioassay Laboratory Services	Perform chemical and radiological analyses on low level radioactive, Environmental, Bioassay and Industrial Hygiene samples.
4	ESS&H: Medical Operations & Service	
4-1	Occupational Medicine	Occupational health services including health risk management and medical services to personnel at SRS. Identify and analyze the hazards that SRS personnel face in the work environment and bring an awareness of health and safety issues to SRS employees. Services include thorough medical history, blood-work, urinalysis, vision testing, electrocardiogram, pulmonary function testing, audiometry (hearing tests) and physical examinations
4-2	Safety Eyeglass Service	Onsite optometry services for/ provision of safety glasses to employees. Site PPE requirements determine need for safety glasses which are company-paid. Employees may also purchase safety glasses for personal use
4-3	Wellness Program Services	Wellness is about reaching the optimal state of health by making healthy lifestyle choices, thereby minimizing those health risk factors that can be controlled. Services offered through this program include access to the Mayo Clinic's website and employee newsletter, brown bag luncheons, walking programs, health screening and immunization guidelines, and coordination support with other medical programs offered on site and in the local community.
5	Technical Services: Quality & Operational Excellence	
5-1	Quality Assurance Program Support	Provide overall direction, implementation and management for QA function in compliance with applicable laws, regulations, DOE Directives, and M&O Contractor requirements.
5-2	Contractor Assurance	Provide management guidance and maintain SRS Occurrence Reporting, SRS Operating Experience, Site Tracking Analysis and Reporting (STAR), SRS Standards/Requirements Identification Document (S/RID), Quarterly Performance Analysis, and Review of M&O Contractor Activities for Price-Anderson Amendment Act (PAAA) applicability

M&O SERVICES to Liquid Waste Contractor via FSA 2016

5-3	Corrective Action Program Process & Database	Manage company process and procedures for the M&O Contractor Corrective Action Program per DOE Order requirements, including the continued development and maintenance of the STAR database; assimilate various data and conduct the Quarterly Performance Analysis for M&O Contractor in accordance with DOE M 231.1-2; provide oversight for Contractor Assurance activities
5-5	Receiving Inspection	Receiving Inspection (RI) performs inspection and quality engineering functions associated with Level 1 and Level 2 procured materials and components. Perform inspections on procured materials and components for M&O Contractor partners. Supplier QA provides M&O Contractor partners with Supplier Evaluation and Supplier Surveillance services, maintains the M&O Contractor Qualified Supplier List, and manages the M&O Contractor Supplier Corrective Action program.
5-8	Independent Evaluation Board	Provide leadership in promotion and attainment of safety and operational excellence in operating facilities, site programs and projects; confirm ongoing compliance with contractual requirements through rigorous, independent, performance-based oversight. Coordinate and conduct RAs and ORRs as needed. (Site-wide Programs Only)
5-9	Occurrence Reporting Process	Manage process/ procedures for Occurrence Reporting (including ORPS/SIRIM web-page and database) per DOE M 231.1-2; provide routine assistance/ guidance on ORPS reporting decisions; perform the ORPS reporting function (including Fact Finding Meetings) as necessary for M&O Contractor organizations not associated with facilities; develop/maintain variety of ORPS indicators to assist in performance analysis.
5-10	Lessons Learned Program	Manage company process and procedures for the Site Operating Experience (Lessons Learned) Program per DOE O 210.2; screen and research a variety of sources for potential Lessons Learned; prepare and issue site Lessons Learned communications; provide timely "for information" distribution of complex/industry matters; coordinate product recall/suspect part activities; and coordinate M&O Contractor response to DOE-HQ operating experience requests
5-11	Site Training	Provide overall management and administration of training programs and training delivery services for Federal, contractor and subcontractor employees in support of SRS missions. This includes broad operational direction, integration, and support to site projects and functional organizations in the area of training. Responsible for strategic direction and establishing the standards for SRS training programs to ensure worker safety and health and the safety and formality of operations. Note: Contract specific training is the responsibility of each SRS contractor.
5-12	Site-wide Procedures	Provide leadership and resources necessary to develop and maintain site, multi-tenant, tenant shared and M&O Contractor procedural documents.
6	Work Force Services	
6-1	Education Outreach Programs	Develop and implement education outreach initiatives with an emphasis on science, math, engineering and technology. Partner with regional educational community at all levels to provide innovative programs including Traveling Science Demonstrations and DOE Science Bowl. Participate on state, regional and local communities/boards to provide assistance and input on various education initiatives/issues. Leverage SRS resources to improve teachers' and students' knowledge and skills in science, math, engineering and technology (SMET). Assist education community by enhancing curricula for students in preparation for highly skilled workforce. Create educational partnerships and conduct recruitment and marketing activities to support Education Outreach Programs. Work with DOE-SR/HQ and community leaders to implement Executive Order 128898
7	Public Affairs Services	
7-1	Community Relations	Develop and implement a comprehensive community relations program to promote public understanding and acceptance of SRS as a responsible neighbor and as a positive asset to the community and the nation. Serve as the primary M&O Contractor interface with agencies seeking opportunities to utilize site assets for business expansion and other needs of community stakeholders. Manage a Philanthropic Giving Program that funds needs throughout the CSRA and support the Mobile Mammography, United Way, Annual Food and Blood Drives and United Way Loaned Executives programs. Implement the DOE-SR Tours Program; provide guidance, planning and implementation of site events and conferences; develop and implement the SRS Historic Preservation Program and ensure all legally mandated public involvement requirements for NEPA, CERCLA and RCRA are adhered to through public notifications and public meetings.
7-2	Public Relations and Media Communications	Proactively place news, specific to SRS, in local, regional and national media, including trade publications that cover issues pertaining to DOE facilities. The Program also serves as the primary point of contact for all external media inquiries; the creation and distribution point for DOE and corporate publications; and, the content management authority for the SRS external web

M&O SERVICES to Liquid Waste Contractor via FSA 2016

7-3	Business Executive and Employee Communications	Responsible for overall communications to M&O Contractor employees and, where applicable, site employees; executive support to the Office of the President; and business communications to ensure the mission, vision, principles and strategic direction of M&O Contractor are accurately communicated in a professional manner. Activities include presentation and speech writing, several weekly and monthly publications for use by M&O Contractor management, employees and key stakeholders; external publications, marketing, outreach materials and corporate services; maintaining InSite and site overview presentations; M&O Contractor staff biographies and executive organization chart; success sheets; fact sheets, white papers, video scripts and production support; SRS and M&O Contractor internal and external website maintenance
8	Engineering Services	
8-1	Geotechnical Engineering	Provide seismological, geological, and geotechnical engineering services. Conduct SRS seismic monitoring program and SRS settlement monitoring program; manage SRS subsurface database; as well as perform seismological, geological, and geotechnical activities for SRS site-wide applications and specific projects.
8-2	Transportation Services	Provide the services necessary to plan and implement on-site and off-site packaging and transportation of radioactive and other hazardous materials.
8-3	Nuclear & Criticality Safety Program	Provide leadership and resources necessary to establish and maintain excellence in the functional areas of nuclear and criticality safety for the nuclear facilities under M&O Contractor management.
8-4	Process Control & Automation Engineering	Includes Distributed Control Systems, Programmable Logic Controllers and Supervisory Control & Data Acquisition (SCADA) systems. Typical systems utilized are Emerson DeltaV DCS, Novatech D/3 DCS, Modicon PLCs, Allen Bradley PLCs, ICS Triplex Triple Modular Redundant PLCs, etc. Provide direct, real-time control of plant production; typically controlling multiple physical devices such as motors and valves and receiving feedback from multiple devices such as temperature, pressure and position transducers.
8-5	Site Maintenance Engineering	Provide maintenance and reliability engineering services to support the SRS mission. Services include causal and failure modes and effects analyses and reliability engineering.
8-6	Engineering Standards	Provide services for developing and maintaining a program of Engineering Standards and Guides to support engineering and operations.
8-7	Engineering Development Program	Provide technology services and R&D support to advance the SRS mission with solutions to complex process problems via demonstration and analysis. Services range from short-term consultation to large scale experimental design and testing.
8-8	Fire Protection Engineering	Provide Fire Protection Engineering expertise and skills to ensure SRS Life Safety and Facility Fire Safety Compliance requirements are achieved.
8-9	Engineering Technical & Systems Support	Provide Configuration Management services for facilities, including Configuration Management Implementation Plans (CMIPs). Provide procurement engineering services, including Commercial Grade Dedications (CGDs) and preparation/ review of specifications for systems and components. Provide Root Cause Analyses and HPI analysis
8-10	Design Engineering	Provide traditional and specialty design services including project planning design development, calculation and analyses, and procurement support of process and support systems for new facilities as well as modifications to existing facilities. Provides specialty design in the areas of Fire Protection, Safeguards and Security, Dynamic analysis of structures, Pressure Protection, and Soil Structure Interaction analysis.
8-11	Commission & Test Services	Provide leadership and resources to perform commissioning and test services for nuclear and non nuclear facilities and projects at SRS.
8-12	Infrastructure/Utilities Engineering Support	Provide Infrastructure/Utilities Engineering support which includes electrical and piped utility, rigging and traffic/transportation engineering services.
9	Construction Services	
9-9	Hazardous Waste Disposal Program	The scope of this program ensures consistency and compliance with SCHWMR. The tasks that fall under this scope include the responsibilities and requirements applied to the accumulation of all hazardous waste generated by Construction Management (CM) and Construction Subcontractors under CM jurisdiction at the Savannah River Site (SRS)
9-10	<i>Burma Road Borrow Pit Maintenance</i>	Operation of Burma Road Borrow Pit #2. Provide oversight, tracking and monitoring of outgoing material, grading, surveying, erosion control grading, weekly/quarterly inspections, regulatory reports, and compliance notifications. Also operate a site-wide program for environmental recycling, chemical redistribution and hazardous waste processing involving recycling of the site's spent photographic fixative, antifreeze, used oil, solvents, fluorescent bulbs, Ni-Cad batteries, Freon and lead, processing the site's used aerosol cans, and managing associated hazardous wastes

M&O SERVICES to Liquid Waste Contractor via FSA 2016

9-11	Recycle Program	The Recycle Program ensures that procedures, practices and resources are in place for compliance with specific regulatory requirements for waste minimization. This task includes the responsibilities and requirements for operating and maintaining the Construction Waste Minimization Program at the SRS
10	Operations Support Services: Utilities Services	
10-1	Electrical Transmission & Distribution	Management of high-voltage electrical distribution system providing power to facilities on SRS. Includes quarterly updating of EMS4 database and generation of Energy Management Annual Report. Note: SRS contractors will pay for their electricity consumption.
10-2	Energy Management Program	Provide oversight of program requirements for DOE Order 430.2B – “Departmental Energy, Renewable Energy, and Transportation Management.”
10-3	Water Systems	Operation and maintenance of site-wide water systems to include river, fire-protection, domestic, process and de-ionized water. Note: Water systems within facilities are the responsibility of each SRS contractor.
10-4	Sanitary Waste Water Treatment	Operation and maintenance of wastewater systems on SRS in accordance with all applicable State and Federal codes and regulations. Note: Waste water systems within facilities are the responsibility of each SRS contractor.
10-5	Steam	Management of intra-area and inter-area steam distribution systems. Includes operation and management of power facilities in A and D areas. Note: SRS contractors operate and maintain the steam systems within their area and facilities.
11	Operations Support Services: Infrastructure & Support Services	
11-1	Biological Controls	Biological Controls Control of noxious weeds, other vegetation and animal pests. Provide site-wide biological control program in conjunction with USFS.
11-2	Facility Services	Central maintenance functions for non-radiological facilities: facility/sign painting, carpentry, refrigerated equipment services, HVAC, insulation, pipefitting, electrical, sheet metal, instrumentation, cement finishing, glazier work, custodial, locksmith, movers and equipment calibration.
11-3	Site Housing	Provide planning and oversight of site housing space consistent with site/area missions, strategies, and contract principles; optimize space utilization to reduce both operating costs and site footprint; manage personnel/furniture relocations; oversee Trailer Commodity Management Center.
11-4	Fire Test & Maintenance	Provide periodic testing and maintenance of fire protection systems by NICET qualified personnel. Conduct miscellaneous tests including detector sensitivity, full flow, post indicator and internal pipe inspection. Schedule and coordinate activities with affected facility and review test results with same. Perform acceptance testing of new and modified systems and provide recovery/ recycling of Halon gas
11-5	Fuel Management	Provide site fuel supplies (gasoline, diesel, ethanol) and management programs for site specification, supply arrangements, purchases, delivery, bulk tank storage, testing, and self-dispensing gas stations. Provide required diesel fuel testing, controls, and supply and delivery capability for Safety Significant/Safety Class emergency diesel generators to support facility operations and emergency response. Also provide monthly and annual fuel usage reporting to process billings, and monitor usage
11-6	GSA Fleet Management	Track and report usage data for motorized vehicle fleet; perform repairs; provide record-keeping, assignment, utilization and excess/disposal duties for vehicles/parts.
11-7	Hoisting & Rigging Commodity Center	Perform oversight and commodity management center functions related to the acquisition, testing, inspection and allocation of Hoisting and Rigging equipment used at the Savannah River Site.

M&O SERVICES to Liquid Waste Contractor via FSA 2016

11-8	Site Development Control	<p>Provide real property management for SRS land through administration of the following programs:</p> <ul style="list-style-type: none"> • Site Clearance Program – coordinate site clearance request approvals to ensure proposed construction does not encroach upon existing or planned facilities. • Site Use Program – document formal approvals of SR Land Use Committee regarding use of SRS property. • As-Built Program – document as-built configurations of all site utilities, commodities and systems; mapping updates and services to correct legacy as-built discrepancies. • Site Boundary Program – oversee site boundary technical data, including inspection of physical site boundaries for maintenance issues.
11-9	Site Infrastructure Shop Services	<p>Provide machining and fabrication of engineered components, testing and repair of pressure relief valves and custom fabrication of mechanical and electrical Jumpers. Electrical Shop services include calibration and repair of electrical breakers, motors, Portal Monitors, Nuclear Incident Monitors, Measuring & Test Equipment, In Process Instrumentation, Industrial Hygiene and Radiation Monitoring Equipment. Radiological Shops services include custom design and fabrication of radiological containments/ installations and assembly/ testing of Respirators, Plastic Suits and Fresh Air Hoods</p>
11-10	Site Radio Services	<p>Coordinate and support site radio system and trunking infrastructure.</p>
11-11	Site Pager Services	<p>Coordinate and support site pager system infrastructure.</p>
11-13	Real Property Management (includes 10-yr site plan, FIMS)	<p>Oversee and ensure compliance with DOE Order 430.1B, Real Property Asset Management.</p> <ul style="list-style-type: none"> • Administer DOE-HQ, Facility Management System and Condition Assessment Information System databases • Conduct Condition Assessments survey inspections • Oversee planning and administration of Site Housing structures (administrative, warehouse, shop, lab) to ensure maximum utilization of assets; manage the SRS Trailer Commodity Management Center; and provide program oversight of systems and free-standing furniture. • Administer Site Use/ Clearance Permit land use planning and control; maintain As-built configuration of all systems/commodities/utilities; maintain Site Boundary configuration control.
11-14	Respirator Equipment Facility	<p>Supply respiratory protection equipment to protect employees from airborne/ skin exposures to radioactive and chemical health hazards. The REF processes (assembles, tests, maintains, packages) a variety of negative pressure respirators, respirator cartridges, vortex tubes, air supplied respirators and plastic suits and hoods, and administers respirator fit testing</p>
11-15	Roads & Grounds	<p>Includes road and grounds maintenance for support organizations and projects that support primary site roads (traffic lights, and surface maintenance), bridges, road sign maintenance and facility grounds, streets, and parking lots within G&A/ESS areas, snow removal/ adverse weather response, spill recovery/ accident/ abandoned waste site clean-up, traffic engineering, pest control, Railroad & C&D Landfill operations and management of Site High/Low Hazards Dams</p>
11-16	Transportation Operations	<p>Includes central trucking waste hauling services that provide qualified drivers and necessary equipment to transport equipment and materials on and off Site; Roads and grounds support including primary site road maintenance (traffic light repair, crack sealing, striping, patching, paving, sweeping, shoulder maintenance and herbicides), bridge and road sign maintenance; Grounds maintenance (signage on grounds, side walk maintenance, crosswalks, and drainage), street and parking lot maintenance, snow removal/adverse weather response, spill/ accident /abandoned waste site clean-up, traffic engineering and pest control</p>
11-17	Transportation Services (includes trash pickup)	<p>Includes Hazardous Material Transportation guidance and oversight; DOT oversight and administration of DOT drivers and vehicles; Traffic Services processes freight billings, schedules out-bound trucking shipments for major projects and coordinates household goods moves for new hires; Fleet Management manages the Site's fleet of GSA leased vehicles; Fuel Management oversees the Site's 7 fuel stations and bulk fuel station and delivers fuel to equipment, tanks and vehicles at area locations</p>
11-18	Rigging & Cranes	<p>Provide Rigging services to all areas and contractors on SRS as requested. Includes normal, complex, and critical lifts. Also provide crane inspections (conventional & overhead), rigging hardware inspection, fall protection applications, lift truck operations, scaffold erections/inspections to meet site standards. Provide rigging oversight for subcontractors</p>
11-19	Railroad Services	<p>Operate and maintain the rail system at SRS. Identify future use requirements and coordinate with other contractors/projects prior to and during any on-site rail movements. Provide security actions and notifications</p>
11-20	Subcontract Management & Technical Representatives	<p>Provide management and planning services for the execution of subcontracted work activities in support of facilities and projects to include procurement support, design interface, facility interface, specification development, field coordination & oversight, and acceptance inspections.</p>

M&O SERVICES to Liquid Waste Contractor via FSA 2016

11-21	Facility Information Management System	Manage FIMS database to provide inventory and decision-making tool for managing real property assets. Generate all required reporting.
11-22	Janitorial Services	Basic janitorial services for SRS on-site buildings.
11-23	Laundry Services	Commercial laundry and decontamination services for government-owned protective clothing, non-regulated items, and regulated face pieces. Includes periodic batch pick-up and drop-off at site locations
11-24	Food Services	Manage vendors providing food services at SRS. Includes four cafeterias and three food courts in SRS facilities using SRS owned equipment.
12	Operations Support Services: Site Maintenance	
12-1	Site Maintenance Program	Site integration of maintenance programs (M&O Contractor, Liquid Waste Contractor and subcontractors performing work for the Performing Entities) and compliance evaluation of Federal regulations, DOE Orders and Site policies/procedures
13	Operations Support Services: Interface Management	
13-1	SRS Interface Management Plan	Define processes and agreements to ensure effective control of technical, administrative and regulatory interfaces among all SRS contractors. Develop all interface documents needed for exchange of services
13-2	SRS Interface Management Team	Oversee development and maintenance of effective interfaces among SRS tenants. Foster effective collaboration and cooperation among site tenants; oversee development and approval of interface management processes, plans and procedures, and facilitate issue resolution per established procedure.
13-3	SRS Site Interface Communications	Establish processes and systems for interface management at SRS between contractors. Utilizing the IMT, develop procedures for all site tenants to follow and publish in site-level procedure manuals. Communicate interface issues, Lessons Learned and IMO process and procedure changes to all site tenants.
13-4	SRS Interface Issue Resolution	Facilitate issue resolution between M&O Contractor and other site Contractors using a process that is based on problem resolution at the lowest level possible: inter-Tenants to IMO to company Presidents to DOE arbitration
14	Procurement, Assets & Materials Management Services	
14-1	Procurement Services	Execute Contractor purchasing function in conformance with DOE Regulation Subpart 970.44, and in accordance with terms and conditions of prime contract. Provide independent review of procurement operations, develop and administer procurement policy/procedures, oversee training and safety activities, audit and self-assessments, Subcontract Management Program; conduct financial management, operational planning; procurement reporting, requisition control and data entry; administer Procurement Credit Card Program; review procurement packages for Level 1 and 2 (engineered and commercial) items; perform supplier quality audits, systems support, maintenance and storage of procurement-related files and documentation
14-2	Property Systems/Acquisitions & Materials Management	Property Systems/Acquisitions & Materials Management Site-wide processes/procedures for centralized personal property management: recycling, asset tracking and database reporting, excess disposition, equipment transfers and loans and management of on-site inventories/warehousing operations.
14-3	Copier Commodity Management	Provide program oversight for distribution, use and maintenance of ~ 500-leased copiers used by M&O Contractor, Liquid Waste Contractor, and DOE.
14-4	Chemical Commodity Management	An integrated approach to safe acquisition, utilization, storage, and disposition of chemicals and chemical products. The Chemical Management Center (CMC) develops and implements the Chemical Management Program at SRS. The CMC is the Single Point of Contact at SRS for all chemical issues.
14-5	Central Warehouse Operations – Receiving	Perform material receipts and acceptance for materials needed by M&O Contractor (and other site contractors) areas, facilities and projects. Includes unloading/handling of all freight and package deliveries from common carrier and supplier delivery trucks, verifying materials are received in accordance with PO documentation and entering receipt information into the Field Materials Tracking System (FMTS), accounting for/authorizing payment for materials received
14-6	Central Warehouse Operations –Warehousing/Storage	Perform all aspects of Site warehousing. Includes stocking, storage and order fulfillment of stocked “Stores” inventory, storage of project materials, large equipment, compressed gas cylinder storage, bulk liquid nitrogen storage and flammable material storage. Also includes periodic inventory validation documentation and QA storage program management (Shelf Life and In-Storage Maintenance) for associated items.
14-7	Central Warehouse Operations –Delivery/Distribution	Deliver all Material Receipts, Stores Order items, stored equipment issues to M&O programs and projects, as well as to other site Contractors. Includes site-wide pick-up/delivery of empty/full compressed gas cylinders. Provide material packaging, palletization, rigging and stabilization of materials in preparation for safe transportation and coordinate with cranes and rigging to load, transport and offload items, as needed.

M&O SERVICES to Liquid Waste Contractor via FSA 2016

14-8	Central Warehouse Operations –Shipping	Provide off-site shipping of SRS materials, return of materials to suppliers, and radioactive shipments for M&O Contractor and other site contractors. Services include bill of lading preparation, material packaging, loading, blocking and bracing as required
14-9	Central Warehouse Operations –Mail Services	Mail Services provides intra and inter-area mail drop distribution and pickup, as well as incoming and outgoing mail sorting and processing for M&O projects and programs, as well as DOE-SR and multiple other site Contractors. Mail Services include morning pick up from two local area post offices and evening drop-off to one local post office on a daily basis
14-10	Material Access Centers	Provide primary field/facility contact for procurement activities. Perform purchasing activities utilizing site Procurement Card (Pcard) and releases on Strategic Source contracts. Determine “best method” of material acquisition for field customers. Provide programs to manage, control, and issue facility- owned materials including facility warehousing, laydown yards, tool control, bulk materials, spare equipment and “dedicated” items. Provide intra-area receipts, materials delivery, and mail delivery
15	Safeguards, Security & Emergency Services	
15-1	Physical Security Programs – Government Property	Security Representatives are assigned to security areas at the SRS to support facility/area implementation of site level S&S Policy and Procedures for the protection of government property (includes security plans, barriers, access control, lock and key control, etc.) except those areas maintained by the USFS (SRS boundary maintenance)
15-2	Physical Security Programs – Nuclear Material, SNM, & Classified Matter	Security Representatives assigned to all security areas at the SRS to support facility/area implementation of site level S&S Policy and Procedures for the protection of Nuclear Material, SNM and Classified Matter
15-3	Vulnerability Assessment & Physical Security Analysis	Conduct systematic evaluations of targets to identify weaknesses in facility operations, physical security systems, material control & accountability, protective force, response plans, physical structures, emergency operations, processes and procedures. Develop cost-effective counter measures and prioritize program investments focused on reducing or mitigating risk. Prepare Safeguards & Security Authorization Basis documents including Vulnerability Analysis Reports, Site Safeguards & Security Management Reports, and technical risk assessment reports. Provide physical security expertise for RAs, Facility Surveys, ORRs, FEB. Support, coordinate and participate in large-scale force-on-force exercises.
15-4	Information Security Program	Control and accountability requirements for classified matter including marking, reproduction, receipt and transmission, and destruction; physical protection requirements for classified matter and operation of Classified Document Control Center
15-5	Personnel Security Program – Badging	Access control, badging, visitor control, and subcontractor badging administration including manufacture, issuance, destruction, control of and accountability for DOE Standard, SR Specific, Temporary, and Personal ID Verification badges
15-6	Personnel Security Program – Human Reliability Program	Administration of HRP to ensure that employees with access to certain materials, nuclear explosive devices and programs meet highest standards of reliability and physical/mental suitability. Includes initial and refresher training
15-7	Personnel Security Program – Workplace Substance Abuse Program	Administer the WASP and establish testing procedures. Program applies to DOE contractors and their subcontractors in testing-designated positions, and is designed to maintain a workplace free from use of illegal drugs
15-8	Nuclear Materials Control & Accountability Program	Responsible for programs, policy oversight and accountability of all reportable nuclear materials in the custody of M&O Contractor. NMC&A staff monitors access controls, surveillance, containment, and protection of nuclear materials. Material Accountability staff supervises/reconciles physical inventory of SNM, maintains central accounting records, accounting software - LANMAS/ SRSMAS, administers tamper-indicating device (TID) program, monitors material control indicators, and evaluates measurements and measurement control. Additionally, provides DOE-HQ/ SR data, investigates anomalies, responds to emergencies, performs internal assessments, and supports International Atomic Energy Agency inspections
15-9	S&S Program Management – Safeguards & Security Awareness	Provide S&S Awareness training for Federal and contractor employees, subcontractors, and visitors at SRS; conduct security training for all permanently badged employees initially and on an annual basis thereafter
15-10	S&S Program Management	Provide S&S policy/ processes for planning, performing, assessing and improving the secure conduct of work in accordance with risk-based protection strategies. Manage S&S program elements and Site S&S Planning. Provide S&S Self Assessment Program, S&S Performance Assurance Program, S&S Training Program and administer S&S Findings Program. Act as primary M&O Contractor POC for Centerra-SRS Team.
15-11	Security Systems Maintenance	Provide security system maintenance for all facilities with significant S&S assets, design or assist in design of security systems for new facilities or system upgrades for facilities with new or changing requirements
15-12	Media Sanitization	Meet control, accountability, and physical protection requirements for destruction of site classified/un-classified computer media and electronics. Perform sanitization/High Risk Assessment of all Automated Data Processing Equipment (ADPE) exiting site through excess operations. Perform Cyber Security reviews/ approvals of all site electronic shipping orders containing ADPE for any security issues. Provide guidance/direction to site on DOE procedures/ orders on all items listed above.
15-13	Locksmith Support	Provide locksmith support for installation, replacement, and maintenance of locks, keys, and access control systems to protect Government property and nuclear materials, classified matter, etc
15-14	Fire & Emergency Response	Provide fire prevention, fire suppression, fire investigations; technical rescue; emergency medical service and patient transport; incident command; and hazardous material and chemical/biological/radiological emergency response for the SRS

M&O SERVICES to Liquid Waste Contractor via FSA 2016

15-15	Emergency Operations (SRSOC)	The SRS Emergency Operations Organization is the first point of notification for any emergency on site. All emergency responders can be requested and dispatched by calling the SRS Operations Center (SRSOC) at 3-3911 from any site telephone or (803) 725-3911 from any cellular phone.
15-16	Emergency Management	Site-wide Emergency Preparedness Program including operation of the EOC, hazard surveys and assessments, EOC staff training, site-wide emergency exercises, and facility-specific plans and procedures for emergency preparedness
16	Solid Waste Management Services	
16-1	Waste Forecast & Tracking System	In conjunction with the Solid Waste Integrated Forecasting Tool identify future quantities of hazardous/ radioactive/ sanitary waste generation for SRS and off-site generators, and track through disposal
16-2	Waste Storage, Treatment & Disposal (LLW, MLLW, HW, Sanitary, TRU)	Treatment, storage, and disposal of LLW, MLLW, HW and Sanitary Waste. (Other contractors characterize, package, interim store and prepare waste for transport to M&O Contractor.) Also includes TRU and TRUM certification, interim storage and loading of shipments for transport to WIPP. (Other contractors characterize, package and transport waste to M&O Contractor.
16-4	Waste Generator Certification Support & Oversight	Provide support for required waste generator programs shipping waste to on-site and off-site T/S/D facilities. Includes initial generator certification approval and periodic follow-up surveillances/audits; waste acceptance procedure maintenance, performance indicators, and document control; review/ approval of waste stream characterization forms and certification plans, dose-to-curie calculation assistance, and periodic waste stream characterization re-validation. Provide waste avoidance program support in accordance with the SRS Pollution Prevention Program. Oversee the Solid Waste Management Committee. Manage GCO qualifications, curriculum and training including support for Environmental Compliance Authorities and waste Cognitive Technical Functions. Support pre-generation approval requests to DOE-SR for the generation of waste with no identified path for disposal. Provide POC support for generator waste management operations required to meet SRS waste acceptance criteria. Provide oversight and certification for off-site waste shipments. Provide DOE-required forecasting and reporting of newly-generated waste. Maintain site procurement specs for the procurement and inventory of radioactive solid waste packaging, bags, and required packaging filter vents.
16-5	Pollution Prevention (P2) Program	Provide site-level pollution prevention program compliant with regulations and directives as defined per 3Q, 6.11. Services include managing and integrating the P2 Program with the SRS Environmental Management System (EMS) and associated Integrated Safety Management System (ISMS); providing data collection and associated reporting to meet annual DOE requirements; providing POC support and database maintenance to help identify and document waste avoidance opportunities; supporting employee P2 awareness with training programs/events and community outreach to promote P2 concepts.
17	Information Services: Communications Infrastructure	
17-1	Telephone Services	Provide basic access to on-site and off-site voice communications via the SRS Telephone System. Includes authorized long distance service; voicemail; access to site audio conferencing; directory and site operator services; emergency phones; cellular and Blackberry contract integration/ administration; long distance calling card administration
18	Information Services: Consolidated IT Services	
18-1	SRS Standard Desktop Support	Provide and manage the SRS Standard Desktop including site standard Window-based software, automated updates to all desktop software configurations including anti-virus software and security patches, Windows file and print services including file back-up, and PC lease coordination.
18-2	CCF Systems Access	Operate primary and back-up data centers to include backup and disaster recovery support services. Provide access to major site information systems/applications including the Data Warehouse. Provide end-user Help Desk support and oversee Computer Accounts management and administration.
18-3	SRSnet Access	Operate and manage on-site IT networks and provide connectivity to major site systems and services for authorized network users.
18-4	Intranet/Internet Access	Provide and manage InSite and related applications including Auto Page System, HR Query Tool, Organization Trees and Traversal, Password Checker, Phonebook, Personal Information Editor, PIN Code Utility, Quick Search, Web Statistics, TACS Shift Calendar, Yellow Pages, Homepage, Provider Tool and SRS Phone on Disk
18-5	Cyber Security Compliance Coordination & Admin	Includes Cyber Security Operations coordination, implementation and liaison with Cyber Security; coordination and enforcement of Site Vulnerability and Patch Management Process; management of approved desktop and server Security Baselines; management of Secure Desktop program; coordination of Certification and Accreditation Program for CI managed boundaries for both unclassified and classified systems; management of DNS appliance, proxy server configurations, Bomgar appliance and SecurID configurations, and firewall and Bluecoat proxy filters; implementation of Homeland Security Presidential Directives (HSPD-12); and, identification/protection of classified, unclassified and sensitive information generated, processed and stored by CI for the SRS.

M&O SERVICES to Liquid Waste Contractor via FSA 2016

19	Information Services: Cyber Security	
19-1	Cyber Security Services	Develop, implement and enforce classified and unclassified cyber security programs per DOE directives and federal law. Includes security architecture development and oversight, system and network security, intrusion detection monitoring and response, certification and accreditation, auditing and assessments, incident handling, encryption programs, media sanitization and destruction oversight, virus and malware detection and eradication, configuration management oversight, vulnerability scanning systems, forensics, training and awareness.
20	Information Services: Email Accounts	
20-1	Email Account Services	Provide access to Lotus Notes email accounts, applications and Personal and Group Notes Document Libraries. Manage and support integration of the Blackberry infrastructure within Lotus Notes. Provide email Spam filtering services
21	Information Services: Documentation & Records Management	
21-1	Records Management	Manage, in compliance with government regulations, the electronic and hardcopy collection of classified and unclassified records originated or held by SRS contractors. Maintain systems for access, distribution, and storage of records, ensuring availability consistent with SRS needs. Includes all media (electronic systems, databases, spreadsheets, photo/negatives, hard copy paper, all other formats and medias.)
21-2	Printing & Reproduction Services	Provide state-of-the-art, color/font managed reproduction products/services including copying, CD and DVD duplication, poster production, etc. Perform subcontracted printing process for SRS including specifying job requirements and ensuring requirements are met, in compliance with Federal regulations.
22	Information Services: Direct Services	
22-1	Software Development & Maintenance Services	Develop software to meet business requirements for on-site business processes and productivity needs and maintain software once in a production environment. Includes application support to existing tenant portfolios as well as commercial off the shelf product support for on-site use. Also includes certification and accreditation support in compliance with DOE Cyber requirements, as well as implementation of IT projects developed to DOE System Development Methodology
22-5	End User Hardware Provisioning	Acquire and manage phones, Blackberries, personal computers, radios and pagers for SRS personnel.
22-6	Engineering & Operations Document Control	Disseminate the latest configuration of facility documentation such as Drawings, Procedures, Calculations, Vendor documentation etc. Maintain technical baseline documentation and manage associated change documents. Provide control and maintenance of essential documentation to EOC and other Facility Control Room locations. Provide Controlled, Information Only and Working copies.
23	Savannah River National Laboratory Services	
23-1	Research & Development	Conduct research and technology development studies to address needs of SRS contractors, other DOE sites and Federal Agencies, and some commercial entities. Provide facilities/services in robotics, atmospheric technology, materials science, computational science, and various analytical techniques. Develop and perform unique research and development activities over a wide range of scientific disciplines with both radioactive and non-radioactive materials, as needed
23-3	Analytical Instrument & Sampling Services	Analyze samples for radioactive and non-radioactive components. Design, procure and test installed analytical instruments and detectors; develop operation and calibration procedures; establish instrument limitations. Provide analytical instrument development research as needed. Support development of methods and confirmation of results for SRS labs and others. Develop and provide customized samplers for remote and/or unique sample retrieval
23-4	Calibration Services	Calibrate measuring and test equipment (M&TE) to meet requirements of DOE Standards and Calibration Program. Maintain National Institute of Standards and Technology calibrated reference standards; provide calibration services for users of transfer working standards and M&TE. Maintain system to preclude use of M&TE for which calibration is out or expired. Confirm acceptance criteria for procurement of special items.
23-5	Process Support	SRNL offers process support through a wide range of techniques and capabilities, e.g., qualify feed batches for processing (any scale), analysis of samples, computer modeling, statistical data analysis and planning. Provide complete meteorological support for relevant processes, including consequence assessments for timely response to site emergencies or scenarios in emergency planning; create and manage meteorological databases for use in EPA models and provide meteorological data required for compliance and safe site operations.
23-6	Flow-sheet Development	Develop waste forms and formulations to meet disposal criteria. Provide needed materials or formulation for vendors, e.g., grouts and fill materials. Develop/provide reagents, simulants, and tracer fluids for testing or process control.

M&O SERVICES to Liquid Waste Contractor via FSA 2016

23-7	Environmental Services	Develop technical basis for performance assessments supporting closure of and disposal authorization for facilities – includes original development work, periodic revisions and ongoing maintenance of baseline documents. Services include development of conceptual models and input data (lab and field work); material property testing and material degradation testing and modeling; development/ testing of computer models; atmospheric release models; aqueous release models; testing/analysis of waste forms and treatment and cleaning technologies. Also provide direct support for treatment/remediation of contaminated soil and groundwater - includes development of methods to remediate waste sites in-situ and ex-situ, sampling, monitoring, modeling, and regulator interface support. Expertise is available in dealing with contamination of radionuclides, organics, and heavy metals.
23-8	Project Support	Participate in systems engineering evaluations, provide input to hazard analyses, design document reviews, design and construction plan reviews, technology reviews, downstream impact assessments, out-year planning for feed batch preparations, reviews by external panels, and participate in Operational Readiness Review. Includes general technical support such as technology development input, consultation, literature reviews, etc.
23-9	Safety Documentation & Program Support	Perform testing to support safety documentation or analysis for facilities. Includes sample analysis and process testing/evaluation in support of DSA/TSR issues (e.g. tank flammable gas control program). Provide technical support for Waste Acceptance Criteria, Waste Compliance Plans, Waste Form Compliance Plan/Waste Form Qualification Reports, Quality Assurance audits and similar documents.
23-10	Vendor & External Interactions	Initiate and maintain vendor subcontracts. Act as STR for selected vendor/provider contracts, review vendor documents and bids, perform QA audits of vendors/suppliers, and generate or prepare samples for off-site analysis. Subcontract services to vendors, universities, or other laboratories to meet project objectives, depending on circumstances
23-11	Materials, Welding & NDE Support	Maintain welding technology development program, administer site welding procedures, and continue support of site welding program. Maintain activities related to materials support and NDE techniques. Perform tasks such as essential technical corrosion support, inspection programs, modeling, and experiments to support the operation of facilities. Includes such items as: welding consultation – failures, material issues, metallurgy, etc.; welding work package implementation; oversight of subcontractor welding; NDE examinations structural reviews - failure analysis; corrosion evaluation testing; cathodic protection analysis; service life estimates and modeling; structural integrity calculations; radiation degradation studies; etc
23-12	Packaging Support	Provide technical guidance and support to develop/ maintain On-site Safety Assessments for radioactive packaging and Safety Analysis Reports for Packaging (SARP) for off-site shipments. Includes support for radioactive packaging, fabrication, testing and modification; preparation of safety documentation for alternative packaging; determination of Type A/B fissile packaging design criteria; support of non-routine radioactive material shipment and transfer; preparation/maintenance of SARP for certified packaging designs, etc.
23-13	Indirect & Miscellaneous Support	Collaborate with site contractors at SRS and other DOE sites to promote DOE objectives and maximize resources. Arrange and manage meetings and workshops, support CRADAs, provide personnel for temporary assignment, part-time or co-location assignment, and for back-up SME support – as requested and funded by contractors. This support includes SMEs for tasks such as in-service inspections or the Corrosion Control Program.
23-14	Engineering Programs Support	Provide Engineering support to SRNL facilities along with site and off-site initiatives and missions. Support Solid Waste and Infrastructure 2004-2 evaluations. Develop Table 5.1, Ventilation System Performance Criteria for SRNL BC, EF, & AD Wings per System Evaluation Guidance.
23-15	Mechanical Systems & Custom Equipment	Provide design and fabrication, installation testing assistance, and field operation of unique equipment systems for use in radioactive, hazardous, or inaccessible environments. Includes development and mechanical design of robotics and remote handling systems for new capital projects and work for others; development, design and deployment of robotic or remote devices into existing facilities for sampling or inspection purposes; mechanical design and modification to existing on-site process equipment or systems; and providing remote and mechanical equipment to facilitate quick response to emergent SRS issues and situations
23-16	Environmental Management	Provide EM support that includes technical integration, process flow-sheet development, regulatory compliance studies, technical strategic and program planning, and technology development, assessment and deployment at this and other DOE sites and external entities.
23-17	Energy Security and Engineering	Assess/develop applications for hydrogen storage, biomass and wind energy, battery technology, fuel cells, next generation nuclear plants, etc. Provide destructive and nondestructive evaluations, packaging technology, robotics and remote systems for specialized application.
23-18	National and Homeland Security	Provide expertise in hydrogen and actinide technology to support NNSA programs (Tritium, MOX, actinide storage and shipment, spent fuel management, etc.) at this and other DOE Sites.
23-19	Environmental Science and Biotechnology	Provide technical support for biological/ ecological sciences, geosciences, biotechnology /microbiology and regulatory response. Services include site selection, environmental dosimetry, biohazard assessments, wetlands delineation, water and sediment quality/toxicity/treatment, geological core facility, and environmental compliance strategies and mitigation measures

M&O SERVICES to Liquid Waste Contractor via FSA 2016

23-20	SRNL Facilities	<p>Provide Operations, Safety, Industrial Hygiene, and Radiological Control support services, materials, and equipment associated with SRNL facilities.</p> <p>Maintain Category 2 and 3 nuclear facilities within the approved authorization basis.</p> <p>Ultra low-level underground counting facility –located 50 feet below ground level with 4” thick walls of pre-nuclear weapons era steel to allow measurement of ultra-low amounts of environmental radioactivity, free from interference by background radiation.</p> <p>Remote systems laboratory –design, develop, fabricate, and test unique equipment systems for use in radioactive, hazardous, or inaccessible environments.</p> <p>Radiochemistry and analytical laboratories - feature contained instruments for analysis of radioactive and non-radioactive samples for many species.</p> <p>Engineering development laboratory – innovative tests/demonstrations of equipment and designs.</p> <p>Glovebox facilities – sealed, protectively-lined compartments with attached gloves that allow workers to safely handle dangerous materials.</p> <p>High-pressure test facility – steel-walled cells for high-pressure hydrogen exposure, fatigue and fracture toughness testing of metal specimens.</p> <p>Metal hydride laboratories –research and develop metal hydride absorption and desorption performance.</p> <p>Primary standards laboratory –calibration services compliant with American national standard.</p> <p>Atmospheric Technologies Center – feature extensive capabilities for world-wide meteorological forecasts and real-time atmospheric transport modeling and assessment.</p> <p>Gamma Irradiation Facility – equipped with devices for irradiating solid and liquid samples, allowing a wide range of tests to determine effects of radiation on materials (life expectancy and/or materials performance under a variety of conditions).</p> <p>Environmental Sciences R&D Laboratory – environmental analyses of soil and water; workshops for assembly and deployment of innovative technologies in field applications.</p> <p>Biotechnology Laboratories – bio-analytical, microbiological and molecular biology instrumentation to support R&D in environmental and energy technology development and demonstration.</p> <p>Glass Blowing Facility – design and fabrication of specialized glassware and glass equipment.</p>
24	Analytical Services	
24-1	F/H Analytical Lab Services	<p>Perform chemical and radiological analyses on a wide range of materials including liquid and solid process, environmental, industrial hygiene and highly radioactive samples.</p> <p>Note: Special analyses to support Contractor activities may be on a fee for service basis.</p>
24-2	Analytical Integrated Planning	<p>Provide integrated site-wide analysis plans, data quality objectives, and process and analytical technology support. Develop sample analysis rates and waste generation estimates. Use integrated planning products to plan sample analysis expenditure:</p>

Current LW GSA LEASED		
Number of Vehicles	License Number	Description
1	G410219H	Van, Passenger (7)
2	G410585R	Van, Passenger (7)
3	G420617P*	Pickup
4	G421525R	Pickup, Crew Cab
5	G420555K*	Pickup, Crew Cab
6	G421520R	Pickup, Crew Cab
7	G421523R	Pickup, Crew Cab
8	G430138P*	Delivery Van, Cut-Off Cab
9	G432730B*	Van, Multistop (Breadtruck)
10	G432731B*	Van, Multistop (Breadtruck)
11	G432734B*	Van, Multistop (Breadtruck)
12	G410587R	Van, Passenger (7)
13	G420101H	Pickup
14	G433083K	Pickup, Utility
15	G410249H	Pickup
16	G410596R	Van, Passenger (7)
17	G131041N	Sedan, Subcompact
18	G420086H	Pickup
19	G421042R	Pickup
20	G421058R	Pickup
21	G421060R	Pickup
22	G421066R	Pickup
23	G131042N	Sedan, Subcompact
24	G410220H	Van, Passenger (7)
25	G410241H	Pickup
26	G410251H	Pickup
27	G410255H	Pickup
28	G410261H	Pickup
29	G410264H	Pickup
30	G412689G	Van, Passenger (7)
31	G420082H	Pickup
32	G420092H	Pickup
33	G420122L	Van, Cargo
34	G420140L	Std Pickup C Cab (Hybrid)
35	G420554K	Pickup, Crew Cab
36	G420574K	Pickup, Crew Cab
37	G420577K	Pickup, Crew Cab
38	G420618P	Pickup
39	G420620P	Pickup
40	G420621P	Pickup
41	G420853M	Pickup, Crew Cab
42	G421043R	Pickup

Current LW GSA LEASED		
Number of Vehicles	License Number	Description
43	G421044R	Pickup
44	G421047R	Pickup
45	G421067R	Pickup
46	G421076R	Pickup
47	G421136G	Pickup
48	G421139G	Pickup
49	G421141G	Pickup
50	G421147G	Pickup
51	G421199N	Pickup
52	G421267N	Pickup, Crew Cab
53	G421479L	Pickup
54	G430133P	Pickup, Utility
55	G430134P	Pickup, Utility
56	G430151H	Pickup, Crew Cab (6)
57	G432091G	Pickup
58	G432098G	Pickup
59	G433092K	Pickup, Utility
60	G433093K	Pickup, Utility
61	G433094K	Pickup, Utility
62	G433111K*	Stake Truck
63	G631132G	Carryall, 4x4 (8)
64	G710204B*	Stake Truck
65	G710588L*	Stake Truck
66	G8200125*	Truck Tractor, 6x4
67	G820029F*	Stake Truck
68	G820136L*	Stake Truck
69	G820143F*	Stake Truck
70	G820281B*	Stake Truck
71	G820283B*	Stake Truck
72	G820433H*	Truck Tractor, 4x2
73	G900012K*	Fuel Truck
74	G410605R	Van, Passenger (7)
75	G410685P	Van, Passenger (7)
76	G414907L	Van, Passenger (7)
77	G420158P	Pickup, Crew Cab
78	G421045R	Pickup
79	G421095R	Pickup, Crew Cab
80	G421097R	Pickup, Crew Cab
81	G421145G	Pickup
82	G421194N	Pickup
83	G430164H*	Service Utility, Ext Cab
84	G432096G	Pickup

Current LW GSA LEASED		
Number of Vehicles	License Number	Description
85	G433090K*	Pickup, Utility
86	G433097K*	Pickup, Utility
87	G101045K	Fusion - Hev
88	G410684P	Van, Passenger (7)
89	G430236R	Van, Passenger (15)
90	G410265H	Pickup
91	G410601R	Van, Passenger (7)
92	G412670G	Van, Passenger (7)
93	G420081H*	Pickup
94	G420084H*	Pickup
95	G420559K*	Pickup, Crew Cab
96	G420570K*	Pickup, Crew Cab
97	G421127G*	Pickup, Crew Cab
98	G421207N	Pickup
99	G421222N	Pickup
100	G421611N	Pickup, Crew Cab
101	G421908K*	Pickup, Crew Cab
102	G430152H*	Pickup, Crew Cab (6)
103	G430910N	Pickup, Crew Cab (6)
104	G432064G*	Pickup, Utility
105	G432083G	Pickup
106	G432108G*	Pickup
107	G432854P*	Stake Truck
108	G434354M*	Stake Truck
109	G630079P*	Pickup, Utility, 4x4 (6)
TOTAL COUNT: 109		

PARSONS GSA LEASED *		
Number of Vehicles	License Number	Description
1	G42-0556K	2011 Chevrolet C1500 Pickup HEV AFV
2	G43-0085P	2014 Ford F250 Pickup AFV
3	G42-0558K	2011 Chevrolet C1500 Pickup HEV AFV
4	G12-0692L	2012 Chevrolet Malibu AFV
5	G42-1478L	2012 Chevrolet Pickup C1500 AFV
TOTAL COUNT: 5		

* PARSONS's SWPF GSA Leased vehicles are expected to transfer to the liquid waste contract at the time SWPF operations transfers